COMMERCIAL CAR JOURNA

with which is combined Operation & Maintenance Reg. U. S. Pat. Off.

Acceptance under the Act of June 5, 1934, authorized December 18, 1934.

Published monthly,

Member C.C.A.

Vol. LVII

Philadelphia, June, 1939

No. 4

Editorial Department

JULIAN CHASE, Directing Editor GEORGE T. HOOK, Editor C. B. RAWSON HENRY JENNINGS HOWARD KOHLBBENNER Managing Editor Technical Editor Art Editor JOSEPH GESCHELIN J. ALBERT LAANSMA **Detroit Technical Editor** Contributing Editor

MARCUS AINSWORTH, Statistician L. W. MOFFETT & JAMES G. ELLIS, Washington Editors B. M. IKERT, Chicago Technical Editor

EDITORIAL CONTENTS

Copyright 1939, by Chilton Company (Inc.)

Feature Articles

INC CHILITITIES THE STREET	0
Some Weighty Ideas on Light Vehicle Costs 2	_
	8
Thumbs Down on Toll Roads 3	0
Servicing the GM 2-Cycle Diesel Injector 3	2
Dynamometer Tune-Ups 3	5
Specifications	
Commercial Car Journal Trick Specification Tables 4	9
Descriptions	
New FWD Model HG 3	8
Crosley Midget Car 3	8
Departments	
Free Books, Booklets, Catalogs	7
	7
	8
	8
	8
	4
	6
	6
New Truck Registrations 3	8
CCJ Newscast 4	10
Free Money Savers for You 10	15
Advertisers' Index	6

C. A. MUSSELMAN, Pres.; J. S. HILDRETH, Vice-Pres. and Manager Automotive Division; G. C. Buzby, Vice-Pres. OFFICES

Philadelphia—Chestnut & 56th Sts., Phone Sherwood 1424. New York—239 W. 39th St., Phone Pennsylvania 6-1100. Chicago—Room 916, London Guarantee & Accident Bidg., Phone Franklin 4243. Detroit—1015 Stephenson Bidg., Phone Madison 2090. Cleveland—609 Guardian Bidg., Phone Cherry 4188. San Francisco—444 Market St., Room 305, Phone Garfield 6788. Long Beach, Cal.—1595 Pacific Ave., Phone Long Beach 613-238. Washington, D. C.—Room 1061 National Press Bidg., Phone District 6877.

SUBSCRIPTION RATES: United States and United States Possessions and all Latin-American countries—\$3.00 per year. Canada and Foreign—\$4.00 per year. Single copies—40 cents.

Owned and Published by



CHILTON COMPANY

(Incorporated)

Executive Offices Chestnut and 56th Streets, Philadelphia, Pa., U. S. A.

Officers and Directors

C. A. MUSSELMAN, President

FRITZ J. FRANK. Executive Vice-President

FREDERIC C. STEVENS, JOSEPH S. HILDRETH, GEORGE H. GRIFFITHS, EVERIT B. TERHUNE, Vice-Presidents; WILLIAM A. BARBER,
Treasurer; JOHN BLAIR MOFFETT, Secretary; JOHN H. VAN DEVENTER, JULIAN CHASE, THOMAS L. KANE, CHARLES S. BAUR,
G. CARROLL BUZBY, P. M. FAHRENDORF.

COMMERCIAL CAR JOURNAL

When writing to advertisers please mention Commercial Car Journal COMMERCIAL CAR JOURNAL. Vol. LVII, No. 4. Published monthly by Chilton Co., N. W. Cor. Chestnut & 56th Sts., Philadelphia, Pa. Subscription price: United States and Possessions, Latin American Countries, \$3.00 per year; Canada and Foreign, \$4.00 per year. Single copies, 40c, except April Issue, \$1.00. Acceptance under the Act of June 5, 1934, authorized December 18, 1934.



-and again TRU-STOP **EMERGENCY BRAKES**

brought them home Safely

* One of many letters from users tells how TRU-STOP Emergency Brakes brought a heavy truck safely down miles of steep mountain road when the service brakes gave out. The terrific heat developed at the braking surfaces of an ordinary emergency brake would have burnt out the linings.

Every TRU-STOP gets rid of braking heat very quickly. "The disc does it." Every disc is ventilated so thoroughly that heat is at all times being rapidly removed. A number of emergency uses do not impair its efficiency. This is one rea-son why disc brakes are used on the newer stream-lined railroad trains.

You won't hire reckless drivers. Why depend on anything but the most reli-able brakes? Savings through avoiding an accident are often enough to equip a whole fleet with TRU-STOPS. Then real brake economy begins for the fleet.

Why TRU-STOP Discs **Brake More Safely**

The brake engineer of one of the largest truck manufacturers tested a contracting-band propeller-shaft brake on a 12,500-pound vehicle against a TRU-STOP that had only 65% as much brake lining surface. He says:

"A few light and two heavy applications of the band brake from 20 M.P.H. completely ruined the lining... The disc brake was used repeatedly to stop the vehicle

... The disc brake was used repeatedly to stop the vehicle from 50 M.P.H. and was also used to decelerate on steep grades without serious damage to the lining."

The answer is ability to dissipate heat.

MADE FOR ALL TYPES OF TRUCKS AND BUSES

AMERICAN CABLE DIVISION

12-252 General Motors Bldg., Detroit, Michigan San Francisco: 630 Third Street

See our exhibit, Metals Building, New York World's Fair

AMERICAN CHAIN & CABLE COMPANY, Inc.

In Business for Your Safety

FLEET OPERATOR



Part of fleet (mostly Internationals) of Norman Packing Co., Portsmouth, Va. Success in these trucks and in the plant, is the record of Texaco Lubricants here. There's engineering service available to make Texaco Automotive Lubricants a success in *your* fleet. Ask for it.



TEXACO

Texaco Dealers invite you to tune in The Texaco Star Theatre—a full hour of all-star entertainment — Every Wednesday Night — Columbia Network—9 E.D.T., 8 E.S.T., 8 C.D.T., 7 C.S.T., 6 M.S.T., 5 P.S.T.

C O M M E R C I A L C A R J O U R N A L

JUNE, 1939

VOL. LVII, NO. 4





By converting a standard International D-2 panel (top) into a "Jim Crow Black Maria," another into an ambulance (above) Macon, Ga., got handsome cars and saved a plenty



High-tensile steels helped keep the weight of this 26-foot Trailmobile to 7500 lb. including all equipment. Tractor is by White



The largest Mack-built semi-trailer hauls 10-ton loads for Cushman. Mack Tractor too



Here's proof that production is under way on the new White Horse package delivery

COMMERCIAL CAR JOURNAL JUNE, 1939

EARS PROUMA

Tension Tantalizer

An old established tool maker broke down and confessed to one of our agents the other day that he could not hold out on this department much longer and that if promptness was one of our qualities we could be the first to tell the waiting world about his new tension wrench. No mechanical details, but the price is \$11.50.

Valve Verse

An agent who has been very successful in playing the waiting game suggests to this department that it wait with him and see if a manufacturer long known for his engines with unadjustable tappets doesn't incorporate a zero lash arrangement in cars and trucks for 1940. Said agent also ex-

pects similar equipment on a class passenger car for next year but this department does not concern itself with luxury transportation.

Body Blackboard

The ellipses, hyperbolas and parabolas scattered around on drawing boards have already begun to take on meaning to anyone who understands such things and this department's interpreter says that they portend a flock of radical bodies on passenger cars next year.

Dump Declaration

A company that up to this time has been completely foreign to this department is coming into the truck industry with a line of dump bodies and hoists. Just by luck our agent with something else entirely on his mind caught this one before it had a chance to bounce.

Brake Boom

At least two entirely independent organizations were shadowed by our operative and found to have some new braking systems for heavy-duty service well under way. Some of the equipment has been on the road for many miles of actual operation. It's still too early to make a definite statement, but you can look for some important news before long.

free Books

PAMPHLETS

CATALOGS

... a special selection made by the editors... to get your copy, just check the letter on the post card between pages 104 and 105 which corresponds with the item you desire... and mail to Commercial Car Journal, Philadelphia, Pa.

A Tachometer Parlay

Two intriguing leaflets just released by Stewart-Warner direct attention to the operating advantages of its new Motor-Mile Tachometer. One of the pieces, directed especially at the fleet owner, briefly describes the device and points out how it can be of help to the driver and can go a long way toward reducing fleet costs. The other leaflet talks shop to the driver and shows how the tachometer can make him more efficient and his job easier and safer. Check "A" on the post card.

Rayon Tire Data

Some remarkable statistics on the performance of the new U. S. Raymaster truck tire are contained in a 16-page booklet recently published. Stressing particularly the advantage of the rayon cord, the figures cover relative tire costs, temperatures and net power loss through the tire. For yours check "B" on the post card.

AFTER HOURS EDITORIAL COMMENTS BY GEORGE THOOK EDITOR



Molecular attraction does the trick but it's only possible with a flawless super finish such as developed recently by Chrysler Corp.

1. What War Would Mean to the Truck Industry. 2. Will Examiner Snow Find a Need for Regulating Private Trucks?

What War Would Mean to the Truck industry

DOES business want the United States to go to war in Europe?

Associations of businessmen are formally on record saying that business does not.

Rabid anti-war elements that pretend to know the mind of business better than businessmen themselves, assert that business does. In Congress, in the press and over the radio these elements are blaming business for the current propaganda which seems to have as its aim the preparing of Americans for active participa-

tion in the settling of European affairs. These elements argue that business favors war because it has much to gain from so horrible an event.

Now the term "business" covers a lot of ground and therefore must include the business of manufacturing trucks and the business of operating trucks for a livelihood. Assuming the same right to think for the truck manufacturing and the trucking industries that critics assume, we say without reservation that these indus-



Marginalia

This issue of CCJ seems to have the truck industry well in hand, as always. For the mechanical crew there is an article on "Varnish," the kind that gums up engines not the kind that gives paint that lustre. Can be found on page 20. Believing that for a whole month the shop library should contain information on more than one phase of maintenance, this article is accompanied by Shop Hints capsule, experience articles. The prescriptions are on page 24. Towards the back of the book, on page 25, Fleetman R. E. Rowley, of Los Angeles, tells you what can be done with a dynamometer in your shop. The second article in the diesel maintenance series takes the GM diesel injector apart and puts it back together again in working order on page 32.

Cause for Pause

H. O. Mathews has some things to say

that should interest the boys that pay the bills and he says them on page 22. He tells why costs have come down in some fleets where vehicle selection has kept pace with design. He also makes a few suggestions for further economies. While on the subject of costs do not forget that you have a stake in the roads as well as in your truck equipment. Neither would be much good without the other. On page 30, James G. Ellis gives the toll road idea a pretty thorough going over in a factual way and the answer seems to be "Phooey."

Lyric for Laundries

Designer Westberg renews his acquaintance with those interested in bodies. He uses a laundry body to keep the conversation interesting and to vary his main theme of better and better looking bodies. Mr. Westbergs' publication address is page 26. Fleetman Henry J. May, of Chicago, tells you how "the last shall be first." He did



Everybody starts even on this month's quiz since everybody knows 26 letters. All you have to do is know when and where to apply the letters that you know. On the basis of 10 points for each correct answer, tell the boss how good you are if you score 90. If you get 80 do not blush, and if you make 70 or less write to Robert Bahl, Bendix-Westinghouse Automotive Air Brake Co., who thought up this quiz and tell him that it was too stiff.

(Correct Answers on Page 46)

1. Don't let this one put the brakes on

you. If you had a Timken brake with lining 34 in. thick, you would know right off that it was of the

a. W type c. A type b. TW type d. H type

2. Here's a chance to use some head work. Which of these engine head designs is often referred to as the "valve-inhead" design?

a. L type b. T type c. I type

3. See if you can rise to the occasion to let us know which of these is otherwise known as the "constant-rise" cam



Newcomer to the utility field, the Fruehauf "semi", with two-man crew, packs everything needed for full sub station maintenance



Gordon Bakeries use the 2700-gallon stainless steel tanker (powered by Diamond T) to haul milk direct to the powdering tank



Six times daily, Jimmie Lynch, the Texas death dodger, flies through the air to entertain Goodrich visitors at New York Fair

tries do not want the United States to go to war in Europe. They certainly oppose the idea on humanitarian grounds and, for the record, we shall set forth some of the reasons why they oppose the idea on economic grounds.

What can the truck manufacturing industry expect in the event the United States goes to war? First, it can expect the government to declare the motor truck a defensive and an offensive weapon of war. Second, it can expect the War Department to

set into motion its plans for standardization of equipment. The War Department already knows all it needs to know about factory productive capacities. When war is declared it will simply issue orders. Officers will be stationed at the factories to see that they are carried out. Third, Congress will pass a law taking the profits out of war materials, among which trucks will be included.

Add to all this the passage of a law like the May bill now before Congress, whereby each citizen will be told where he shall work, what his wife and children shall do, and how much they shall be paid, gage its effect on factory management and try, if you can, to gage the economic value of war to the truck manufacturing industry.

We see only orderly confusion with management being told what to do and how to do it; with unprofitable war orders taking precedence over profitable orders having nothing to do with war; the demoralizing effect

(TURN TO PAGE 42, PLEASE)

it with his Boston Store fleet in safety contests during a three-year span. Look on page 28.

Answer to Inquiries

at

as

an

in.

ng

ng

ng

ick

in

ay

us-

the

He

me

ept

ew

nile

hat

25

uld

age

dea

ual

y."

in

He

rsa-

me

Mr.

26.

ells

did

rith

ght

-in-

vise

NAL 939

Leaving the issue in your hands but still on the subject of safety, the editors who never seem to catch up with their correspondence, hereby answer a whole flock of queries all at once by stating that the Williams Jewelry & Mfg. Co., Silversmiths Bldg., Chicago, Ill., make a safe driver emblem finished in enamel and gold. Suspended from the emblem is a merit bar which can be changed as the driver piles up the years on his "no accident" record. If the safety budget is a little shy you can take the merit bar back from the driver as he adds a year, give him his new one and give the old one to a driver who is just a year behind him. The emblem says the same. The manufacturer tells us that he will be glad to send a sample to any operator who writes for one on his own letterhead.

The 13 Original Diesel States

James E. DeLong, president of the Waukesha Motor Co., gathered statistics from 13 states (all he could get) and found that in these 13 states there are 2221 diesel engine trucks. The eastern division total adds up to 750 trucks and the western division to 1471. California, Washington and Oregon, considered leaders in the dieselization movement, accounted for 1176 trucks of the western division's 1471. He makes an estimate for the 48 states 4900 diesels in trucks and buses.

It Can Happen Here

J. Andreau, a French consulting engineer, in a paper on modern light European cars, said, "I believe for a long time, even since the first automobile crept along our roads, the tax collector has been the chief

engineer in all countries of Europe."

Contest Closes

On May 15, the CCJ "How Our Shop Reduced Fleet Operating Costs" contest closed when postoffice cancelling machines stamped last-minute entries with the hour of midnight. The prize decisions are now in the laps of the judges. We wish all those who participated the best of luck. The winners will be publicly announced in the August issue.

Contest Opening

We are always on the lookout for new ideas. Perhaps you have an idea for another prize contest which CCJ might sponsor. Let us have it. What kind of a contest having to do with fleet operation would you like to participate in? Think along that line. We'll give a brand new Stetson hat to the one that sends in an idea that is accepted.

a. A type
b. O type
c. S type
d. U type

4. What letter in a Studebaker model designation indicates that the model is of the cab-over-engine or cab-forward type?

a. The letter J c. The letter D b. The letter K d. The letter M

5. Now, how about the G.M.C.? Which of these letters tells you at a glance that the model is a cab-over-engine?

a. The letter A c. The letter D
b. The letter C d. The letter F

6. Initial this one off, please. What are the initials of Mr. Sloan, the president of

General Motors?

a. A. C. c. E. W. b. A. P. d. E. L.

7. Don't dodge this one. To what series does the 1939 vintage of Dodge trucks belong?

a. M series c. S series b. R series d. T series

8. Now we belt you with this one. Just what is a "V" belt?

a. A belt used on a V-8 engine.

b. A belt, the cross section of which is in the shape of a triangle

c. A belt, the cross section of which is in

the shape of a trapezoid

d. A belt used with a three pulley train
9. We should be D-lighted if you told
us in what year the D series of the International Harvester came out—


 a. 1936
 c. 1938

 b. 1937
 d. 1939

10. You've surely heard of B-K vacuum brakes. Show us that your mind isn't a vacuum by telling us what those letters stand for.

a. Brake Kontrol c. Bendix-Koppers b. Bragg-Kliesrath d. Bendix K series

Commercial Car Journal June, 1939



The


PPARENTLY the only positive thing known about the varnish or lacquer formation in the engine lubricant that is plaguing fleet operators to some degree is that no one has much positive information on it. It is found in some engines at internal inspection periods, covering surfaces on the piston skirt, on the connecting rod, on valve stems, on valve lifters and other parts. It hardly ever accumulates in the catch-alls, such as ring grooves, with the result that it hardly ever causes rings to stick. However. it is sometimes confused with sludge by the uninitiated, so occasionally it is accused of being a prime ring sticker.


The manifestations by which it makes its presence known are sticking valves, sticking valve lifters and occasionally, in severe cases, engines seizing when hot and refusing to turn over by starter power until cooled. It seems safe to guess that varnish will increase internal friction before any of these things happen and even in less severe cases interfere with output and fuel consumption.

Sludge is well recognized as a product of a cold running engine or one that is intermittently accelerated and decelerated. Lacquer or varnish is pretty well recognized as a product of an engine that runs hot, at least in spots. Sludge in its formative stage is a black, jelly-like substance. Later in its development it becomes flinthard and black as a result of further subjection to high temperatures and it seems to have an affinity for restricted places like ring grooves. Varnish or lacquer on the other hand usually looks like orange shellac. Sometimes it varies from that through red to dark brown. In automotive engines it is seldom black, whereas this color is the most common in aircraft engines where the problem is much more serious than it is in automotive engines. Usually the varnish is spread pretty evenly. It looks as if it had been deliberately put on with a brush.

The conditions which promote varnish are so varied that formation of varnish cannot be reduced to a single set of circumstances. This much, however, can be said about it: varnish is a product of oil deterioration. This is not to say that varnish formation is a reflection on the oil. One analytical chemist stated that, as a result of his investigations, he is beginning to believe that where the conditions (whatever they may be) are right for the formation of varnish, there will be varnish regardless of the oil used. However, he admitted that some oils seem to be found in the company of varnish more often than others. Since these oils are the less stable kind, it left him with the suspicion that oils which oxidize most readily have, at least in this respect, less resistance to aiding and abetting the production of varnish.

Since heat is a pretty well recognized factor in the formation of varnish, the engine cooling system can well be considered an accessory before the fact. To prevent the formation of sludge it is a pretty good rule to operate the engine so that the oil temperature is over 125 deg. F. To prevent the formation of varnish, it is also a pretty good rule to keep the oil temperature below 275 deg. F. Keeping the oil temperature below 275 deg. is not the whole story on cooling. An engine may maintain a good oil temperature in the pan but






COMMERCIAL CAR JOURNAL JUNE, 1939

unvarnished truth about

A report on the suspected causes, the known effects and the experimental remedies thus far brought to light in the field and in the research laboratory

The two illustrations on the left show a piston and piston and connecting rod assembly badly varnished. Those on right show identical parts without varnish



COMMERCIAL CAR JOURNAL

due to mechanical design cause overheating of the oil on cylinder walls.

Whenever the temperature of a lubricating oil is mentioned it seems that the time element must also be expressed or you have not said anything. This suggests that the prevalent practice of keeping the oil too long in the engine may be a contributing factor. What with expander type piston rings and other means of preventing oil consumption the thin films of oil on the cylinder walls are exposed to a high temperature for longer periods. The result is that we save oil but may wind up with varnish.

Tied up with this time and temperature is the pressure of the piston rings on the oil film. While expander

type rings are not designed to preserve oil by increasing the ring pressure until the gap between cylinder and piston is plugged up, it seems safe to say that generally they provide greater pressure than do the conventional rings. In addition, it seems that conventional ring design has resulted in higher pressures in the last few years. This increased pressure would cut the film thinner, making it more readily subject to oxidation and at the same time increase the heat. In addition, it cuts down the oil consumption, leaving the film on the cylinder walls for a longer period.

Another school of thought is that closer clearances help to bring about (TURN TO PAGE 120, PLEASE)




By H. O. MATHEWS

Automotive Engineer, Public Utility
and Service Corp., Chicago

(Editor's Note: Mr. Mathews in his discussion of the light car and 1/2-ton truck at the SAE World Engineering Congress on May 24 borrowed liberally from his own experience and that of six other public utility fleet operators. In his paper, entitled "The Utility and Economics of Small Passenger Cars and One-Half Ton Trucks," he covered 21 phases of light vehicle operation. This article covers in detail those portions dealing with operating cost trends and the effect of driving habits on costs. To it are appended the author's interesting and pertinent observations on many related angles of his subject.)


N order to demonstrate a few pertinent facts relative to the operation of light cars and 1/2-ton trucks, some actual results are given in the accompanying charts. Data pertaining to a large eastern utility fleet are shown as "fleet Y" in Figs. 1, 2, and 3. Note the gradual shift away from heavy trucks to lighter vehicles as shown in Fig. 1, and the relatively constant cost figure shown in Fig. 2. The gasoline mileage shown in Fig. 3 is of unusual interest as it reflects the change to modern cars. The best mileage was obtained when the fleet consisted of Model A Fords. There was a loss of 2 miles per gallon with



GASOLINE


OF


GALLON






... in which the author commends the utility of light cars and 1/2-ton trucks, criticizes







The accompanying charts, carefully explained in the text, illustrate pertinent details of an eastern and a midwestern fleet and also show the effect of high speeds and fast acceleration on gasoline consumption.

the advent of the V8 which has never been recovered. Operating conditions contribute to this unusual result, but what can the operator do about it other than to ask the manufacturer to reduce performance? Increased power and ability work to a disadvantage in this fleet operating in a metropolitan area due to traffic and grades.

"Fleet Z" in Figs. 1, 2 and 3 shows data for a similar fleet operating in the Midwest. In this case the difference in operating conditions has made it possible to keep the gasoline economy on the increase with the change in type of vehicle. One particularly large contributing factor to the improvements in this company is the improvement in all roads. Many secondary roads were wholly unimproved 10 years ago and have since been paved or at least gravel has been added. Many miles of poor roads are still in existence which are used regularly by vehicles of this fleet.

Both fleets provide excellent examples of the utilization of the passenger cars and ½-ton trucks which have steadily increased while the large capacity trucks have decreased accordingly. Decreased body weights and increased capacities of the small trucks have made it possible to use them for the same payload as was formerly carried on the 1½-ton or 2-ton trucks. Large crews have been reduced and in some cases two small

(TURN TO PAGE 97, PLEASE)


economy models and proves the economic importance of proper driving technique

COMMERCIAL CAR JOURNAL JUNE, 1939

KS

8





1. Rebound Plate

By Gerard J. Guilmette

Coca-Cola Bottling Co., Providence, R. I.

We have found that by adding a spring leaf under the main leaf of Ford front springs we prevent breakage of the spring without interfering with the riding qualities of the car or truck. The added leaf or rebound plate should be about half as long as the main leaf.

2. Bleeding Equipment By August M. Schmitz

Hertz Truck Lease Service, Milwaukee, Wis.

We have made a one-man job out of bleeding hydraulic brakes and at the same time saved brake fluid. We use a 15-ft. length of ½-in. hose which we connect one one end of the wheel to be bled and insert the other end in the master cylinder. Then one man can pump and watch at the same time. When he completes one wheel he moves on to the next one until all four wheels have been bled.

One Bendix 3/16-in. fitting and one Lockheed ½-in. fitting complete the equipment.

3. Head Aligning Tool By J. L. Ross

State Highway Dept., San Antonio, Texas

In some of our camelbacks there is very little room to lift cylinder heads when they have to come off. Naturally they are hard to line up when they go back on. We made a tool for aligning them by taking soft steel bolts same size as the head bolts and cutting the heads off and then chamfering the tops. Then take a double

hacksaw cut to provide a screw driver slot and drill a ½-in. hole as shown in the illustration. When the head is to go on we screw in our aligning bolts and set the head. Then we turn the aligning bolts out with a screw driver and lift them out with a piece of welding rod bent to a hook on one end and a finger ring on the other.

4. Fuel Filter


By Roger H. Miller

National Park Service Garage, Yellowstone Park, Wyo.

We have about 20 dump trucks with the gas tanks mounted on the

6 3/8" x 2 1/2" ANGLE IRON PIPE | SPACER 0 BOLT FEET 9IN. - 38" X 21/2 STEEL -13"-SPACE FOR TIRES UP TO 40 x 8 FENCE BRICK 3 FEET 4 IN. WALL "X 6" STUD

Hints from FLEET SHOPS



side of the truck behind the running board. Due to this location they accumulate fine sand and this plugs idling jets and sticks accelerator pump plungers.

UEL

UMP

lriver

hown

ad is

gning

turn

screw

piece

n one

her.

rucks

n the

URNAL 1939 By installing a moderate priced oil filter in the fuel line between the tank and fuel pump we were able to eliminate this trouble. We installed a changeable type filter connecting the fuel inlet to the filter inlet and the outlet to the line running to the pump. The only change we made was to drill a 3/16-in. hole in the oulet restriction. These filters last about 1½ to 2 years in our service, which is severe.

COMMERCIAL CAR JOURNAL JUNE, 1930

5. Tire Guard

By Preston R. Coleman

Rainey-Wood Coke Co., Norristown, Pa.

For different causes tire rims sometimes fly off when inflating the large size tires and when it happens the mechanic is very lucky if he does not get hurt. To prevent injury from rims we have made a tire fence at our door where the air hose is. When we inflate a tire we simply roll it behind this fence which is bolted through a brick wall at the top and held by studs in concrete at the bottom and no one gets hurt. A photograph appears in circle above.

Starter Gear Precaution


By R. L. Case

Leisy Brewing Co., Cleveland, Ohio

Our service consists of a good deal of stop and go driving and we find that after a vehicle has been in it two or three years that flywheel starter gears are worn in three places only because a 6-cylinder engine always stops in one of three positions. We now make it a practice when we have a clutch job to remove the flywheel and turn the starter gear 1/6 of a turn. This places the worn teeth in a different position and we save the price of a new gear plus labor.

This is the eighth in Commercial Car Journal's series of original body designs. Again we remind fleets that the designer has worked in body shops and knows the practical problems of building truck bodies. All designs are copyrighted but arrangements can be made with the designer for procuring complete construction drawings and specifications. For further details address The Editor, Commercial Car Journal, Philadelphia, Pa. July issue—a body designed for package delivery.





VOCATIONAL USES

Primary consideration in creating this design was given to city pick-up and delivery of laundry, but it is so designed that it may be used with slight variations in other vocations where a light short-wheelbase unit may be best suited.

DESIGN FEATURES

Reflecting the commercial body of tomorrow this design emphasizes modern lines, unusual molding treatment and liberal use of chrome plating and stainless steel. A modern design, different from the ordinary, is effected by generous roof quarter and rear corner radii, and by the elimination of the usual full-length roof-drip and rear vertical moldings.

DIMENSIONS


The loading capacity of the unit is approximately 290 cu. ft. which is a size well-suited to laundry work of this type. Actual clear inside dimensions are 10 ft. long, by 5 ft. 6 in. wide, by 5 ft. 4 in. high at the center.

BODY MATERIALS

Construction materials consist of hardwood understructure, side framing and roof bows. The flooring is ship-lapped fir. Side panels can be either stretcher-leveled auto body steel over plywood, or metal-faced plywood. If latter is used it is suggested that light weight formed steel posts be substituted for the hardwood side framing which would save a considerable amount of weight. The roof is of hammered steel with welded joints where moldings do not occur.

COMMERCIAL CAR JOURNAL June, 1939

39 B E. M. WESTBERG, BODY DESIGNER DESIGN NO. 8 . . LAUNDRY BODY



DETAIL FEATURES

t of

ram-

g is

n be

steel

ply-

ested

osts

side

der-

f is

ints

1939

The front entrance doors to the driver's compartment are of the sliding type, which can be locked in an open position when the driver is working at short stop-and-go intervals.

The rear door is made of polished stainless steel and designed to roll up.

A partition and sliding door is provided behind the driver which allows deliveries to be made from the front of the body. This partition also keeps the load compartment dust proof when riding and working with the doors open.

The port-hole type ventilator with spun glass air filter does two things: it enhances the appearance of the body with its stainless steel grilles and it provides fresh clean air to the interior of the body.

The front and rear bumpers are of modern design fabricated from square steel tubing and steel plate welded together and chrome-plated.

Lettering is cast aluminum polished and mounted about an inch off

of the side panels on painted wood bars.

COLOR SCHEME

A two-toned, one-color scheme with a second matching color in the lettering panel and on the wheels is suggested. By using a light shade of the color selected on the roof and the rear panel with the dark shade below the belt line and ahead of the lettering panel above the belt, the modern molding is emphasized and brought out to its best advantage.

COMMERCIAL CAR JOURNAL



From the lowest safety standing among all Chicago department store fleets in 1935, Netcher's Boston Store brought itself to the top in 1938. In 1935 the fleet's 93 vehicles encountered 101 accidents traveling 1,063,365 miles. In 1938 the same fleet, increased to 114 vehicles, had only 12 accidents covering about the same mileage. As a result the fleet won the annual trophy of both the National Safety Council and Greater Chicago Safety Council.

Because most of the fleet is still made up of the same trucks and manned by the same drivers, management credits these six principles of general supervision:

1. Expect from all drivers a good honest day's work. (This includes rearrangement of routes to assure uniform distribution and minimum overtime, and a chance for extra money during sales.)

a chance for extra money during sales.)

2. Give drivers and helpers as steady employment as possible.

3. Help drivers to eliminate personal worries, including financial loans.

 Train drivers in road courtesy and particularly to avoid traffic arguments.
 Keep trucks in best possible mechanical condition, including daily inspection and special attention to tires.

6. Get cooperation of drivers in winning fleet no-accident awards.

The story of a Chicago fleet's spectacular climb from last to first place in a safety contest with practically the same trucks—2-wheel brake jobs at that

By HENRY J. MAY

Sup't of Delivery, Boston Store, Chicago

HAVE been asked to describe the "methods" which have enabled the fleet of Netcher's Boston Store of Chicago, within three years of time, to step from a very low-place accident record among large department stores up to the position of a winner of local and national safety trophies.

In general, I must say that we have had no special "safety methods." That is, I did not start out, about three years ago when I was appointed to the position of delivery superintendent of the Boston Store, to win a fleet safety record. Rather, I started out to reorganize our Store trucking and delivery methods, and our improved fleet safety record has been a natural and expected partial result. Our improved management methods enabled our fleet of 114 vehicles to win the last annual trophy (for the year ending June 30, 1938) awarded by the National Safety Council, and also to win a like award for the same period from the Greater Chicago Safety Council, and an additional trophy for having made the largest percentage reductions in accidents among the competing large Chicago

COMMERCIAL CAR JOURNAL June. 1939



department stores, as compared to the previous annual period.

ucking

ur im-

s been

result.

ethods

cles to

for the

warded

il, and

e same

hicago

litional

largest

cidents

hicago

OURNAL

E. 1939


As proof that our new fleet safety records must have been due mostly to our revised "management methods," I might add that the Boston Store today is operating practically the same fleet of trucks that we had ten years ago. That is, nine-tenths of our present trucks are more than ten years old and still equipped with two-wheel brakes. Likewise, nine-tenths of our drivers have been with the Boston Store for ten years or more. A number of these drivers have splen-

did safety records. Eighteen of them have driven for more than four years without chargeable accidents; and all of our 57 regular drivers have driven more than 3 million continuous no-accident miles.

However, when we began the reorganization of our delivery department about three years ago, our total fleet had a very poor safety record. In fact, in the annual Interfleet Drivers Safety Contest of the Greater Chicago Safety Council for the year ending June 30, 1935, the Boston Store was at the bottom of the list among the large department stores—reporting 101 accidents for 93 vehicles which travelled 1,063,365 miles, or an accident rating of 94.9; as against 43 accidents reported by the winning store, with a rating of 30.9.

In contrast to this very poor accident showing in 1935, practically the same fleet—increased to 114 vehicles but operated by practically the same drivers and helpers, since all new and extra drivers are chosen from our helpers—had only 12

(TURN TO PAGE 64, PLEASE)



Maps above show toll road routes (left) selected for study by the Bureau and also nearest existing routes. Right: Artist's sketch of suggested intersection between U. S. Route 1 and possible belf line around the city of Baltimore

TOLL ROAD PUNCTURE

(From the Bureau of Public Roads' Report)

The three east-west and three northsouth transcontinental toll superhighways suggested for study by the 1938 Act of Congress would aggregate 14,-336 miles.

The cost of construction would be about \$2,899,800,000, which is at the rate of \$202,270 per mile.

The average estimated annual expenditure for the period 1945-1960, required for financing the construction, maintaining the property and operating the facility, would be \$184,054,000,

which is at the average rate of \$12,840 per mile per year.

Utilization of the system would average, during the 1945-1960 period, 12,-450,000 vehicle-miles per day.

Assuming toll charges of 1 cent per vehicle-mile for passenger cars and an average of 3.5 cents per vehicle-mile for trucks and buses, this travel would produce an average annual revenue of \$72,140,000.

Thus the toll system would be only 40 per cent self-supporting.



Thumbs Down on




By JAMES G. ELLIS

OMORROW'S highways will be the product of more Federal funds and greater Federal planning. Existing roads will be swallowed up by a nationally planned system whose theme will be reasonable direct connections between major cities. Linked to these will be intra-city routes directed toward business centers via depressed roads. Cities and towns

will be by-passed. Outstanding roads like the Merritt Parkway in Connecticut and the depressed boulevard in St. Louis will be widely imitated. Toll roads will be abandoned as "traffic repelling," and superhighways where drivers have to "cash in" at toll stations before gaining admission will be the exception and not the rule.

Briefly, this is the picture drawn by the Bureau of Public Roads in its 212-page report to Congress on a projected nation-wide system of toll highways proposed by road-conscious members of both Houses on Capitol Hill. The report, based upon data collected through the cooperation of state highway officials and supplemented by a message from President



BOADS

Commercial Car Journal Washington Bureau

They are traffic repelling, says The Bureau of Public Roads in an extensive study transmitted to Congress, which proposes instead a superhighway program to be based upon existing routes

Roosevelt, who urged that it be used "as a basis for needed action to solve our highway problem," will go down in highway history as the last word on the subject. It probably more accurately reflects what will be done than any other contemporary forecast.

While the analysis will long be remembered as throwing cold water on a few Congressional "unquenchables" who have persistently nursed the toll-road, super-highway idea through several sessions of Congress, it introduces wide latitude for those members who still desire to exercise their constitutional prerogatives in the direction of providing bigger and better roads.

The Bureau proposed a master


highway plan calling for these joint contributions by the Federal and State governments:

1. Construction of a special, tentatively defined system of direct interregional highways, with all necessary connections through and around cities, designed to meet the requirements of the national defense and the

(TURN TO PAGE 82, PLEASE)




Above: Test fixture for checking injectors. Right: Cross section of the injector showing how the amount of fuel injected is metered by the travel of the plunger when the helix has stopped registering with the upper port and before it registers with the lower port. Far Right: Parts of the injector below the injector body in order of assembly.



Servicing
THE GM 2-CYCLE DIESEL
OF TOTAL
OF THE GM 2-CYCLE DIESEL
OF TH

THERE is no reason in the world why a fleet operator cannot service GM diesel fuel injectors if he makes up his mind that the job is just a little different from anything he has ever done. A little training and very little equipment will be sufficient to start a mechanic in this specialty. He will improve, as in all other phases of mechanical work, with experience. Because of the accuracy and manual dexterity required in electrical or carburction work, it looks like a job for the shop



the hands can be seen through it when the occasion arises. If the work bench can be located in a room or coop apart from the shop so much the better. A wired off or boarded off corner of the tool room would be ideal.

The equipment required is a kit of injector tools, all of which, even though special, are low-priced hand tools; an injector vise, which is a fixture for a regular bench vise that holds the injector without damage to it, and testing equipment which consists of a source of fuel, a fixture for holding the injector, a lever hook-up to depress the injector or plunger and a pressure gage. An air hose supplying filtered air and two enamel pans complete the equipment.

Before dis-assembling the injector should be checked on the testing equipment. Make the checks in the following order: First — examine spray pattern to make sure that all orifices in spray tip are open. Make sure that a receptacle is placed under the injector so that it will catch the spray. Do not let spray touch fingers as this spray is under high pressure and oil may penetrate fingers and may cause infection.

Second: Check pressure at which spray occurs. This should be between 1000 and 1800 lb. and should not vary more than 200 lb. among injectors of the same engine. There should be no dribbling or wetness at the tip after injection.

Third: Subject the injector to 500 lb. pressure for at least 30 seconds without dribbling and without wetness at the spray tip. Make sure that

(TURN TO NEXT PAGE, PLEASE)

electrician or carburetor specialist.

One of the prime requisites for successful servicing of these injectors is a new conception of cleanliness. A bright metal surface on the work bench is desirable because it is easier to keep clean, but it is not absolutely necessary because every part as it is laid down must be placed on a clean sheet of paper. An adjustable work-light over the bench is necessary. As a matter of convenience, a magnifying glass should be fastened to it at such an angle that work in



A DIESEL ENGINE SERVICING SERIES


By HENRY JENNINGS

Technical Editor, Commercial Car Journal

Servicing the GM 2-cycle Diesel Injector is the second article in the series developed by the author (third from right above) who spent two weeks studying and working on these new engines along with 13 Greyhound men. The purpose of this effort is to point out in a practical way the details that will seem new and strange to experienced gas engine mechanics so that they may approach diesel engine maintenance with confidence. These articles are not intended to replace shop manuals furnished by the manufacturers.





Servicing THE GM 2-CYCLE DIESEL (CONTINUED)



1. Dis-assembly begins by unscrewing the seat nut with injector in the inverted position in injector vise. 2. Plunger bushing bearing surface must be cleaned, blown dry and wiped with absorbent tissue. 3. Plunger must be cleaned, blown dry and wiped with absorbent tissue and not touched with the fingers. 4. Six orifices in the tip must be reamed with .006 in. wire. 5. Gear and rack must be timed according to marks. 6. Re-assembly up to and including the spray tip. 7. Hold spray tip with tool while locating seat nut.











COMMERCIAL CAR JOURNAL June. 1939

there is no leakage at seat nut threads.

Fourth: Take injector in hand and hold it horizontally with rack extended up. Rack should fall of its own weight. Turn injector over and check to see if the rack will fall the other way.

If the injector passes these tests it is satisfactory for service and can be put back into the engine. If it is to be stored in the stock room, it should be filled with a non-corrosive fuel oil.

If the injector does not pass the tests it must be dis-assembled, the trouble corrected and then reassembled.

Dis-assembly and Re-assembly

To dis-assemble:

1. Place injector in injector vise (GM No. J-1261) in inverted position. Using seat nut wrench (GM No. 1238) unscrew but do not remove seat nut.

2. Remove injector from holding vise and hold it just over No. 1 cleaning pan filled with clean fuel oil. Remove seat nut and place all parts in cleaning pan. If spray tip does not free itself from the seat nut, it can be removed with seat driver (GM No. T1032).

3. Place injector in holding vise in right side up position and using screw driver (or GM No. 7647) pry follower spring out of the way and remove stop pin. As pin is withdrawn hold left hand over follower spring to prevent plunger and bushing assembly from springing outward. Place parts in No. 1 cleaning pan. Jar the rack pinion from injector body and withdraw the rack.

4. With injector in upright position in vise remove fuel connections making sure that filter springs do not spring outward. Place connections, filters and springs in No. 1 cleaning pan.

5. Brush all parts thoroughly making liberal use of cleaning fluid from No. 1 pan. Blow parts dry with filtered air. Repeat process several times. This is important.

6. Check plunger and bushing through magnifying glass for any trace of mechanical damage. If there is any these parts must be discarded. Since the plunger and bushing are lapped together they are not replaced separately. If there is no mechanical damage place these parts in No. 2 cleaning pan full of clean fuel oil or carbon tetrachloride and rinse thoroughly. Dry with filtered

(TURN TO PAGE 92, PLEASE)

MNAM METER June ups

(Editor's Note: Excerpted as of particular interest to fleetmen, the following comments are from a paper entitled "Engineered Automotive Operation and Maintenance" addressed to the Engineering Congress of the Society of Automotive Engineers in San Francisco. Mr. Rowley is in charge of the engineering section, General Plant Division, of the Department of Water and Power, City of Los Angeles. Together with the fleetmen, whom he quotes, he is well qualified to speak on the usefulness of the chassis dynamometer as well as upon the importance of acceptance tests for new equipment.)

STATISTICAL studies of road failures reveal a surprising number of adjustment deficiencies in new equipment. These are probably due to the human element in factory line production methods rather than to engineering. Defects found in the acceptance tests of 26 new cars received during one month are listed as follows:

No. of	
Cars	Defect
23	Loose wiring
20	Loose manifold bolts
18	Wrong ignition timing
7	Loose vacuum line nuts
7	Wrong valve clearance
6	Insufficient distributor point clearance
5	Wrong carburetor float level
3	Loose carburetor mounting
3	Loose fan hub bolts
1	Gas gage defective
1	Generator cut-out loose
1	Fuel pump loose
1	Loose cylinder head bolts
1	Defective carburetor


This and similar records have (Turn to Page 74, Please)

The charts show net horsepower loss as a result of various common ailments. See text for full description

COMMERCIAL CAR JOURNAL JUNE, 1939 Modern tune-up tool makes old trucks young and young trucks bold, according to fleetmen who describe its use

By ROBERT E. ROWLEY

Engineering Section, Department of Water and Power, City of Los Angeles



SIIIW LAST of New Products

Leibing Motor Degasser

A new device for the control of exhaust gases from gasoline burning engines has been introduced by Leibing Automotive Devices, Inc. Known as the Leibing Degasser it is available for use on all makes of trucks and buses. Almost total elimination of both carbon monoxide and carbon dioxide gases in the exhaust are claimed. Aldehyde concentrations (those offensive smelling fumes) are said to be approxi-



mately 185 times less with the degasser than without, and gas mileage showed savings from 12 to 25 per cent.

The degasser mechanism consists of a flexible diaphragm which is actuated by the increased vacuum resulting from motor deceleration. This in turn shuts off the excess flow of gasoline. Less crankcase dilution is also claimed.

The device cannot be installed as a separate carburetor attachment but is available at the present time as a built-in unit on both updraft and downdraft Zenith commercial carburetors and on certain Stromberg models. Address Leibing Automotive Devices, Inc., 5725 Mt. Elliott Ave., Detroit, Mich., for full details.

Snap-on Torqometer

The new Torqometers made by Snap-on Tools Corp. have been designed with long, slender bodies which work freely in rather close quarters and are fitted with pre-set type, easy-to-read dials. These tools, with a pre-determined leverage, measure the deflection of a solid steel bar at any pressure and indicate this deflection on the dial. They are designed to give readings of the greatest accuracy. The cast aluminum alloy housing incloses all the working parts, protects the beam from nicks, sur-

face scratches or other damage, and keeps the entire mechanism sealed against grease and grit. The pressure ranges of these six instruments are as follows: Zero to 80 ft. lb.; zero to 150 ft. lb.; zero to 350 ft. lb.; zero to 600 ft. lb.; zero to 1000 ft. lb.; zero to 1500 ft. lb.; zer

New Gatke Brake Block

An improved brake block said to have remarkable qualities for dissipating heat has been announced by Gatke. According to the manufacturer, it has a more constant holding power at all service temperatures and a greater resistance to wear than any lining material ever tested in the Gatke laboratories. Available in custom-britication value for balanced action on all standard type trucks, tractors, trailers, and buses. For details, write Gatke Corp., 228 N. LaSalle St., Chicago.

Inner Tube Seals Punctures

A passenger car inner tube, capable of actually sealing punctures on moving wheels without loss of tire pressure, is announced by Goodrich. The new tube reduces blow-out danger, at the same time giving protection against flat tires caused by nails, screws and glass, closing such breaks instantly. For details, address the B. F. Goodrich Co., Akron, Ohio.

Do-Ray Directional Signal

An economical single unit passenger car directional signal has been announced by

Do-Ray Lamp Co., 1458 S. Michigan Ave., Chicago. Universal mounting bracket permits easy installation without drilling. Body of brass, chrome plated. A fingertip switch is provided for the steering post. No. 50 (with one lamp) lists at \$5.00 complete; No. 51 with two lamps for front and rear installation, \$8.00. Full details from the manufacturer.



Jack Has Flashlight

No longer is it necessary to feel around in the dark with the jack saddle in an effort to get it placed under the axle for Blackhawk service jacks of 2, 3 and 4-ton capacity are now equipped with a spotlight so you can see the position of the jack. A press of a button in the handle grip



shoots a beam of light to the axle.

In addition, the 1939 Blackhawk line includes a positive handle lock. The release valve is equipped with a built-in safety tumbler lock so that with a turn of a removable key, all controls are disengaged. Blackhawk Mfg. Co., 5325 W. Rogers St., Milwaukee, Wis.

Valve Trouble Shooter

Black & Decker Mfg. Co., Towson, Md., have a new piece of equipment for testing valves called the Lectro Valv-O-Meter. It is operated by electricity and compressed




air. The purpose of the instrument is to determine the condition of the valves and if they need grinding without dis-assembling the engine.

Kex Tire Plugs


KEX nail hole tire plugs are used to seal holes in casings too small to vulcanize and to protect the casing structure after

puncture. The plug stem is enclosed in a metal quill tapered to a needle point and compressed to about one half its normal size for easy insertion. When the quill is removed from the stem after the plug is installed the stem




(TURN TO PAGE 60, PLEASE)

Bendix B-K puts power on your brakes, instead of in them! Naturally, any truck or bus manufacturer will



Bendix B-K Controlled Vacuum Power Braking, pioneer in its field, is backed by fifteen years of world-wide experience. As a result, Bendix B-K units are far in advance in engineering principles, providing finest graduation of brake control and perfect balanced brake action. The Reactionary feature of the Bendix B-K system is unique in that it constantly maintains desirable "pedal-feel," and avoids sudden, lock-wheel stops. Bendix design protects against external injury to mechanism through mud, water and road impacts.



Naturally, any truck or bus manufacturer will disapprove of altering the brake layout he has carefully designed and painstakingly proved. He urgently recommends that it be left intact—undisturbed—and that is precisely why Bendix B-K Vacuum Power Braking is so popular!

In the Bendix System, power is applied on the brakes—not in them. The original, factory-engineered brake layout, whether it be Mechanical or Hydraulic, Bendix or some other make, is left intact.

Bendix B-K consumes no engine power (except a very slight amount with Diesel power). It vastly multiplies the driver's muscle-effort, while constantly responsive to his slightest variations in pedal pressure. It meets all state laws for single vehicle or trailer operation.

Nation-wide Bendix Service is at your driver's disposal, and the cost of perfect maintenance is very, very low. Write—

BENDIX PRODUCTS DIVISION
OF BENDIX AVIATION CORPORATION
401 Bendix Drive, South Bend, Ind.

BENDIX

Controlled Vacuum

POWER BRAKING



COMMERCIAL CAR JOURNAL JUNE, 1939

F W D OFFERS NEW MODEL HG

NEW Model HG, equipped with underbody blade and incorporating many refinements and improvements, was recently announced by The Four Wheel Drive Auto Company, Clintonville, Wisconsin, and Kitchener, Ontario, Canada.

Model HG was developed primarily for underbody blade service, but also serves every purpose as a truck and is ideally suited for snow removal, with either a one-way or "V" type plow.

With a 154 in. (standard) wheel base, the new Model HG has a chassis weight of 6800 lb. with cab. The



The new FWD Model HG equipped with underbody blade. Its clearance is 23 in.

gross rating is 16,000 lb. The chassis may be equipped with either an 8 ft. or 10 ft. body.

Increased power, better performance and greater economy are achieved by improvements incorporated in the 91 hp. engine, having a

piston displacement of 381 cu. in., a bore and stroke of $4\frac{1}{8}$ in. x $4\frac{3}{4}$ in., and a torque rating of 270 ft. lb.

Single plate 14-in. clutch, five speed transmission and patented FWD transfer case are features. Standard gear ratio is 7.85 to 1.


SMALL CROSLEY CARRIES 1/4-TON



Top: The convertible Coupe converts to 1/4-ton pick-up. Right: Front end of chassis

RADIOMAN Powell Crosley's new automobile may offer interesting possibilities in the fleet field, for one of the two models easily converts to a 1/4-ton pickup. As yet unknown is

its production schedule.




Based on advanced models, the car has an 80 in. wheelbase and a 40-in. tread. Its 2-cylinder, 4-cycle, aircooled engine has a displacement of 38.87 cu. in. It is built especially for Crosley by Waukesha. The Hawley brakes give 350 deg. of lining contact.

Top speed of the new car is said to be 50 m.p.h. and the weight is 925 lb. The convertible coupe delivers in Richmond, Ind., for \$325.

New Truck Registrations by Makes by Months*

	Auto- car	Brock- way	Chev- rolet	Diam- ond T	Dodge	Fed- eral	Ford	G.M.C.	Hud- son	Inter- nat'i	Mack	Ply- mouth	Reo	Ster- ling	Stew- art	Stude- baker	White Indiana	Wiliya	Misc.	Total
January 1939	143	127	13,615	378	4,002	85	10,188	2,384	47	4,709	482	507	168	25	47	169	348	88	203	37,71
January 1938	130	64	10,338	357	3,145	118	9,304	1,777	103	4,581	257	691	217	16	27	161	301	179	229	31,99
February 1939	134	98	12,007	308	3,821	79	9,224	2,218	44	4,284	398	510	159	29	11	143	275	97	263	34,10
February 1938	96	57	9,174	350	2,677	110	7,863	1,424	81	3,847	223	587	184	9	20	147	319	142	241	27,55
March1939	150	168	15,933	392	4,736	116	11,541	2,651	39	5,315	473	853	172	17	5	190	367	144	347	43,60
March1938	110	86	12,151	392	3,640	131	9,874	1,941	78	5,216	356	782	286		32	161	384	174	300	36,11
Three Months 1939 Three Months 1938	427 336	393 207	41,555 31,663	1,078	12,559 9,462	280 359		7,253 5,142	130 262	14,308 13,644	1,353 836	1,870 2,060	499 687	71 42	63 79	502 469	990 1,004	329 495	813 770	115,42 95,85
% Change 3 Mos.	+27	+30	+31	-2	+33	-22	+14	+41	-50	+5	+62	-9	-27	+69	-20	+7	-1	-34	+6	+2

^{*} Complete except for Tennessee for March.



The Exides in this fleet see 2450 miles of delivery service per day...

DOOR-TO-DOOR delivery is one of the toughest types of service, requiring batteries of utmost dependability. The Virginia Dairy Company of Richmond, Va., operates a fleet of 49 units, each of which

averages about 50 miles per day.

The entire fleet is Exideequipped. This operator has used Exides for several years, and is convinced of their dependability.

Exide Batteries, which stay on the job and out of

trouble, always mean greater economy. You experience fewer tie-ups and delays. Battery replacements are reduced, and maintenance expense is cut down. You are sure of lower battery cost per mile.

The Exide line is complete, with Heavy Duty Exides for all commercial vehicles, as well as Exides for cranking Diesel-powered equipment. Why not standardize on Exide and cut costs? See your Exide Wholesaler today.



THE ELECTRIC STORAGE BATTERY COMPANY, Philadelphia

The World's Largest Manufacturers of Storage Batteries for Every Purpose
Exide Batteries of Canada, Limited, Toronto

COMMERCIAL CAR JOURNAL JUNE, 1939

When writing to advertisers please mention Commercial Car Journal



Wheeler-Truman Developments

Once again Capitol Hill figures in the news, for fleetmen everywhere are keeping an anxious eye on the fate of the Wheeler-Truman transportation bill (S. 2009) which, on May 18, was introduced to the Senate by the Senate Committee on Interstate Commerce which recommended its passage.

Briefly the bill seeks to codify and incorporate under a single statute the present Interstate Commerce Act, Part I (railroads) and Part II (Motor Carrier Act, 1935). It also brings water carriers and pipe line companies under regulation of the ICC but leaves air transportation still under the Civil Aeronautics Authority. As revamped by the committee, however, the bill differs materially from the original.

In a 39-printed-page report the committee explained its reasons for favoring the bill, based largely on the fairness of putting competing transportation agencies under a common starting point of regulation. "At present there is a plethora of transportation facilities," says the report significantly, "and under these circumstances it becomes apparent that some tribunal must be empowered with the authority to determine into what particular niche each form of transportation is best fitted, and to discourage other forms of transportation from entering therein." The minority opinion, printed separately, pointed out the increased cost necessitated by regulation and asks why the consumer should be called upon to bear this additional cost.

Among the changes is the stipulation that the "Commodities clause" applies only to the railroads and that the "Long-andshort-haul" clause be broadened to include all carriers. The amendments include one which may force the railroads to pool their less-than-carload shipments and which might force independent freight forwarders out of business. It was inserted by the committee at the last moment and stipulates that the ICC may, at its own discretion and in the interest of more efficient handling, require the carriers to form such a pool for forwarding freight through a common agency and such agency would then become subject to the provision of the act. Observers who had advocated regulation of freight forwarders commented that this provision might rather annihilate rather than regulate them.

ICC Figures Again

A month never goes by but that the ICC makes news in the trucking world. This time they have handed down a self-ruled decision that their jurisdiction over interstate carriers applies only to employes whose activities affect the safety of operation of motor vehicles. The decision applies to common, contract and private carriers alike, and automatically places all employes who do not meet this qualification under the jurisdiction of the Fair Labor Standards Act. It is understood that the American Trucking Associations, Inc., will file suit shortly in the Federal Courts under the Declaratory Judgment Act to have the courts pass on this question.

. . . and Again

Apparently pointed at relieving doubt in the minds of operators with respect to certain speed regulating devices now on the market, the Commission has ruled that Rule 2 of Section A of the code covering safety equipment be amended so that "the color blue or purple may be used on the front and rear of any motor vehicle in a device to indicate the speed at which the motor vehicle is moving."

Production Still Way Ahead

Again we had to break into the form at the last minute to give you truck production figures (U. S. and Canada) for April. The total was 68,063 units, a drop of 12 per cent from the March figure of 77,097, but 42 per cent, nevertheless, above April a year ago when the output was 48,018. Total for the first four months, 268,916; last year 210,000; gain 28 per cent.

Users Pay for Highways

Contributing an interesting angle to the old problem of whether or not motor vehicles actually do pay their fair share of the highway costs, comes the report of an investigation into the Illinois state highway system. The study, undertaken at the request of the Illinois Highway Users Conference, was conducted by Grover C. Dillman, president, Michigan College of Mining and Technology; D. Philip Locklin, associate professor of economics, University of Illinois; G. Lloyd Wilson, professor of transportation and public utilities, University of Pennsylvania, and John S. Wor. ley, professor of transportation engineering. University of Michigan. The report is long but these brief points are important:

1. The motor vehicle owners not only pay their share of highway costs, but much more. The committee found that in figuring the annual highway costs there was a charge for amortization of present highways as well as an item for depreciation. Thus, in effect, the users are paying for highways twice, for they are not only paying in full for the present highways, but also accumulating a reserve to build new highways when present ones have worn out.

2. The committee pointed out that because of such reasons as mail routes, national defense, public health and education, agriculture, commerce, etc., the state should assume a part of the highway cost out of the general fund, directly refuting the theory that the state should be reimbursed for taxes lost on property occupied by the highways which it classed as ridiculous. The committee cited previous studies that fixed the users' share of highway costs. at from 82 to 90 per cent. Based on 1936 totals of highway cost the users' share was \$38,318,591. Yet highway taxes that year amounted to \$53,361,907, leaving a substantial balance for future highways or other uses.


3. On the question of allocating a greater share of highway costs to the heavier vehicles, the report said that its studies proved that roads of a width and thickness sufficient to support heaviest traffic would be built even if they were to be used solely by passenger cars. Practically all the states favored a width greater than the generally-accepted minimum for light-car traffic.

Anti-Diversionists

As a hedge against "other uses," however, five state legislatures have now ap-(Turn to Page 42, Please)



Detroit's ash and rubbish collectors, organized as the "Knights of the Iron Horse," recently purchased these 115 Ford trucks. Seventy-five are Truckstell-equipped c.o.e. units; 40 are conventional 85 hp. models.



What's bad for cats but good for oil men?

"Curiosity," the old saw has it, "killed the cat!"

But it is the *lack* of curiosity—and the research it fathers—that would be fatal to an oil company. For nine-tenths of the petroleum industry's progress... in prospecting, new products, and refining technique... is won in the laboratory.

Gulf's attitude toward research speaks for the progressiveness of this company. To its two great scientific institutions —the Research Laboratory at Harmarville near Pittsburgh and the Refinery Technological Laboratory at Philadelphia— Gulf awards a generous budget.

The object: To answer such questions as these . . .

"What significance have certain recurring rock formations with respect to oil deposits? Can a more effective insecticide be made from refinery gases? Do automobile engines operate better in damp weather? If so...why?" With the aid of geological, chemical, and metallurgical research, Gulf scientists uncover each year new processes, new principles, and new products.

Nobody recognizes more than Gulf the fact that, without research, a modern industry stagnates. And few are using research to greater advantage.



GULF OIL CORPORATION . GULF REFINING COMPANY . GULF BUILDING . PITTSBURGH, PA.

ehi.
the
an
ighat
sers
C.
of
dlin,
verssor
Univoring.

was ighion. for paybut new rorn
benaicatate cost

was rear ubor

theits and

iest

ter for

OW-

ap

NEWSCAST

(CONTINUED FROM PAGE 40)

proved anti-diversion constitutional amendments according to reports received by the National Highway Users Conference. These states are Idaho, Iowa, Nevada, South Dakota and Wisconsin. In most of these states the question will be submitted to voters at the next general election. North Dakota re-enacted its anti-diversion law.

Illinois Week-end Truck Ran

Again from Illinois comes word that Senate bill, S. 155, providing week-end and

holiday ban to truck operations was assigned to the senate Committee on Rail-roads with the report "Do Pass," without opponents being heard. Twice postponed, a hearing was scheduled for the latter part of May.

Arc Welding Encyclopedia


Remember the big prize contest that Lincoln Arc Welding Foundation (a Lincoln Electric Co. enterprise) staged a year or so ago? As could well be expected in a \$200,000 undertaking, some of the entries made mighty worthwhile reading, and the best (109 of them) have been incorporated in a new 1400-page book just published by the Foundation. It seems there are 89 pages and 47 illustrations devoted to automotive welding alone. \$1.50 per copy in the U. S. A. Address Lincoln Age Welding Foundation, P. O. Box 5722 Cleveland, Ohio.

(More News Begins on Page 58)

AFTER HOURS

(CONTINUED FROM PAGE 19)







• Truck delays are not always the driver's fault. Perhaps the office is responsible. And that discovery leads the way to truly enormous savings.

Here's a truck waiting for its load for 2 hours, at a cost of \$2 or \$3 an hour! Here's a truck with a short afternoon route, getting in at 3:30 and nothing more to do till closing time. bucking rush hour traffic unnecessarily; here's a truck that needs a helper; here's a truck that's overworked, causing costly overtime!

Time, time, time!

It's all a problem in TIME-and of course the Servis Recorder gives you all this information, on its chart, at a glance. It gives you the clue, it points the way to a proper grangement of your whole truck system, where the driver is only a small

part of your problem. Write for free booklet: "Ten Ways of Getting More Work Out of Motor Trucks."

The SERVICE RECORDER Co. 1422 Euclid Ave., Cleveland, O. Branches in Principal Cities

COSTLY DELAYS!

Here's a truck that's up against a hold-up at the freight station, which could be corrected; here's a truck



The Servis Recorder The Good Driver's Best Friend of this patriotic preference on branch and dealer sales organizations that must depend upon deliveries of private orders for subsistence; the disruptive effect of compulsory standardization on assembly lines; the interference with normal engineering improvements; the problem of readjustment after the war has ended. In short, all of the evil effects of bureaucratic control over an industry as dynamic as any in the world, the spice of whose life is in meeting the transportation requirements of private industry, and the mother of whose inventiveness is competition.

Definitely the truck manufacturing industry has more to lose than to gain by war.

What can the trucking industry expect in the event the United States goes to war? History provides the During the last war the answer. government took over the railroads. It didn't do the railroads a bit of good. In the next war, the government will not merely take over the railroads but the railroads' competitors to boot. The trucking industry will not take orders from private management; it will get its orders from Washington. The young and middle-aged truck drivers and helpers will be drafted and put to driving army trucks. The trucking lines will have to find, or the government will find for them, a new crop of drivers and helpers. The chances are they will not be fitted for their tasks. Efficiency will fall off, vehicles will be abused, equipment will become undependable, management will hesitate to make replacements, and the financial losses incident to government control will have to be met by the private owner. He'll find out the real extent of those losses when the war ends and control is returned to him.

Decidedly the trucking industry and the truck manufacturing industry (TURN TO PAGE 44, PLEASE)

COMMERCIAL CAR JOURNAL

Around the World in 60 days!



FROM THE START of production 60 days ago, the new White Horse line has operated at capacity to meet the amazing demand for this entirely new and basically better home-to-home delivery truck.

THE WHITE HORSE is as different as profit and loss for all types of city route delivery service...for bakeries, dairies, laundries, dry cleaners, groceries, department stores and other progressive merchants everywhere.

Only a basically better design would get the spontaneous acceptance given THE WHITE HORSE from the start.

What's different about it? Everything!

Its economical air-cooled, aviation type engine. Its new driving ease and safety features. Its fully insulated, all-welded, fume-proof body, cradled on live rubber and coil springs for extra protection of fragile loads.

THE WHITE HORSE comes in two wheelbases with proper body sizes for all types of house-to-house delivery service. The 99" wheelbase unit, complete with body, is priced at \$1260, at Cleveland, plus taxes.

Get in touch with your local White

Branch or Dealer today for a demonstration.

THE WHITE MOTOR COMPANY

PHONED, WRITTEN for details of the WHITE HORSE franchise!



The White Factory has been flooded with inquiries and reflooded with inquiries and requests for open White Horse territory because car dealers tercitory because car dealers recognize The White Horse's unusual sales appeal. Here Vice Pres. J. N. Bauman is shown with a few covering his desk. • Your territory may still be available—mail coupon below for full information.

oppress 1939, the White Motor Company, Cleveland, U.



AVIATION TYPE, air-cooled, 4-cylinder engine, mounted integrally with the rear axle, clutch and transmission. Entire power unit easily removable and interchangeable.



TRUCKS

PERFECTLY FLAT FLOOR, from side to side, no obstructions. Low (11½-inch) step.



"EASY AS RAISING THE HOOD" of your passenger car. Fender skirts lift up on either side providing instant accessibility to the power unit.

ı	Cleveland, Ohio.	
	Gentlemen: Please send me complete in- formation about the new WHITE HORSE	
	Signed	
	Firm Name	
١	Street Address	
ı	City	
	State	
	Dealer CC	ı

al ar (CONTINUED FROM PAGE 42) do not want the United States to engage in a European war. They have too much to lose by the virtual dictatorship which the government—no matter what party is in power at the time—will invoke.

Both industries have much more to gain with nations at peace. There are wars to be fought that are more important than bloody wars in which man kills man and is killed in return. There are the "bloodless wars" to bring other countries nearer the American standard of living, to improve the American standard, to eliminate waste in distribution practices, to help the laundry, the dairy, the department store and numerous other vocations deliver their goods more economically to the public.

All these and many other similar "bloodless wars" can be successfully fought only in an atmosphere of peace. In all of them the motor truck is destined to play a vital part. And in playing that part, those who make and those who operate trucks stand

to gain much more than they could possibly get out of a bloody war,

Will Examiner Snow Find a Need for Regulating Private Tracks?

IF the well-known Dr. Gallup were to poll private truck owners who attended the Interstate Commerce Commission hearings intended to determine if there is need for Federal safety regulation of private trucks in interstate commerce, he would find that Examiner R. W. Snow is indeed a very unpopular person.

The basis for this unpopularity—of which Mr. Snow has probably been made aware—is the belief of private truck owners that by his conduct on the bench the Examiner revealed a prejudice against privately-operated trucks. They arrived at their conviction simply by considering the manner and method in which Mr. Snow questioned witnesses and by his general remarks and his rulings, and by comparing them with their own feelings.


Of course, in fairness to Mr. Snow, this does not prove the existence of a prejudice. In fact, his conduct, no matter what suspicions it aroused, is defensible on the ground that it was a necessary device in order to try to develop a hearing record that would be something more than a blanket opposition by private truck owners to Federal regulation. We are not familiar with the rules by which I.C.C. examiners conduct themselves, but if the term "examiner" is truly descriptive of their function, it would be difficult to single out a single statement or action by Mr. Snow that could be criticized as not in line with


his duty.

If Examiner Snow actually entertains a prejudice, private truck owners must look for it in the report which he will shortly make to the Interstate Commerce Commission.

In the Federal Motor Carrier Act. Congress said "It shall be the duty of the Commission to establish for private carriers of property by motor vehicle, if need therefor is found, (italics ours) reasonable requirements to promote safety of operation, and to that end prescribe qualifications and maximum hours of service of employees, and standards of equipment."

Private truck owners may be justi-(Turn to Page 46, Please)





WEIGHT SAVING-1500 LBS.

		TABLE OF	EXTRA E	ARNINGS	
Rate per Cwt.	Per Trip	50 Trips	100 Trips	200 Trips	250 Trips
\$0.16	\$2.40	\$120	\$240	\$ 480	\$ 600
.24	3.60	180	360	720	900
.32	4.80	240	480	960	1200
.40	6.00	300	600	1200	1500
.48	7.20	360	720	1440	1800
.56	8.40	420	840	1680	2100
.64	9.60	480	960	1920	2400

The EXTRA PROFITS

THE chart at left shows the extra earnings you make with the new AEROVAN, based on its minimum added payload capacity of 1500 pounds. You can double even triple—these figures when the AEROVAN is compared with many Trailers now on the road! Ask the Fruehauf man to show you the savings as applied to your exact operation. He has them ready for you.

COST-CUTTER NUMBER TWO DUAL DIFFERENTIAL WHEELS

IF you're looking for the ultimate in economy, don't neglect cost-cutter number two in the Fruehauf line for '39, Dual Differential Wheels • They cut gas and oil costs up to 20%. Double tire life. Give freer rolling, permitting one gear higher in hilly country. Cut running time on the straightaway • As with the AEROVAN, your nearest Fruehauf representative has all the facts.

FRUEHAUF TRAILER COMPANY, DETROIT, MICHIGAN

World's Oldest and Largest Manufacturers of Truck-Trailers • 10940 Harper Avenue • Sales and Service In Principal Cities

FRUEHAUF TRAILER



"Engineered Transportation" REG. U. S. PAT. OFF

COMMERCIAL CAR JOURNAL

187

errai

nd

bly

re-

ly.

at

er ch

ul-

ith

ıld

cet

ch

ld

le

rt

ty

or

re

When writing to advertisers please mention Commercial Car Journal

(CONTINUED FROM PAGE 44) fied in their fear that Examiner Snow will take a rather broad view of what constitutes evidence of need. Mr. Snow should have a difficult time evaluating the testimony in the record as an evidence of need. The private carriers who testified were almost unanimous in their opposition to regulation. The proponents of regulation certainly did not prove a need. Their testimony merely proved their desire for regulation of private trucks.

Apparently an I.C.C. Examiner is expected to base his recommendation solely upon the testimony submitted at hearings. Such was hardly the case when hearings were held to determine what hours of service should be prescribed for common and contract carriers in interstate commerce. There was no testimony then to prove that long hours of service caused accidents. There was ample testimony proving that accident frequency was greatest during the first few hours a driver was on duty. Yet Examiner

Snow recommended a maximum week of 60 hours and doubtless felt he was liberal in doing so. The Commission accepted the argument that "a begin. ning in the regulation of maximum hours of service of drivers should be made at this time." And in an nouncing the regulations the Commission made mention of its "well. established practice of deciding cases solely upon the evidence submitted at the hearings," but accepted this choice bit of reasoning by the examiner: "It is clear, however, that only carriers who did have good accident records appeared and testified Therefore, the fact that few accidents were shown to have occurred in the operations of carriers whose employees worked such long hours (as much as 16 per day) cannot be given too much weight."

PERFECT ALABUE

Examiner Snow will have to minimize similarly the testimony adduced in the private carrier hearings if he is to prove there is a need for private carrier regulation. He will have to prefer his own logic to the testimony of witnesses, a preference which he displayed in his common and contract carrier recommendations. He will have to take recourse in the argument that if there is a safety value in regulating common and contract carrier operations, the cause of safety will certainly be advanced by regulating an even greater number of private trucks. He will have to advance the argument that it would be unfair to regulate one type of carrier and not another.

In short, the fear of private truck owners is that Examiner Snow will be concerned not with deciding whether there is need of regulation on the basis of the testimony, but with determining what he shall construe as representing a need.

In which case they will feel their suspicions of prejudice were justified.

How Much of Your Truck Tire's Usefulness Does HEAT Consume?

Have you figured out how much heat wear in your tires costs you?

You needn't start guessing all the things you want and need to know about internal heat generation which weakens fabric and causes road delays from tire failures. . . That makes operating costs go up and profits down. . . LEE engineers have found out for you. They tested all makes of truck tires. The

results are set down in an informative cost-reducing article by A. H. Nellen. For your FREE copy of "Comparative HEAT Generation In Truck Tire Treads and Carcasses" write today to the Lee Tire & Rubber Co., Dept. A., Conshohocken, Pa.



Copyright 1939, Lee Tire & Rubber Co.

QUIZ ANSWERS (See page 18)

- 1. W type
- 2. I type
- 3. S type
- 4. The letter M
- 5. The letter F
- 6. Alfred P.
- 7. T series
- 8. A belt with trapezoid cross section
- 9. 1937
- 10. Bragg-Kliesrath

was sion gin-num be an-om-vell-ases tted this ex-that ac-ied. (as

to adngs for vill the nce non darse is a non the adter vill hat one


ing ion out

eir ed.

AL |39



Tonnage Rating—Where a spread of ratings is given the maximum ratings are for ideal operating conditions and the minimum for extremely difficult conditions: the ranges between are for varying operating conditions. Chassis Price—Chassis price quoted applies to standard wheelbase with standard tires. All prices are F.O.B. factory. Gross Vehicle Weight—Is chassis weight stripped, plus body and cab weight, plus payload. Gross vehicle weight is based on maximum recommended the size, not on tires listed as fikandard. Chassis Weight Stripped—Is weight of standard chassis with Standard chassis with Standard chassis with Standard chair ment, with crankease and cooling system full, and 5 gal, of gasoline in tank. Does not include weight of cab. Exceptions are noted. Make and Model—Only basic models are listed. Variations are available with most manufacturers. OURNAL'S



(*) Ford... 5.83 axte ratto also optional at a coxth charge. 2-special xale (ration (f. 5.83 and 8.11) optional at extra cost. (a) General and Access. The size included in column. Maximum The size represent in column. Maximum The Size Furnished. Is anximum eaparity dual tires recommended for normal operating Brought up to date in this issue from data supplied by truck manufacturers

AF-300 to AF-850 to AC-851 and available for export only as coach ebasis. Dual performance rear axies are available on AC-300 to AC-700 and AF-300 to AF-300 to AF-300 to AF-300 AID-10181vc. Double AC-450 to AC-700 and AF-450 to AF-700 inclusive. Double AC-450 to AC-700 and AF-450 to AF-300 to AF-850 and AF-850 to AF-800 and AF-850 to AF-800 and AF-850 and AF-850.

(\$) International Harvester—For the express purpose of best fitting the truck to the individual job most international Trucks can be provided with optional engines, transmissions, axies, etc., and engines, transmissions, axles, etc., and these units when so equipped are ye considered standard stock truck models

Chassis weights as listed involve popular wheelbuses, recommended tire sizes and include weights of cabs.

Mack—For the express purpose of best fulling the trunk to the individual job most Mack Trucks can be provided with most Mack Trucks can be provided with wholenal regimes, transmissions, axics, etc., and these units when so equipped models.

Maximum Tire Size—1s furnished at extra cost, if the maximum differs from the standard tire size. Dual rears are understood except where otherwise noted.

Maximum Brake HP, at Given R.P.M.—Is actual dynamometer reading without accessories.

(6) Reo -- Also available with four speed transmission and bevel gear rear axle.

(*) White-Tractor rating only.

Gear Ratio Range in High—Ratios within the range given are available at no extra cost. Exceptions are noted. Tractore—Unless given the designation N (meaning not savaliable as tractor). Be available as tractory be available as tractory.

OF

(C) -- Converted Ford o model, identifiable by make listed.

(10) Indians—These models are for Government use and their chassis price depends upon quantity ordered.

Operation

(14) Federal—283 et. in. engine and 11.* clutch available on Models 15 and available on Models 10. and available on Model 40. 428. ct. in. engine available on Models 15. 82. 20. 25. 29. 29. 40. 75. 80. 85. 89 and 89H. 40. 75. 80. 85. 89 and 89H. on Models 20. 25. 29. 29H. 40. 75. 80. 85. 89 and 89H. on Models 20. 25. 29. 29H.40. 80. 85. 89 and 89H. and 89H. Two or Interespeed auxiliary transmissions available on all models. All above equipment furnished at extra cost.

(2)—These models available with double drop bus frames.

BRAKES—SERVICE

Location

(11) Diamond T—Weights given in Chassis Weight column are average chassis weights.

(12) Available -- All models available in c.o.e. design. (13) White—This is special model—price on application,

(15) La France-Republic — Chassis weights include cab, water, oil, sparerim or wheel, and approximately five gallons of fuel. (16) Marmon-Herrington—All Model F Units become Model FF if Urnished With 95 h.p. Ford engine. Weight increases 20 lbs., and ilst price increases \$25.

(a) Mack—Weight in Chassis Weight column is shipping weight which includes weight of a chassis of medium standard wheelbase, cab, prevailing the size, ready for the road.

(7) Sterling-Available with Diesel.

(9) Wiltys—Adverlised like price less Federal fax. Cab Pick-up \$530. Cab Stake \$545. Parlick-up \$500. Selec-Price. confide with about absorbera and front and ear bumper De Sandard (1 tree 5.50 for 4 py; Panel De. 6.00) if

2 C—Center of double propeller shaft,
2 C—Center of double propeller shaft,
4—Six wheels,
1—Six wheels,
1—Transmission,
P—Transmission,
P—Propeller shaft, A—Air.
D—Bydraulic and mechaniesi.
H—Bydraulic.
M—Mechaniesi.
V—Vacuum. BRAKES-HAND Location

MAKES-ALL

SRAKE DRUMS

P-Pressed sites! c-Cast iron.
s-Cast steel. P-Pressed sites.
(Where a combination of any of the above is used, the first reference mark applies to the front and the second to the rest drunas.) A—Cast alloy fron.
A—American Car Forv
C—Contrituse. D—
E—Ermalite. P—P
G—Gunite. N—P Material A La P—American La France,
B—Bendix. BL—Brown-Lipe.
Bu or Bud—Buda.
Cart—Caterpliar. Cl or Cla—Clark.
Cor Chew-Chervolt.
Co—Covert
Co—Columbia.
Ea—Eakon. Fu—Fuller.

Cum—Cumma-Diesel
Est—Eston. Fu—Fuler.
Furd. Bereule. L-Lockheed.
LO—Lockheed front, Own rear.
LW—Lockheed front, Warear.
Ly—Lycoming.

or Opt—Optional.
—Salisbury

PPT-Spread Property of the Pro

1—"I" Beam.
C—Channel.
T—Channel tapend front and rea.
L—Channel reinforced with liner.
Bad flabplate.
And flabplate.
T—Channel tapered front and rear and reinforced with plate, and tapered front and rear with liner.

GOVERNOR STANDARD

Y-Yes. N-No.

REAR AXLE

on all

2—Two Wheels, rest only.

4—Two-wheel brises effective
four wheels through driveshaft

4—Four Wheels, front and rest.

4—Four Wheels, rest only.

6—Six Wheels, front and rest.

Final Drive and Type

B—Bavel. C—Chain.
H—Drad. F—Full-floating.
H—Papold d—Dual range axie.
S—Spiral bevel.
H—Worm.
H—Worm.
H—Bem-Ioating.
H—Three-quarker floating.

X-External.

i-Internal. Type

Only one ratio.

Drive and Torque

A—Radius Rods and Torque Arm. H—Hotchkiss. (springs) R—Radius Rods T—Torque Arm. U—Torque Tube.

WHEELS DRIVEN

2P—Forward unit of Rear Axle Group.
2R—Rear Unit of Rear Axle Group.
4R—Forward and rear units of Rear Axle Group.
4F—Front Axle and Forward unit of Rear Axle Group.
4F—Front Axle and Forward unit of Fear Axle Group.
4FR—Front axle and rear unit of rear axle group.
4—All wheels.

0-Tru-Stop disk, X-External,

5	0							
m		Type		444444444444444444			MFFFFFFF	Donne
FRAME	. 81	Side Rail Polenemid	A TANK TO THE TANK	#	6x3xy 6x3xy 10x3xy 10x3xy 10x3xy 10x3xy 12x3xy 14x3xy 14x3xy 14x3xy	6667767777777 	*********	HAPPPE
-	nolan (C-A Dime	00000000000000000000000000000000000000	XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX	######################################	00000000000000000000000000000000000000	******	Destruction .
	noise	Type Toca	ZZZZZZZZZZZZZZZZZZZZZZZZZZZZZZZZZZZZZZ	DECOXULATION OF THE PROPERTY O	KXXXXXXXXX	899888888888	222222222	8.40000000 8.4777700
BRAKES	99	Area Drum Material	6478 6478 6478 6478 6478 6478 6478 6478	65000000000000000000000000000000000000	848822383 848882383 8488888888 9660 9660 9660 9660 9660 9660 9	4 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6	a a a a a a a a a a	\$200000000 \$2000000000 \$200000000000000
BRA	SERVICE	Type Operat'n Lining Area	V 368 V	DV 580 V V 3688 V V 3688 V V 3688 V V 3688 DV 479 DV 466 DV 580 DV 580	# # # # # # # # # # # # # # # # # # #	90000000000000000000000000000000000000	2000 2000 2000 2000 2000 2000 2000 200	20000000000000000000000000000000000000
		Make	44444444444444444444444444444444444444	1041DV 11411DV 11411DV 11411DV 11411DV 11411DV 11411DV 11411DV 11411DV 1141DV 11	######################################	44444444444444444444444444444444444444	141HV 141HV 141HV 141HV 141HV 141HV 141HV 141HV	9000000 EHEHHHHH
FRONT		Make and	Thm 31007 Thm 32008 Thm 32502 Thm 32502 Thm 32502 Thm 32500 Thm 32500 Thm 26452 Thm 26452 Thm 32602 Thm 32602 Thm 32602 Thm 32602 Thm 32602		Tim 30000H Tim 30000H Tim 30000H Tim 31000H Tim 32502H Tim 33502H Tim 33000A Tim 33000H	201.00 11m 30000H 11m 30000H 11m 31000H 11m 31000H 11m 31000H 11m 31000H 11m 32505H 11m 32555H 11m 32555H	Tim 32505H Shu 15685B1 Shu 15685B1 Shu 15685B1 Shu 15685B1 Shu 15685B1 Shu 15685B1 Shu 15685B1 Shu 15685B1	Own Own Own Own Own
eq.		Ossr Ratio I ni sgnaЯ	7.1.2.2.2.2.2.2.2.2.2.2.2.2.2.2.2.2.2.2.	200 000 000 000 000 000 000 000 000 000	&&&&&&&&&&&&&&&&&&&&&&&&&&&&&&&&&&&&&&	000000000000000000000000000000000000000	60 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	55 43 6 17 0 6 43 6 17 0 6 17
AXLE		Ocar and Drive & To			MEMBERS AND A		**************************************	מממממממ
REAR			20200000000000000000000000000000000000	**************************************	H	25522 2552 255	56200H SF 58205H SF 72000L 2F 1337BH 2F 1337BH 2F 1377BH 2F 13757H 2F 1357H 2F 1357H 2F	ancanana Liebisis
		Forward S Make and Model	4 Tim 54412 5 Tim 56410 5 Own RI 5 Own DB 5 Own DB 5 Own DB 5 Own TF 6 Own TF	No.	4 Thm 53508 4 Thm 53508 4 Thm 53308 4 Thm 54411 4 Thm 56410 5 Thm 56810 5 Thm 58305 5 Thm 58305	44 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4	5 Tim 562 5 Wis 720 5 Wis 133 5 Wis 133 5 Wis 133 5 Wis 133 5 Wis 133 5 Wis 133 6 Wis 133 6 Wis 133 7 Wis 175 7 Wis 175	33004h 004h 004h 004h 004h
TRANS-		Make and Model	Cla 185F Cla 200VO Cla 200VO Cla 200VO Cla 200VO Cla 1815 Cla 1815			WG T9 WG T9 WG T9 WG T9 WG T9 BE B341 BE B341 BE B341 BE B341 BE B341 BE B341 FU E344	Fu 5-4-3 Fu 5-4-3 Fu 5-4-62 Fu 5-4-62 Fu 5-4-62 Fu 5-4-62 Fu MHC	
ри	Main Bearings	Number, Diameter and Length Governor	AAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAA	AKKAKAKAKAKAKAKAKAK T T T T T T T T T T T T T	*********	KANNANNANNAN AMARANAN	XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX	ZZZZZZZZ + C C C C C C C C C C C C C C C C C C C
60	.M.q	Max. Brak. H.P. at R.I Given	73 2300 78 2300 85 2300 85 2300 97 2200 108 200 108 200 108 200 108 200 108 200 108 200 108 200 108 200 108 200	108-2200 173-2200 173-2300 173	2886-28800 286-28800 286-28800 286-28800 286-28800 286-28800 286-28800	2000 2000	78-2650 95-2600 95-2600 95-2600 106-2600 106-2600 135-2200 135-2200 135-2200 135-2200	778-3200 778
DETAILS	.11	Torque lb.	######################################	######################################	88 88 188 154 165 154 165 177 177 177 177 177 177 177 177 177 17	# PPPPP4488484444	######################################	2777777
INE DI	-	Displacem Comp. Rat	8880 8888 8888 8888 8888 8888 8888 888	4 2520 4 2520 5 2520	က်က်က်က်က်က်က်က်က်က်	88888888888888888888888888888888888888	10 1041044444	00000000
ENGI		No. of Cylinders, Bore and Stroke		###### ###############################	AND		00 44 44 44 44 M K K K K K K K K K K M 4 4 4 4 4 6 0 0 0 0 M 6 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	900000000
		Make and Model	Her JXB Her JXC CHET JXC	2022 2022 2022 2022 2022 2022 2022 202	ZEKA ZEKA ZEKA ZEKA ZE ZE ZE ZE ZE ZE ZE ZE ZE ZE ZE ZE ZE	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	22.5.5.5.5.5.5.5.5.5.5.5.5.5.5.5.5.5.5.	Own Own Own Own
SIZES	rear rear	Maximum Tire Size Furnished	25/20 25/20	1.25/24 1.25/24 1.25/20 1.25/20 1.00/20 1.00/20 1.25/2	250 250 250 250 250 250 250 250 250 250	20002500000000000000000000000000000000	000000000000000000000000000000000000000	15-6 6.00/208 32x6s-8P 32x6-10p 32x6-10p 32x6-10p 32x6-10p
TIRE S	S-single rear	Standard Front and Rear	6.50.20D 6.50.20D 6.50.20D 9.00.20D 9.00.20D 9.00.20D 9.00.20D 9.00.20D 9.00.20D 9.00.20D 9.00.20D 9.00.20D 9.00.20D 9.00.20D 9.00.20D 9.00.20D 9.00.20D 9.00.20D	10.50/20D 10.50/20D	50/188 50/188 50/20D 50/20D 50/20D 50/20D 75/20D	2	12/10 00/20D 00/20D 75/20D 00/20D 75/20D 0.50/20D 0.50/22D	6.00/168 15-68 6.00/208 6.00/208 6.00/2015 6.00/2015 6.00/2015
	1	Chassis W((Stripped)	44.00	00144000000000000000000000000000000000	82000 82000 82000 82000 82000 82000 82000	88 84 84 85 8 8 8 8 8 8 8 8 8 8 8 8 8 8	2250 7250 7250 7250 8550 8650 8650 8650 9050 10000	22240 24240 24150 24150 24150 24150 24150 24150
Keynote)	1 43	Furnished Gross Vehi Weight wit Max. Tires	13500 118500 118500 22500 2250000 2250000 2250000 2250000 2250000 225000 225000 225000 225000	4000 4000 4000 4000 6000	8500 11500 12500 12500 12000 12000 12000 12000	7. 40.70	© 0000000000000	113 x4600 123 5206 133 6700 133 7700 133 13500 158 9500
RAL (See		Chassis Pri Standard Wheelbase Max. W. B.	1250 139 179 179 1825 139 179 1825 139 179 1825 139 179 1825 139 179 1825 139 179 1825 139 179 1825 139 1825 1825 1825 1825 1825 1825 1825 1825	07244999999999474479	103 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	349 75 75 8 849 1100 1120 1130 1130 1130 1130 1130 1130	153 153 153 153 153 153 153	133333333333333333333333333333333333333
OENE		Tonnage Rating	11-0448844606644446664	P977400842222224	2 7 2 27	22222 XXX	**************************************	xxxxx
	MAKE	MODEL	Autocar (I) A B R R R R R R R R R R R R R R R R R R	(6.0.6.) UB (6.0.6.) UB (6.0.6.) UB (6.0.6.) UBL (6.0.6.) UBL (6.0.6.) UDL (6.0.6.)	Able (12) P-105 Able (12) P-105 X-100 X-100 X-200 X-200 X-200 X-200 X-200 X-200 X-200 X-200	Brootway 728 Broot	130-P8 160X + 160X + 165X + 165X + 185X + 185X + 220X +	Chev- (x) Mas. Jf rolet (x) Mas. Jf (x) Mas. V (x) Mas. V (s) (x) Mas. Spec. V (x) (x) Mas. Spec. V (x) (x) Mas. Spec. V
	19	Line Numb	-48400000001004000000		<	2 2422722222222222222222222222222222222	OMMERCIAL CA	

00000

9000 HHHH

SEF H 6 43 6 17 Own SEF H 6 43 6 17 Own

						* :		31	1
	20000000000000		* ** **				-0-0-c -0-0-c	***************************************	lame
	N N N N N N N N N N N N N N N N N N N	10x23xx1 10x23xx1 10x23xx1 10x23xx1	NAME OF STREET O	10x3x14 10x3x1	KARAKAKAKAKA KARAKAKAKAKAKA KARAKAKAKAKA	X-17-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1	TOUGHT COUCH	egeggeggeggggggggggggggggggggggggggggg	
1	SANT XXXXXXXX	1101000	- 00.00 00.0		St-www.www.www.uc-uw	001-0000000000000000000000000000000000	TTTTTT C		1
	1222 288 251111 :	50000000000000000000000000000000000000	652533333	00000000		ः विवयववयवः व	2442222888	9882588588884424 : 387	-
	MANAGAGAGAGA	KNXXXXX	KKKKKanana	KKKKKBBB	KKKKKKKKEEEEEEEK	EKKKKKEEEKE##		<u>KKKKKKKKKKKKKK</u>	10
	COm m m m m m m m m m m m m m m m m m m	66668888888888888888888888888888888888	25000000000000000000000000000000000000	452 660 660 660 768 867 867 867 867	0.000000000000000000000000000000000000	6850 6844430 6611110 68650 6860 6860 6860 6860 6860 6860 68	50000000000000000000000000000000000000	4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4	1
	000000000000000000000000000000000000000	00000000000000000000000000000000000000	8310 23310 2332 2333 2433 26177 66177	2000 2000 2000 2000 2000 2000 2000 200	03399999999999999999999999999999999999	00000000000000000000000000000000000000	\$1000000000000000000000000000000000000	844444444444488888 844444444444488888888	
	00000000000000000000000000000000000000	ATHE ATHIV ATHIV	L41HV L41HV L41HV L41HV W841A W841A W841A W841A W841A W841A	######################################	141H 141H 141H 141H 141H 141H 141H 141H	14.11.0 14.11.0 14.11.0 14.11.0 14.11.0 14.11.0 14.11.0 14.11.0 14.11.0	0001HH 0001HH 001HH 001HH 001HH 001HH 001HH		
			mmmm>>>>>>	HHHHHHHH 00000000000000000000000000000			0000000000	000000000000000000000000000000000000000	1
	21000 n 31000	a F266 a F266 a F266 m 31000 m 32500	m 300201 m 330001 m 350001 m 350001 m 330001 m 35100TV m 35100TV	3300051 m 310051 m 310051 m 330001 m 350001 m 274501	### ##################################	F308 F266 F308 F322 F322 F322 F322 n 36020 n 36020 n 36020 n 36020	404444444	F20520202055FFFFFF	
	17 Own 17 Own 17 Own 17 Own 17 Own 17 Own 17 Own 17 Own 17 Own 17 Own	4D 00 63 00 44 00	250500 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	88888=88	64444444444444444444444444444444444444	8883838383845 000000000000000000000000000000000000	78 78 78 78 78 78 78 78 78 78 78 78 78 7	\$65888337 55 55 55 55 55 55 55 55 55 55 55 55 55	
	66666666666666666666666666666666666666	1-6.8 57-6. 57-6. 12-6. 244-7.	00000000000000000000000000000000000000	14-6 116-7 116-7 57-7 57-7 85-9 02-9	88844444444444444444444444444444444444	14-5.43 557-6.33 557-6.33 557-6.33 557-6.33 557-7.37 85-7.37 85-7.37 85-7.37	73-4.78 9-4.78 87-5.85 87-5.85 87-5.85 111-7.16 111-7.16	ual Rng 16-7-16 16-7-1	
	00 00 00 0	EEMEMEE Codedada	HEHHHHHHHH	ETHTHTH CCCCCCC			田田田田田田田田田田田田田田田田田田田田田田田田田田田田田田田田田田田田		
	00000000000000000000000000000000000000	00000000000000000000000000000000000000	######################################	WANDONS ON THE	######################################	A SECTION OF THE SECT	HHY SSF SSF HAY HAY HAY HAY HAY HAY HAY HAY HAY HAY	PARTHER DESCRIPTION OF THE PARTHER O	
		R750 53300 54411 53300 54411 56410	1m 54411H 1m 56411H 1m 58300H 1m 1337BH 1 544117W 1 564117W 1 m 583017W 1 m 583017W 1 m 583017W	53200H 56411H 56411H 56411H 55330H 75733H 66725H	14650 1750 1750 1850 1850 1850 1850 1850 1850 1850 18	17075 R651 R750 R950 R1100 R1100 R1300 1357H 1357H 1357 R1300 S871.			
	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	THE STATE OF THE S	71m 55 71m 55 71m 55 71m 55 71m 55 71m 55	BEREERE SOCIETION SOCIETIO	COB R R COB R	COLEAN REAL SOLUTION OF STATES AND STATES AN	Own Oown Oown Oown Oown Oown	Eat Eat Eat Tim Tim Tim Cown Oown	
	4444444444	य क क क क क राज्या	400000000000	40000000	の キ キ ★ キ キ キ キ キ さ ら ら ら ら ら ら ら e	これももももこここれのの	0004444000	10101010101010101010101010101444101010	
	**********	T9 T9 185F 185F 200V 200V	B116(554330 554430 554430 554430 554620 554620 7551	MLLU 5A330 5A430 5A430 5A430 5A620	WG T83 WG T93 SPI 2341 SPI 2341 SPI 2341 SPI 2341 SPI 2341 CG 200V CG	2007 2341 2007 2007 2007 891	*******	386700 386750 2000 2000 2000 2000	200
	NN KNN KKN KKZK		MANNNNNN ANNNNNNN	2222222	NNNNNNNNNNNNNNNNNNNNNNNNNNNNNNNNNNNNNN	AYYYYYYNNY OODSTANDS WAND	AKKNNNNNN GÜÜNNNNNNNNNNNNNNNNNNNNNNNNNNNN		
		x598 x598 x598 x100 x100 x100 x100 x100 x100 x100 x10	2 -5 -5 -2 -2 -2 -2 -2 -2 -2 -2 -2 -2 -2 -2 -2	XXXXXX44 001XXXX44 001XXXX44			COCOCOCOCOCO	200000000000000000000000000000000000000	
	######################################	00000000	4777777	2222222	00000000000000000000000000000000000000	######################################	00000000000000000000000000000000000000		OV.
	000000000000000000000000000000000000000	25000000000000000000000000000000000000	80000000000000000000000000000000000000	000000000	4677694 467	000000000000000000000000000000000000000	000000000000000000000000000000000000000	000000000000000000000000000000000000000	000
	77777777777777777777777777777777777777	4447755	05000000000000000000000000000000000000	25.8000001 25.8000001		00000044400 00000000000000000000000000	27758885555 077758885555 0777788888555	202000000000000000000000000000000000000	
	000000000000000000000000000000000000000	0000000 00004444	55. 52.00 55. 62.00 55. 62	944444 944444 94444 9325 9325 9325 9325 9325 9325 9325 9325	11	14. 1734.4.8. 1736.0.0000.0.0000.0.0000.0.0000.0.0000.0.0000	50000000000 50000000000000000000000000	0.000000000000000000000000000000000000	
	######################################	00000000	4400 2383 2383 2383 2440 2583 2583 2583 2583 2583 2583 2583 2583	77 27227 2000000000000000000000000000000	61010000000000000000000000000000000000	222273 272727 222273 272727 22227 22	2224-52222 90999999999 90099999999	2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	S more
		******	**************************************	777777 7777777 77777777 77777777	*************	AAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAA	KKKKKKKKKK 44444444444	SONO ORONO O	200
	<u> </u>	4440000	000000000000	<i><u>aaaaaaaaa</u></i>			11111111111	pppppppppppppppppppppppp	
	**********	S XBKH S XBKH S 6BKH S 6BKH S 6BKH S 6BKH	A6244 M6290 F-603 N6290 N6290 1 E-603 1 21-R M HB	JXC JXC JXC WWXC WXC RXC RXC		DE CONTROL DE LA			
			888888888888888888888888888888888888888	HHHHHHH		CYCE TE PE		0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	
	22.00 23.20 23.20 23.20 23.20 23.20 23.20 23.20 23.20 23.20 23.20 23.20 20 20 20 20 20 20 20 20 20 20 20 20 2		8.25/20 9.00/22 10.50/24 10.50/24 9.00/20 9.75/22 10.50/24 9.75/22	7.50/20 9.75/20 9.75/20 10.50/20 11.25/20	8.88.79.79.79.79.79.79.79.79.79.79.79.79.79.	2.00/20 2.00/2	88.55/20 88.55/20 88.55/20 88.55/20 88.55/20 88.55/20	8.60	0.00
	2000 000 000 000 000 000 000 000 000 00	2000 2000 2000 2000 2000 2000 2000 200	2010000000		6.00 (200 (200 (200 (200 (200 (200 (200 (7.00/20D 22x6D 22x6D 22x6D 22x6D 22x2D 20x2D 20x	- PAGE
	400000000000000000000000000000000000000	8888888	2322305555	00 322x6 00 322x6 00 922x6 00 975 00	000000000000000000000000000000000000000				
	00000000000000000000000000000000000000	0.000000000000000000000000000000000000			23.00 23.00 23.00 25		######################################		
	13500 13500 13500 13500 13500 13500 13500 13500	12000 13000 13000 16000 21000		14000 115000 120000 23000 24000 26000		900000000000000000000000000000000000000		63500 63500 13500 13500 13500 1500 1500 1500	
	1077 1077 1077 1077 1077 1077 1077 1077	00000000000000000000000000000000000000	656 666 667 670 670 688 688 688 688 688 688 688 688 688 68	00000000	113 127 139 139 151 151 175 151 175 175 175 175 175 175	10020000000000000000000000000000000000	200000000 25550000000000000000000000000	22022222222222222222222222222222222222	3
	945156 9857 181 9857 181 9732 181 9732 181 9757 181 9857 185 9857 185 9857 185 9857 185 9857 185 9857 185 9857 185 9857 185	1565 1635 1850 1850 1252 2525 3175 175 1	2500 159 22400 166 2250 167 2250 167 2250 142 2350 142 4340 149 6925 149 7750 150	1695 0 27400 0 27780 0 32780 0 3200 0 4625 0	575 119 765 127 765 127 765 127 765 128 765 12	2850 6601 1095 11095 11095 11095 11095	465 535 530 530 530 126 630 126 630 126 630 126 136 136 136 136 136 136 136 136 136 13	10-130-130-130-130-130-130-130-130-130-1	Carrie o
	3 88 8	60 000 4 000 61 24 20 200 2	63 29	50 Aris			20044	40000000000	
	SHANNING SHA	2×××××	- OT OR HE OT OR WELCO HE OD			12000000000000000000000000000000000000		1111111111111111	- non-
	(a) (a) (b) (b) (c) (c) (c) (c) (c) (c) (c) (c) (c) (c	BCW-12 CCW-12 CCW-13 CCW-13 CCW-13 CCW-13	13B 17B 21B 21B 14BT 18BT 22BT 22BT 22BT D22BHT D22BHT	30G 40G 50G 50G 50G 70DR 80W	d T 201 306 404 404H 404H 404H 509H 509H 612H 614DR 614DR 614DR 614DR 614DR 614DR 614DR 614DR 614DR 614DR 614DR 614DR 614DR 612DR 613DR 61	(D) (G.C.) 137 (G.C.) 201 (G.C.) 306 (G.C.) 306 (G.C.) 509 (G.C.)	10. TC TD16 TD20 TE20 TF36 TF35 TF35 TF435 TF440 TG440	THA452 (c.e.) 100552 (c.e.) 700552 (c.e.) 700552 (c.e.) 710502 (c.e.) 71	E) 100
	(2) (2) (3) (4) (4) (4) (4) (4) (4) (4) (4) (4) (4	(g)	<u>.</u> : : : : : : : : : : : : : : : : : : :		puouna	600 600 600 600 600 600 600 600 600 600	8	83833838888 3 3 ₈ 969 5666666	100
	888768 888768 888768 8998 8988 8988 8988	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0		ā	2		H	ė ė	
	Соммента		111000001111111111111111111111111111111	=======================================	22222222222222222222222222222222222222	**************************************			24

+ Rear 32 x 6. †† Rear 7.50/16. (x) Delivered at Factory Price. Includes all Federal Taxes but does not include any state and/or local taxes. (*) Price includes chassis & cab. (E) Fer export only.

Dart—Any length wheelbase available at no extra cost. (Abvrolet—(A) Gross veh. weight, 8.000 lbs. with 32 x 6—10 ply rear tires. (A) Gross veh. weight, weight, weight, car axle with special tire equipment available at extra cost. (*) Gross veh. weight, (*) Gro

4 84 CT. (X) Man.VID 115 GEO. 3240 G.00.20D G

52		
FRAME	ide Rait imensions	DOS SOCIOSOS DE PREPERENTE ENTRE SOCIOSOS DE CONTROL DE
1	fand Location ype -A Dimension Std. W. B.)	EXECUTATION SERVICE SE
	mund fairstah	DASSASSON OS SERVICIOS SERVICIONAS SERVICIOS SERVICIONAS SERVICIOS SERVICION
BRAKES	S n'asiaque Saini.	1985 1985
	noisassion ype n'sanaq	
AXLE	lake and	00wn 00wn 00wn 00wn 00wn 00wn 00wn 00wn
AXLE	oitse & Torque de l'astro de l'as	ПИТИМИМИНИ ПЕПЕПЕПЕПЕПЕ В 2010000000000000000000000000000000000
	ear and Type	
	orward Spd's	Managamagagagagagagagagagagagagagagagagag
MISSION	bake and labol	NNN NN
	umber. iameter nd ength gg ength	ANNINNNNNNNNNNNNNNNNNNNNNNNNNNNNNNNNNN
SC	ax. Brake P. at R.P.M.	7177 - 28000
DETAIL	omp. Ratio	
NGINE	insmeasiqei	
ā	o, of ylinders, ore and troke	
	pue suq	OWN DOWN DOWN DOWN DOWN DOWN DOWN DOWN D
SIZES	bna Juon 189 189 189 5 mumixa 95 S S S S S S S S S S S S S S S S S S S	175001688 1750011688 1750011688 1750011688 1750011688 175001088 17
TIRE	Dandard bna inor	0.000
ote)	ax. Tires hassis W.c. itripped)	00000000000000000000000000000000000000
AL (See Keynote)	andard freelbase ax. W. B. urnished soss Vehicle eight with	\$\text{4.1}{\text{6.1}}\$\$\text{6.1}{\text{6.1}}\$\$\text
GENERAL	gniss gniss soir9 eieenn	83222222222222222222222222222222222222
	WAKE WODEL WODEL	Column C
	tedmuN en	- 1222年 - 12
		COMMERCIAL CAR JOURNAL

. 7. 3.3.3				uuu									53
		ARARE TERRET	ALLE X					FFF	**		00000000000000000000000000000000000000	Takakakakaka wana	
	NAME OF THE PARTY	XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX	not be not be be	X	**************************************	SEX-CAL	SHIPS SHIPS	x3x 1/3 x3x 1/3 x3x 1/3	222225 2525 2525 2525 2525 2525 2525 2		######################################	**************************************	ZXZ ZXZ
88888000000000000000000000000000000000	44-4440 XXXXXX	10x2% 10x2% 10x2% 74x2%	20000 20000 20000 20000		988883 98883 9783	0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.0	WKKKKKK		XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX			44444444444444444444444444444444444444	9x3 9x3
515151515252	90000000 90000000	000000 000000	555 555 555 67	327	2222222	3555444	888881-88 88881-88	56 38 56 38	000011388	1722228888	22200022222 222000222222	444444444	96
XXXXXXXXXX	KKKKKK	KKKKK	SXXXX		FFFEE	5++555	222222	NXX	PESTYNXX	XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX	55555555XX	KKKKKKKK	KK
Z	ನ ಪಡೆಯಿಯ	ವವರಾದ ಮ	0 0 0 0 0 0	0.0.0.				chenen		0.000.000.0	ಪ್ರೆ ಹೆ. ಹೆ. ಹೆ. ಹೆ. ಹೆ. ಹೆ. ಹೆ.	ಪಟ್ಟಿಸುವ ಸವಸನ	at at
923 923 923 923 923 923	800 4 4 70 70 200 5 4 4 70 70 200 5 4 4 70 70 200 5 4 70 70 70 70 70 70 70 70 70 70 70 70 70	578 578 660 442	578 578 578 660		510 613 687 687 875	875 540 540	8857 540 1138 1386 1138	477	9984444 880011117 448099999	4400000044 000000000000000000000000000		865 655 655 655 655 655 768	784
617 617 617	388 380 380 388 388	3888 3888 4388 2772	8888 443888 466	155 155 155	306 360 366 415 415 618	618 399 415 331 360 360	727 717 717 717 506 360 727	296 296 296	222222 222222 3402222 3402222	340 3367 3367 4777 6177 620 291 291	84207772884 48014440048	04488888888 04488888888 04488888888	384
TW4IA TW4IA		LAHEV LAHEV LAHEV	22222 59559	HHH	HHY HHY THY THY	HAV SMV SMV SMV	TYTY HAY		B41H B41H B41H B41H B41HV B41HV	B411HV B411HV B411HV B411HV T411A T411A B411H	141HV 141HV 141HV W841A W841A W841A 141HV 141HV 141HV	HEEREREEN H	IHV
11111111111111111111111111111111111111	222222	22222	22222	MMM MMM	72727≽	ASSES	*********	222	<u> </u>	######################################	<u> </u>	<u> 2222222</u>	
	F182 F182 F266 F266 F266 F31000	31000 31000 32500 266F	000000000000000000000000000000000000000		888888 888888	20000000000000000000000000000000000000	u 1673 u 1673 u 1673 u 1673 u 655 u 655	020H 020H 020H	99999999	F400 F500 F500 F500 F600 F700 F450 F450	88888888888888888888888888888888888888	00000000000000000000000000000000000000	5000H
	PER FI	88884	Tim 33	WD	Shu Fine Fine Fine Fine Fine Fine Fine Fine	0-000	EEEEEEE		REERRERE		EEEEEEEEE	222222222	E S
25555444400 0000000000	55555F	84488 EEEED		-22-	400000	97 160 160 160 160 160 160 160 160 160 160	2222222	666 666	8=88=9=9	00000000000000000000000000000000000000	8283484884 EEEEEEEEEE	8484848484 FEEEFFEEE	40 T
201-00000000000000000000000000000000000	52-6 1-6-1 12-6-12-6	8 4 4 4 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5	25 - 7 25 - 7 29 - 7 29 - 7	55-4	75-7 75-7 34-7	28 * * * 88 7 - 7 - 8 - 8 - 8 - 1 - 1 - 1 - 1 - 1 - 1 - 1	9-10 -22 -22 -10 -22 -22 -23 -23 -23 -23 -23 -23 -23 -23	14-6 83-6	425.084.284.28 425.085.85 425.085.85	6.44-852 6.43-8716 6.43-8716 6.43-8716 6.45-985 7.10-8.05 6.57-98 6.57	### ### ##############################	0-2888-21-28 21-684-31-28	71-7
						± ∞∞	T-T-T-T-T-T-T-T-T-T-T-T-T-T-T-T-T-T-T-	HHH	ETTETET 64400000	HHIII HIII HIII 	HEEKEHEEE CCCCCCCCC	EEEEEEEE	RR 755
	WHERE'S	THE STATE OF	20000000000000000000000000000000000000	20.00.00	20 20 20 20 20 20 27 27 27 27 27	222222 777777	A A COLAR	1000m	Z LLLLLL	70000000000000000000000000000000000000			
	0000011	19988	1000H		21W	21W	90 40	00H 00H 13A1	000000000	R2400 R1500 R2500 R1550 R1600 R1500 R1200 R2200		76738 56411 56411 56411 56411 573300	
	R656 R756 R756 5336 544	5644 5664 5683 5833	5644 5644 5644 1233	886	950 RELI 1300 1300 797	1300 1300 8 133 8 191 8 191	797 n 1300 1910	533	EREEREE	AREER ERE	7577	7.000 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	264 n 764
000000000000000000000000000000000000000	THE CONTRACTOR	45554 HHTTH	THE STATE	333	4000000 1000000	WWW.	TWCOOTH TWCOOTH	T-1-1-	00000000 88888888	2222222 000222 00022 0000 0000 0000 00	EEEEEEEEEE		FF
0000		£>>>&	4>>>		-88888_		A86 8 Tim 79740 A86 8 Tim 79740 B86 8 Own A820 5 Cia 1300 A62 5 Cia 1300 A62 4 Tim 79740	eo _	HDS HDS H41 H41 W42 W42 F51A		8888888	22222222	333
***********	000000	a 2000 a 2000 a 2000 a 2000 a 185F	Cla 185F Cla 200V Cla 200V Cla 200V Cla 200V	999	A 185F 5B330 5B330 5A430 5A430 17351	Piciologica	200000000000000000000000000000000000000	G T9	OWD OWD OWD OWD OWD W	Own F51 Own F52 Own F52 Own F52 Own F52 Own H4A Own H4A	5A620 5A620 5A620 7341 7341 7341 5A-620 5A430	5A430 5A430 5A430 5B330 5B330 5A430 5A430	1 5A3
MARIE MARI	NXXXXX	SUDUU K	NAKK				YYYYY YYYYY SPu Spu	XXX XBX	ZZZZZZZZ	000000000 XXXXXXXXX			
**************************************	000000	2222	-24-2-2	X5% X5% X5%	0000722			122	CONTRACTOR CONTRACTOR	**************************************	**************************************	**************************************	200
BUBBBBBBBBBBBBBBBBBBBBBBBBBBBBBBBBBBBB	my m m m m	SANAGA	3x10 3x10 3x10 3x10 3x10	25.2% XXX	222222 222222 222222	4000004 	4444666 X-X-XX- XXX-XX-	SISSE	9 0000000	2111111111112	44444460000	CTT NXXXXX	212 8 8 8
64444000000000000000000000000000000000	888888	88888	00000	3900 3900 3900 3900	25500 25500 25500 25500 77 75 75 75 75 75 75 75 75 75 75 75 75	1225000 122500 12250 122500 1225	telefelelets	1-1-1-	ब्ली (क्षेत्र क्ली क्ली क्ली क्ली क्ली क्ली	and the the traction the traction and and	101010 P. P. P. P. P. P. P.	tototototototototo	
883355 883355 11000256		72888	77-26 77-26 84-26 84-26		74-25 78-25 83-25 95-22 105-22	250 250 250 250 250 250 250 250 250 250	132-18 132-18 150-18 72-18 72-18		2000 2000	89-3200 93-2800 93-2800 1111-2700 1114-2600 114-2600 114-2600 118-3200 81-3200	8882228888 888888888444	22222222222	86-38
83933333333 8395000000000000000000000000000000000000		202220			175 188 210 286 308 1468	2500 2500 2500 2500 2500 2500 2500 2500	806448 8062724 8068 8068 8068 8068 8068 8068 8068 806	8277	82220022 82220022	12222222 22222222 2222222 2222222 222222	202000000000000000000000000000000000000	2000882020	
0000000000	000000000000000000000000000000000000000	20000	22224	666	4.300	17 17 17 17	4.6 17.6 16 15	===	80000000P	PPPPN000000000000000000000000000000000		0.00000FFF	1010
00000000000000000000000000000000000000							8666448 8574668 857857885			777777 77 89899999 80899999 80899999 80899999		**************************************	320
AXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX	**************************************	*****	77.4.4.4 XXXXX	4x x x x x x x x x x x x x x x x x x x	44 44 25	8 X X X X X X X X X X X X X X X X X X X	2 X X X X X X X X X X X X X X X X X X X	*****	*********	**************************************	**************************************	**************************************	4x4 4x4 4x4 12
000004444444	200000	00000	00000 00000	600	000000	4600004	0000004 0404440 08008888	60-3	6466666	00000000000000000000000000000000000000	4440000000	44448882444	44
20000444444 200000000000000000000000000	OXB3 OXB3 JXB JXB JXB	XXXX	S C C C C C C C C C C C C C C C C C C C		BEZ BEZ SMZE SOAL	HB6 3BK 3BZ 6MZ 6MZ 8RK HB4	3GAL HB6 HB6 HB6 HB6 HB6 HB6 HB6 HB6 HB6 HB6	XXB	FC13 D213 D213 HD23 HD23 NB24 NB24	A B25 B B29 B B29 B B29 B B36 B B36 B B36 B B36 D 232 D 232	HB44 HB6 HB6 HB6 HB6 K428 K428	A SECONDARY SECO	BZ
0000000000		Her J	Here	JWD JWD	Wau Wau Wau Wau Wau Wau	Nau Nau Nau Nau Nau	Wau 6GAL Cum HB6 Wau 6GAL Cum HB6 Cat D4600 Cat D4600	Her JX Her JX	Wau Wau Wan Wan We We We	OW FAB259 OW FBB298 OW FBB298 OW FBB361 OW FBB361 OW FBB361 OW FBB361 OW FBB361 OW FBB301 OW FBB32A		Bud K438 Bud K393 Bud K393 Bud K393 Bud K393 Bud K393 Her JXCM Her JXCM Coun AA6	Vau
2558888888888	0 000	000000	88888	5585	988888	88888	24440	000	82202020	888888 88	88888888888	**************************************	000
690000 69000 690000	00 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	9.75 9.75 10.50	9.75	7.00/	88.25 9.05 9.75 1.25	9.75/ 9.75/ 12.00 12.00	12.00/24 12.00/24 13.50/24 13.50/24 9.75/20 11.25/20	7.50/	0887750 0887750 08850 08850	9.00/20 9.75/20 9.75/20 10.50/20 10.50/20 40x10 7.50/20	9.75/ 10.50 10.50 10.50 10.50 10.50 10.50	10.50/24 9.75/20 10.50/20 9.75/20 9.75/20 9.75/20	00.6
	0025 0025 0025 0025 0025 0025 0025 0025	000000	00000	898	000000	200000	12.00/24D 13.50/24D 13.50/24D 13.50/24D 13.50/24D 11.25/20D 24.00	S02	9998889	000000 0 0000000 0	555555555555555555555555555555555555555		
000000000000000000000000000000000000000	9000000	7.000	7.000	8.00/	6.50 7.50 9.00 10.50	10.50 9.00 9.00 11.25	2222222	8.00/ 32x6 6.50/	6.50 6.50 6.50 6.50 6.50 6.50	7.00/20D 7.50/20D 7.50/20D 7.50/20D 9.00/20D 9.00/20D 9.00/20D 36x8D 30x548 30x548	080000000000000000000000000000000000000	20000000000000000000000000000000000000	1210
7560 7560 7560 8850 10065 10620 10650	33200 33200 46000 46000	\$2000 \$3000 \$7000 \$7000	55000 55000 50000 50000 50000		44200 5100 6660 6660 6660 6660	0500 6520 87350 9500 9500	111920 151920 151225 151225 111920 111920	4000 4000 4000	98844666 888668666 4886668666 2886668666	862222 862242 8622426 8662426 86666464 866664 866664 866664 866664 866664 866664 866664 866664 866664 866664 866664 866664 866664 866664 866664 866664 866664 86666464 866664 866	7350 10000 10000 10000 14000 1	22222222222222222222222222222222222222	7750
	1500 2000 3000 4000 6000	18000 13000 13000 13000			!!!!!!			111		-	9428282838 9428088888888888888888888888888888888888	20000 20000 20000 20000 20000 20000 20000 20000	
1006 1006 1006 1006 1006 1006 1006 1006	222222 222222 222222 222222 222222 22222		2220 2220 2220 2220 2220 2220 2220 222	455		8252888	4445 1500 1500 1500 1500 1500 1500 1500	196 214	2222222	2227 2227 2227 2227 2227 2227	00000000000000000000000000000000000000	2004 2004 32 2004 130 2004 130	215
200000000000000000000000000000000000000	3000000	136 136 136 136	38688	8 5 5 5	888344	4222888 6000444	44400844	3008	8888866	455554446055	222299222	**************************************	755
\$ 4080 \$ 4080 \$ 5610 \$ 5610 \$ 7000 7 10	785 765 795 895 1045	1395 1625 1795 1995 1995	2595 2845 2995 3195 5500	553 592 880	22125 22125 30275 49005 6050	2222 2222 2222 2222 2222 2222 2222 2222 2222	2448 84425 86225 68725 68725 68725 68725 68725 68725 68725	825 1120 955	6056 6056 6056 6056 6056 6056 6056 6056	1550 1975 2185 2185 2185 2185 2185 2185 2185 218	5505 5789 5789 5789 5080 3550 3550	2230 2330 2330 2330 2330 251 251 251 251 251 251 251 251 251 251	3015
2000 2000 2000 2000 2000 2000 2000 200	200 24	4 0 000 0	700 m		\24	27 mm 20 mm							1010
00000000000000000000000000000000000000	444444 	2444 600040	4444 88844	288	\$8888 \$8888	2000000	22 0 0 4 0 5	222	20000000	99999999999	222-0-222	-84400P3844	-
インの日本では、日本では、	1264400	25. 70. 70. 70. 70. 70. 70.	DJX55A DJX76A DJX75A DJX85A	300	0444	(D) 43W 83W 85W 87W 87W	(D) D98 (D) D98 (D) D98CD (D) D98CD	8688	00000000	DO DE PER	00000000000000000000000000000000000000	99999999999999999999999999999999999999	513
10000000000000000000000000000000000000		Ď	6888 6888			8:::5	9 6		© 2	D8-40 D8-50 D8-50 D8-50 DR-50 DR-60 DR-70 DR-70 DR-70 DR-70 DR-70 DR-70	\$		ce (15)
		* *	AAAAAAA	0				lana	Inter- (5)		8		La France (1 Republic
(1) ADC (1) AD	<u> </u>	<u> </u>	2 8 88	spn	# :::::			0			8 :::::::::		7
	<u> </u>	<u> </u>	2 8 88	113 Hudson	116 117 119 120 21	364.597	838588	135 Indi	=	\$2.44.50.00.00.00.00.00.00.00.00.00.00.00.00.	74	87880772845 8788077875	77
COM MEI	E 58880000	505040 505040 505050	2000 2000 2000 2000 2000 2000 2000 200	113 Huds 114	王	264582	27828888888888888888888888888888888888		=	6444431 6444431 6444431 6444431 6444431	74	+ 1772 1000 1777 1777 1777 1777 1777 1777	176 La
888 (Google And	E 58880000	505040 505040 505050	2000 2000 2000 2000 2000 2000 2000 200	-	王	122 124 124 126 126	22221122 83282828		=	44446000040	74	100 100 100 100 100 100 100 100 100 100	176 Lau

TIRE	200	Standard Front and Rear	8.25/20D 8.25/20D 9.00/20D 9.00/20D 9.75/20D 9.75/20D 10.50/20D	6.00/178 6.00/2008 6.50/2008 7.00/2008 7.50/2008 7.50/2008 8.25/2008 8.25/2008	828888888888888888888888888888888888888	3288288888	5555555555	88	6.00/168 6.00/168 6.50/168 6.50/168 6.00/2018 6.00/2018 6.50/2019 6.50/2019 6.50/2019 7.50/2019 7.50/2019 8.28/2019	272222222	9.75/20D 9.75/20D 9.75/20D 9.75/20D 10.50/20D 10.50/20D 10.50/248
E SIZES	- 2	mumixaM sxiS sniT bedeimuni	9.75/20 9.75/20 9.75/20 9.75/20 10.50/24 10.50/24 11.25/24	2000000000		00.00 00			6.50/16 6.50/16 7.50/16 7.50/20 8.7.50/20 8.7.50/20 8.7.50/20 8.25/20 8.25/20 9.25/20 10.50/20	8.25/20 8.25/20 9.00/20 9.75/20 9.75/20 10.50/22 10.50/22	0000-0mm
		Make and Model	Wau 6BZ Wau 6BZ Wau 6MZR Wau 6MZR Wau 6MZR Wau 68ZR Wau 6SRLR Wau 6SR	000000000	00000000	Budd Budd Budd Budd Budd Budd Budd Budd	O O B B B B B B B B B B B B B B B B B B	00	OWED OWED OWED OWED OWED OWED OWED OWED	Wau 6BK Wau 6BK Wau 6BK Wau 6BK Wau 6MK Wau 6MK Wau 6MK Wau 6MK	WWW WW W W W W W W W W W W W W W W W W
ENGINE		No. of Cylinders, Bore and Stroke	44444444444444444444444444444444444444	######################################	# 4 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	80 80 40 80 00 00 00 00 00 00 00 00 00 00 00 00	######################################	8-3 1/6 x 4 3/6 6-3 1/6 x 4 3/6	6000000000000000000000000000000000000	*********	# X X X X X X X X X X X X X X X X X X X
	-	Displaceme	651755555555555555555555555555555555555	00000000000000000000000000000000000000	2222222 2222222 2222222 222222 222222 2222	4800	25222222222222222222222222222222222222	16.7	######################################	441919191919	CCCCCONUM .
DETAILS	-	Torque lb. Max. Brake H.P. at R.I	210 86-3000 226 86-3000 286 96-2400 286 96-2400 286 96-2400 328 111-2400 378 125-2300 470 145-2000		270 108-240 310 118-240 166 78-300 188 83-300 220 94-300 220 96-280 250 103-260	210 210 270 270 270 270 270 270 270 270 270 27	336 118-200 382 131-200 152 63-230 212 85-240 224 90-230 224 96-230 336 118-200	145 70-3000	98 42-280 98 72-280 145 70-280 150 73-300 150 73-300 150 73-300 150 73-300 150 73-300 150 73-300 150 73-300 178 83-280 178 83-2	1888 85-3200 1888 85-3200 1888 85-3200 1888 85-2200 252 85-2500 188 85-2500 188 85-2500 257 85-2500 267 89-2400	302 102-2400 302 102-2400 328 125-2400 331 110-2300 470 145-2000 470 145-2000 470 145-2000
	Main	Number, Diameter and and Length	00000000000000000000000000000000000000	7.2.2.2.2.2.2.2.2.2.2.2.2.2.2.2.2.2.2.2	00000000000000000000000000000000000000	7-2-2-5-8-10 07-3-8-10 07-	7-3 + 3 + 3 + 3 + 3 + 3 + 3 + 3 + 3 + 3 +	0 4-2 % x5 H	64644666666666666666666666666666666666		
TRANS-		Governor	Y Ful 5A33 Y Ful 5A33 Y Ful 5A430 Y Ful 5A430 Y Ful 5A620 Y Ful 5A620 Y Ful 5A620 Y Ful 5A620		Y Own CF Y Own CF Y Own CF N WG TRIII N Fu TRI4 Y Fu TRI4 Y Fu TRI4 Y Fu TRI4 Y Fu TRI4 Y Fu TRI4 Y Fu TRI4	Y Own BF Y Own CF Y Own CF Y Own CF Y WG TRI Y FU TRIA Y FU TRIA Y Own BF	Y WWG Y WWG Y WWG Y Y Fu 1 Y Fu 1 Y Y Own Y Own Y Own Y Own Y	NN NN P.P	WG T88		Y Own UC2 Y Own UC3 Y Ow
NO	9,pd	S brawrol	PATERENO	Q4400000000	1010441010101010	₽	00440000000	888	0 0 000044444004000 0000000000000000000	0) 1010	44444444
REAR		Make and	Im 55300H 11s 72300H 1m 58300H 11s 72300H 11s 1337H 11s 1337H 11s 1757H	Cla RA40 Tim RA11 Own RA12 Tim RA22 Tim RA28 Own AR Own EM Own EM	Own BM Own BA17 Own RA17 Own RA21 Tim RA21 Own RA28 Own EM	Own EM Own EQ Own BA Own BA Tim RA11 Own RA22 Tim RA26 Own RA26 Own EQ	Own BM Own BX Tim RA11 Own RA17 Own EA Own EQ Own BM	Own		53307H 54411H 54410H 76410H 58300H 72000L 775733H 775733H	Par 18100M Nen 18100M Nen 18140M Nen 18140M Nen 18140M Nen 18186W Nen 18186W Nen 18186W Nen 18186W Nen 18186W Nen 18186W
IR AXLE		Gear and 'Drive & To	ARREARE Socoocoo Socoocoo Socoocoo		2228888222 7777777777777777777777777777	252228888882 777777777777777777777777777	72228882222 222277777777777777777777777	Hy 1/2 H 3	00000000000000000000000000000000000000	民族民族民族民族民族	COCOTOTO COCOTO COCOT
-	dailt	Ocer Retion I	57-7-8-40 T 57-8-40 T 77-8-40 T 85-9-41 T 85-9-41 T 85-9-10 T 75-10-19 T	112-6-33 114-6-38 114-7-48-6-89 114-7-48-6-99 11-8-19-6-6-99 11-8-19-6-99 11-8-99 11	24 - 25 - 25 - 25 - 25 - 25 - 25 - 25 -	48.64.0 m m m m m m m m m m m m m m m m m m m	24 - 4 - 4 - 4 - 4 - 4 - 4 - 4 - 4 - 4 -	.73-4.78 Own	4.4.5.9.88.88.89.89.89.89.89.89.89.89.89.89.8	83-6.80 71-7.40 71-7.40 35-8.21 77-7.80 74-10.8 74-10.8 74-10.8	11-10 8 Tim 86-9 20 Tim 86-9 20 Tim 11-10 8 Tim 11-10 8 Tim 16-10 6 Tim 21-12 4 Tig 21-12 4 Tig 26-12 4 Tig 26-12 4 Tig
AXLE		Make and Model	m 35000H IIm 35000H IIm 35000H IIm 35000H IIm 35100H IIm 26452H IIm 27452N W	2 FA18 TO FA12 TO FA12 TO FA12 TO FA16 TO FA19 TO F	BBW BBW BBAB BBFA12 BBFA13 BBFA13 BBFA13 BBFA13 BBFA13 BBFA13	DECONDECTION OF THE PROPERTY O	BM FA12 FA12 FA13 CHOCHOCHOCHOCHOCHOCHOCHOCHOCHOCHOCHOCHOC			33000H 33000H 33000H 33000H 33000H 35000H 35000H 35000H	35100H 35100H 26450N 86450TW 86450TW 152-TW 152-TW
8	SER	Make Location Type Operat'n Lining	L4IHV 384 L4IHV 384 L4IHV 384 L4IHV 384 L4IHV 463 L4IHV 495 L4IHV 495 WerlA 868	14IH 296 14IHV 325 14IHV 370 14IHV 370 04IMV 441 04IMV 498 04IMV 498	041MV 690 041MV 690 141HV 328 141HV 328 141HV 370 141HV 370 041MV 468	041MV 468 041MV 468 041MV 690 141H 226 141HV 328 141HV 328 141HV 328 041MV 468	041MV 690 141H 296 141HV 329 141HV 329 041MV 468 041MV 468 041MV 569 041MV 569	04TH 148 04TH 148	LAIH 198		L41HV 510 O21MV 576 O21MV 528 W841A 574 W841A 646 W841A 7081 W841A 7081
BRAKES	ERVICE	Drum Area	44446668 0000000004 44446404	88800000000000000000000000000000000000	850 850 850 850 850 850 850 850	8800874 880874 880880 880880 9808 98088 98088 98088	0288 0884 098 0288 0884 098 0280 0886 0886 0987 0986 0886	251	99888844444466666 4449968889999666 9977768888888	616 672 754 754 756 756 1138	990 1724 p 746 s 970 p 176 s 176 s 176 s
	neibn	Drum Material Hand Loci	XXXXXXXXX	XXXXXXXXX	XXXXXXXXX	**************************************	XXXXXXXXX	COTTX	DODOS & & & & & & & & & & & & & & & & & & &	XXXXXXXXX FFFFFFFFF	
	noian (,i	C-A Dimer	96 96 96 96 96 96 96 96 96 96 96	222222222222	2000000000000000000000000000000000000	748888888555 72	\$2200000000000000000000000000000000000	37 # 40 #	444444444444444444444444444444444444444	9911111	80004444444444444444444444444444444444
FRAME	su	Side Rail	\$25,000,000 \$25,000 \$2	2. 2. 2. 2. 2. 2. 2. 2. 2. 2. 2. 2. 2. 2	6 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	99 5 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	10%x3,x4 10%x3,x4 8x3x,4 8x3x,4 9x3,x4 9x3,xx4 10%x3,xx4 10%x3,xx4 10%x3,xx4 10%x3,xx4	6x2x 16 6x2x 16		**************************************	00000000000000000000000000000000000000

2.00016.00/168. [6.36/16 | Own Or | 6-3 4 x45; [226]6. 9]173 | 99.340014. 252 x51 | N.W.O. Trus. | 9154 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1505 | 1

† Rear 32 x 6. x Front 7.00/20. (*) Price Includes Chassis & Cab. + Denotes New Models or Change in Specifications.

					мы				33
بإ با	000000000000	0000			55	6666	HHAHHHH	000000000000000	
	of text temple eligentic epicentic eligentic entremple evil a edit entre	Zu Zu Zu Zu Zu	K 444 X XIIIIIII X X X X X X X X X X X X	XX4X 4 44444X	19.19		No. 50 50 50		
ANN	XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX	X3X X3X X3X X3X	XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX	CCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCC	x1%x x1%x	XXXX X3XX X3XX	S S S S S S S S S S S S S S S S S S S	O THE THE NEXT WAY	X3X X3X 3X 3X
144 7 20 00 00 00 00 00 00 00 00 00 00 00 00	1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-	7777	00000000000000000000000000000000000000	00000000000000000000000000000000000000	2000	9x3x 9x3x 1015 1015	77% 9x3/x3/x3/x 9x3/x3/x 8x3/xx/x 12/xx3/xx/x 12/xx3/xx/x 12/xx3/xx/x	7.4	976x 976x 10x3
90141400 W	747474 TA	76776	141414141414141414141414141414	. /*	×:	tes tes too to			14/4/2
**************************************	296232525252	20000	8888858888888888888	28222222222	53	**************************************	0000000	7309999999999	200
-			**********	5555555555555555	44		KEEEEEE	****	200
MANAGE PARTIES	กลลลลลลลลลลล	य य य य	4-1-1-1-1-1-1-1-1-1			2222	HHHHHH	4444444444444	555
OFFEZZZZZZZZ	00000000000000000000000000000000000000	2020 1020 1020 1020 1020 1020 1020 1020		24400000400000000000000000000000000000	A 48	9999	ವೆ ನೆ ವೆ ವೆ ನೆ ನೆ ನೆ ಲಾ ಉಂ ಉ ಉ ಯ ಯ		
8372 8372 8372 477 477 659 659		tototo	444466888000 CCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCC	105 105 105 105 105 105 105 105 105 105	311	659 866 975 975	452 578 578 786 976	452 867 867 867 867 867 976 976 976 976 878 878 878 888	864 972 972
421 421 421 421	3333 3333 3333 3333 3333 3333 3333 3333 3333	552 552 495 495	00000000000000000000000000000000000000	66000000000000000000000000000000000000	135	539	270 335 335 534 625 701	24444444000000000000000000000000000000	536 625 654
	>>>>>>>>>>>		5555555555455			>>>>			
	**************************************	01HV 61HV 61HV 61HV	A CANCACCOCCOCCOCCOCCOCCOCCOCCOCCOCCOCCOCCOCC	9000 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	IM	MAH	ZZZZZZ Z Z Z Z Z Z Z Z Z Z Z Z Z Z Z Z	22222222222222222222222222222222222222	VAILE VAILE
22222222	Chacharantan	1999	H4444444444444444444444444444444444444	2222777777722222	B4 B4	HHHH 4444	222222\$	222222222 <u>222</u>	22₹
ZZZZZ							WHERE'S	92 92 92	
F155 F256 F256 F256 F256 F256 F256 F256 F2		RE			00.00	33233	30B 544B 551H 551H 213H 213H	F33-H8 HU 1937 1937 1937 1337 1337 1757 1910 F33-H8	F213 F313 F417
	ord dord ord ord ord	Ford Chev Ford Chev	0 WHD 0 OWN		Own Own	8888	**************************************		888
ADDOREFERE	000000000000000000000000000000000000000		000000000000000000000000000000000000000	000000000000000		FFFF	888888	Wis I	
2-000000044000	5-9.02 5-9.02 5-9.02 5-9.02 5-9.02 5-9.02 5-9.02 5-9.02 5-9.02 5-9.02 5-9.02	*-6.67 -6.166 -6.67 -6.166	66666666666666666666666666666666666666	# 1.44 60 84 17 81 17 17 44 40 80 80 40 17 17 17 17 17 17 17 17 17 17 17 17 17	5.11	10000	88888888 88822488	× × × × × × × × × × × × × × × × × × ×	
000001-01-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1	00 100 100 100 100 1	1919	400044000000000000000000000000000000000	797-222-25-25-25-25-25-25-25-25-25-25-25-25	2-4	5555	280-14-14-14-14-14-14-14-14-14-14-14-14-14-	**************************************	253
44004040000		2222	ら444らららららててのアアファウ	ARABHERERERERERERERERERERERERERERERERERERER	4	2222	500000000	@@@@@@@@# Pr	000
	90000000000				田田		напапап		
10000000000000000000000000000000000000	KAN KAN KAN KAN KAN	S S S S S S S S S S S S S S S S S S S	AND	NONNON NONNONN NONNONN NAMED AND NONNONN NAMED AND NONNONN NAMED AND NAMED A	80 30	2000	00000000000000000000000000000000000000	waaaaaaaaaaaaaaaa FFFFFFFFFF	2000 FFF
						_	53521H 54411H 5002L 72300H 1337BH 1737KW	X XX	
RESERVED BARSES	465 6000 7000 7000 7000 7000 7000 7000 70				~~	5002 72000 1337 1337	3521 021 300 378	1 (53543H) wn HU wn HU wn 1938 wn 1938 wn 1938 HI 1337 HI 1337 HI 1337 HI 1357 HI 1357 WN 1938	2000 337 737
THE BEAUTION OF THE PARTY OF TH		Tim Chev Tim Chev	E5665666666666666	E56666666666666	222	8888			18 13 18 13
2000HEHEHE	NEGREPA PER SECOND		00411 00411 00411 00411	5000000000000000	Sal	FFFF	FFFFFF	FOOODOODDDDFFFO	222
高名を全全で来るらいら	ए सं या ए रा सं या पा स स स स	90 90 90 90	44444400000000000000	000000440040040000	8000	20 00 00 00	@@@0000		101010
## > >>>>		-Own -Own -Own			T84D T84D	DF4 TF4	T9 MGU A430 A620 A620	2000 0 0000000000000000000000000000000	222
22000 27000 27000 27000 27000 27000	bey ord	2525	899898888888888888	WAD WAD WAD WAD WAD WAD WAD WAD WAD WAD	EF DD	2266	G T6 B B1 MC 5A3 5A3 5A6	1 5B33 1 5A43 1 5A43 1 5A43 1 5A62 1 7A40 1 7A40 1 7A40 1 7A40 1 7A40 1 7A40 1 7A40 1 7A40 1 7A40	5A620 5A620 7351
	OOOOOOHHHHHH	Ford	OWTH OOWTH O		MA M	00wn 00wn	WG Cla Fu Fu Fu Fu 5	FE BEL SOOF	Fu
ルスススススス以以以	::::::::::::::::::::::::::::::::::::::	ZZZZ	MAKKAKKKKKKKKKKKKKKKKKKKKKKKKKKKKKKKKK	たえななななななななななななななななななななない。	ZZ	五五五七	ZZZZZZZ	えんえんんんんんんんんん	- AMM
######################################		4040	000000000000000000000000000000000000000	2 22-4-1-1-1- 222	1010	*****	**************************************	2444 2444 2444	12/2/20
HOROGOOOOOOOOOOOOOOOOOOOOOOOOOOOOOOOOOO	4/4/4/4/4/4/00 ro ro ro ro	5x4 5x5 4x5 4x5	20000000000000000000000000000000000000	24/2/2/2/2/2/2/2/2/2/2/2/2/2/2/2/2/2/2/	3x5 3x5	3 X X X X X X X X X X X X X X X X X X X	SXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX	XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX	3x12 3x13 4x18
***	44444400000000	2424	1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-		6169	10101010	46666666	CONTRACTOR CONTRACTOR	Pri Pri Pri
2000 2000 2000 2000 2000 2000 2000 200	000000000000000000000000000000000000000	3200 3200 3200 3200	64444444444444444444444444444444444444	44444444444444444444444444444444444444	3200	00000 55500 55500	2555555 2555000 2555000 2555000 2555000	85-320 96-2400 96-2400 96-2400 1112-2400 1112-2400 1126-2400	2200 2200 1800
30000000000000000000000000000000000000	60000000000000000000000000000000000000	17301730	233660000000000000000000000000000000000	######################################	8. 8. 8. 8.		888 985 120 120 120 120 120 120 120 120 120 120	64666666666666666666666666666666666666	252
	2222222222	4040	46660066666000000	000004000000000000000000000000000000000		53 108 123	8888888	200000000000000000000000000000000000000	132-2
\$5500044000000 \$550000000000000000000000	DODGE CCCOOO	1150 170 170	91111888888888888888888888888888888888	00 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	7 100	23888	233 276 276 276 276 400	27088 2883 2883 2883 2883 2883 2883 270 270 270 270 2883 2883 2883 270 270 270 270 270 270 270 270 270 270	327 365 468
01	000000 000000	9999	ရောက်ရာရာက်ထဲထဲထဲထဲရာမှာရာရာရ	0.400000000000000000000000000000000000	1010	10101010	47-45000	ပ်လုံလုံလုံလုံလုံလုံလုံလုံလုံလုံလုံ	
00000000000000000000000000000000000000	22222222222222222222222222222222222222	2221 233 216 216		252442822222222222222222222222222222222	134	404 404 501	244 3330 501 501	288444462882 288244662462 288257777775	462 517 648
HANNER MANNER MA	N X X X X X X X X X X X X X X X X X X X	XXXX 00000	**************************************	88888888888888888888888888888888888888	x43% x43%	**** 4440 %%%%	12/2/4 4/4/A	######################################	70.70
0000000004444 \$\$\$\$\$\\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	SOCOOOOOOOOOOOOOOOOOOOOOOOOOOOOOOOOOOO	and to the		The place of the p	700/00	74 14 14 Take		\$ 10 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	2223
220000000000000		80000	p-200-200-200-200-200-4-4-4-4-4-4-4-4-4-4		4.4 8.60	4444	0000000	0000000000000000	dedada
9258							A6244 M6271 E-602 M-6330 20-R 21-R	Vau BK Vau MKR Vau MKR Vau SRLR Vau SRLR Vau SRKR Vau SRKR Vau RRK Vau RRK Cer HXE Cer HXE HXE HXE HXE HXE HXE HXE HXE HXE HXE	HAH
*PETRONS WAS A SECOND OF THE PERSON OF THE P		8 . 8	000000000000000000000000000000000000000	245200000000000000000000000000000000000	44.44 00.00	404 404 501	A62 M62 M62 M62 M62 M62 M62 M62 M62 M62 M	MAK MAZ MAZ MAZ MAZ MAZ MAZ MAZ MAZ MAZ MAZ	68RL 6SRK 6GAL
e e e e e e e e e e e e e e e e e e e	Chev Chev Chev Chev Ford Ford Ford Ford	bed bev	00411 00411 00411 00411 00411 00411	00WH 00WH 00WH 00WH 00WH 00WH 00WH 00WH	OWN	Own Own Own		and sand sand sand sand sand sand sand s	800
OCO CHMMMMMM	00000000	ぎりぎり		000000000000000		0000		DDDDDDDDDDDDD	DDD
200000000000000000000000000000000000000	8888888888888	2222	8.255/20 8.255/20 8.255/20 9.05/20 9.75/20 10.56	11.25/22 11.25/22 11.25/22 11.25/22 9.25/20 9.05/20 10.56/20 10.56/20 11.25/24 11.25/24	.00/168 (9)	9.00/20 9.75/20 9.75/20 10.50/20	8.25/20 8.25/20 9.00/20 9.75/22 10.50/22	9.00.20 10.50 20 10.50 20 10.50/20 111.25/20 111.25/20 12.75/20 13.50/20 13.50/20 10.50/20	50/20 50/20 25/20
90000000000000000000000000000000000000	90000000000000000000000000000000000000	8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8	0.0000000000000000000000000000000000000	200000000000000000000000000000000000000	6.00	9.00 9.75 10.5	8.25 9.00 9.75 11.25	0.0000000000000000000000000000000000000	10.5
22 22 22 22 22 22 22 22 22 22 22 22 22	000000000000		6.00,208 66.56,201 77.00,201 77.00,201 77.50,201 77.50,201 8.25,201 8.25,201 9.00,20	9.77/20D 9.75/20D 9.75/20D 10.50/20D 10.50/20D 1.60/20D 1.50/20D 9.00/20D 9.75/20D 9.75/20D 9.75/20D 9.75/20D 9.75/20D 9.75/20D 9.75/20D 9.75/20D 9.75/20D 9.75/20D	an an	9.00/20D 9.75/20D 9.75/20D 10.50/20D	6.50/20D 7.50/20D 8.25/20D 8.25/20D 9.00/20D 9.75/22D	6.50/20D 9.75/208 9.75/208 9.75/208 11.25/208 11.25/20D 10.50/20D 9.75/20D 10.50/20D 11.75/20D 12.75/20D 13.50/20B 13.50/20B 13.50/20B 9.75/20D 9.75/20D	208 208 208
20000000000000000000000000000000000000	00000000000000000000000000000000000000	0222	88888888888888888888888888888888888888	000000000000000000000000000000000000000	/16	02000	8888888	000000000000000000000000000000000000000	250/2
000000000000000000000000000000000000000	889889889889889 8899889889889 8899889	32x6D 7.00/20D 7.50/20D 7.00/20D	0.0000000000000000000000000000000000000	20.05 0.05	5.50/168 6.00/168	9.00	88.255 90.05 10.55	00000000000000000000000000000000000000	10.5
28.00 28.00 28.00 28.00 28.00 28.00 28.00 20.00	4500 44650 44650 44650 4700 51100 56150 56150	6200 6100 6400 6100	3695 44450 48450 4820 55155 55155 55155 64475 77768 88063 8100 8100 11000	0000770024559809	1285	8415 9900 10915 11145	4480 5060 6500 10000 12500	2460 7100 7800 8100 8800 8800 11200 112300 112300 12300 12300 12500 12500 12500	888
			8444472722225111888E01	000000000000000000000000000000000000000		2001	42200000	2011128888777	9800 11000 11800
	15000 115000 115000 17000 115000 115000 115000 115000 115000	26500 30000 30000			3350	20000 24000 30000		13000000000000000000000000000000000000	
300000000000000000000000000000000000000	200440000000	4040	&&&&&&&&&&&&&	01000000000000000000000000000000000000		80000	0000000	2000000000000404 2200000000004004	990
138 180 138 180 138 180 138 180 101 162 142 184	254281-554881 281-281-281 280044000000000000000000000000000000000	5 194 4 198 4 198 198	66 66 66 66 66 66 66 66 66 66 66 66 66	4 122 4 4 122 4 7 123 5 105 5 105 6 105	00100	3 163 8 168 168	43 180 45 182 55 185 55 185 60 190 85 210 85 210	2x000000000484 3722222222222222	
3000000000000	20212222222222222222222222222222222222	155	000000000000000000000000000000000000000	20000000000000000000000000000000000000	001	00 163 0 168 0 168		88877777777777488	9220
2550 7710 7710 7710 7710 7710 7710 7710 7	1350 1492 1671 1671 1671 1671 1671 1671 1671 167	2130 2175 2235 2175	9200 9200	73500 134 73500 134 73500 134 73500 134 73500 134 73500 97 73500 97 73500 97 73500 109 7400 109 7500 109 7500 109 7500 109 7500 109 7500 109 7500 109	(6)	5000 6000 6750 7250	2375 2375 2300 2500 2500 2500 2500 2500 2500	2800 655440 655440 655440 655440 6550 6530 6530 6530 6530 6530 6530 653	5425 6125 6050
					Pē.	::::	ha		
**************************************	20000000000000000000000000000000000000	8-8- 100 100	00 00 00 00 00 00 00 00 00 00 00 00 00	800111100 800111100 800111100 800111100 8001	1000lbs.	9	7000040 7000040 9 44 0	8 4400000000000000000000000000000000000	4-5 5-7% 7%-1
2002SUZSZ02	NORMANNONNO	4450	004M4~804004;400;4	\$:00-1-36944000F	8000	C	040000F6 -01000040	26人口人口口であたりの20	444
SKS KSK	000000000000000000000000000000000000000	80000 80000	05000000000000000000000000000000000000	72 22 80 80 818 80 818 72 82 82 82 82 82 82 82 83	SC4	TA'Z	FFFFFF	THEODERANDER	444
(co.e.) K180 (H16) (co.e.) K180 (co.e.) K200 (co.e.) K20M (co.e.) K20M (co.e.) K30M (co.e.) K30M	II TRC-400H TRC-500H TRC-500H TRC-500H TRC-500H TRF-500H TRF-500H TRF-500H TRF-600H	ord(C) EB-94 (C) EB-97 (C) BC-94 (C) BC-97	700.7 700.7 700.7 700.7 700.7 700.8	(CO.E.) 8108 (CO.E.) 8208 (CO.E	(9) SC48 SCOE48	5 4444	FFFFFF 14.00005-2	HH6 CUA CUA CUA SUA SUA M16 M16 M17 M17 M10 M17 M10 M10 M10 M10 M10 M10 M10 M10 M10 M10	:::
(6.0 6.0.	THE THE TENT OF TH	5.00		6966666	:6	≥ 5666		0	:::
epi	7ucks 000000000000000000000000000000000000	Warford	2		llys.	3 02	5 ::::::	8	
10 market 20 mar	F 000 000	*	White		8	Four-Wheel-Drive S Auto-(1) (d) 4x4 DF Car (0) 4x4 NF (1) 4x4 NF (2) 4x4 NF	Corbi	<u>s</u>	Hug
\$2000000000000000000000000000000000000	950 1001 1001 1002 1003 1003 1003 1003 100	9001		744 888 888 888 887 887 887 888 888 888	143	147	155 155 155 155 155 155 155 155	156 1662 1663 1663 1664 1664 1664 1664 1664 1664	171
0		+ +	+	•	•			***	

COMMERCIAL CAR JOURNAL JUNE. 1939

C. Reserve B. R. R. C. Price, and such a contract of the contr

56										
		Type						a thinitial	######################################	בובבבבב
FRAME	8	Side Rail Dimension	7 17 12 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	77.77 27.77 27.77 27.77 27.77 27.77 27.77 27.77 27.77 27.77	55%x4 7x2%x4 7x2%x4 7x2%x4 7x2%x4 7x2%x4 7x2%x4 7x2%x4	94 x32 x y y y y y y y y y y y y y y y y y y	10 4 x 3 x 4 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	1000 1000 1000 1000 1000 1000 1000 100	KURUKA 44 4444 KURUKA KERA 4444 SEBEKUKE BEKE KURUKE BEKE KURUKA KERA KERA	944.83.83.94 98.33.84 10.58.83.84 10.58.83.84 10.58.83.84 10.58.84
	nois:	C-A Dimen (Sed. W. B.	3 55555244 2 225	22222	84455338 88858830 7.7	222222	2222882222	25222222223333 55222222223333	41146668888	442388428
	noi3	Material Hand Local Type	555555	2222	444 44X	XXEEEEE	ESSEXXESSES	*******		ESSESSE STATES
BRAKES	33	Drum Area mund	412 528 578 678 678 678 678 678 678 678 678 678 6	785 975 975 975 9	2008 2008 2008 2008 2008 2008 2008 2008	4522 a 2527 a 2527 a 2527 a 2528 a 25	0000440000 000004400000 00000000000000	0000000000 000000000000000000000000000	000000000000000000000000000000000000000	00000000000000000000000000000000000000
BRA	SERVICE	Operat'n Lining Bosh	000084889 000084889 000084889	8458 6488 6488	2202 2346 2446 26446 261	288 288 288 288 288 288 288 288 288 288	20000000000000000000000000000000000000	00000000000000000000000000000000000000	24444888888888888888888888888888888888	2000 000 000 000 000 000 000 000 000 00
		Make Location Type	74 H H H H H H H H H H H H H H H H H H H	Westry Westry Westry	7041H 7041H 7041H 7041H 7041H	1111111 HHHHHHH	**************************************		4444444444 6666666666666	01010101010101010101010101010101010101
FRONT		bns såsM IsboM	Wis F30B Wis F54H Wis F500 Wis F213 Wis F311H Wis F311H	Wis F207 Wis F323 Wis F427	Own LD1 Own IX41 Own IX42 Own IX41 Own IX41 Own IX41	TWH MH81 TWH MH82 TWH MH84 WWH MH84 WH MH84 WH MH86	WH MH89 WH MH90 WH MH90 WH MH91 TWH MH81 TWH MH82 WH MH88 WH MH89 WH MH90 WH MH90	Own JCB Own JD Own B3S Own C3S Own C3D Own FS Own FB Own FD Own GD	Own FN Own FN Own FC	TIME 55.00 TIME 55.00 TIME 55.00 TIME 55.10 TIME 56.10 TIME 56.10
ni.	42ii	Gear Ratio H ni sgnaSi	5 14 5 66 5 14 5 66 6 35-7 35 7 06-8 00 7 14 0 15	6.85-9.41 6.85-9.41 6.02-8.50	44499999 444999999	0000000		4440000000040 440000000000000000000000	45 - 19 - 10 - 10 - 10 - 10 - 10 - 10 - 10	44444
AXLE		Gear and T		HHHH	Eddddd	Feederstand				ELECTE RECEIP
REAR		laboM	53210 54413 5600L 72000L 56205H 1337H 2F 417W 2F		89% 88F 88F 88F 88F 88F 88F	H811 H822 H833 SF H844 H844 H888 2F H866 2F	MH899 2F MH900 2F MH901 2F MH811 3F MH882 3F MH899 2F MH899 2F MH900 2F MH900 2F MH911 2F	140B 140B 140B 140B 140B 140B 140B 140B	PERCECCE SECTION OF SEC	18.10 TR T T T T T T T T T T T T T T T T T T
	8.04	Forward Sp	4 Tim 54 Wis 50 Wis 72 Wis 13 Wis 13	5555	Ford Ford Ford Ford Ford Ford T Ford	STIM M STIM M STIM M SWEM M	5 WE M 5 WE M 5 THE M 5 THE M 5 WE M 6 W M 6 WE M 6 W M 6 W M 6 WE M 6 W M 8 W M 6	55 0 w b J C C C C C C C C C C C C C C C C C C	00000000000000000000000000000000000000	SERVICE SUPPLIES OF THE SERVICE SERVICE SUPPLIES SUPPLINT SUPPLIES SUPPLIES SUPPLIES SUPPLIES SUPPLIES SUPPLIES SUPPLIES
NO.	0,00	Sirve					9999		200	
TRANS- MISSION		Make and Model	BL 2341 BL 2341 BL 3341 BL 5341 BL 5341 BL 5341	Fu 5A62 Fu 5A62 Fu 5A62 Fu 5A62	Ford Ford Ford Ford Ford WG T9	Fu 5A33 Fu 5A33 Fu 5A430 Fu 5A430 Fu 5A62 Fu 5A62	Fu 5A620 BL 7341 BL 7341 Fu 5A33 Fu 5A62 Fu 5A62 Fu 5A62 BL 7341	BE SEE SEE SEE SEE SEE SEE SEE SEE SEE S	OWN FJD OWN FJD OWN FC OWN FA OWN FA OWN FA OWN FA	00000000000000000000000000000000000000
bra	bnat	Governor S	**************************************	よよんえ	ZZZ: ZZZ	XXXXXXX	まえよえええええん	えんえんえんえんえんん	えんえんんんんえんえん	ARREA ARACAC
	Main	Number, Diameter and Length	7-25/3×10 H 7-25/3×10 H 7-3×14 7-3×14 7-3×12 7-3×12/3	7-3x11% 7-3x111% 7-3x111% 7-3x111%	7-22-23 7-22-23 7-22-23 7-22-23 7-23-23-23 7-23-23 7-23-23 7-23-23 7-23-23 7-23-23 7-23-23 7-23-23 7-2	7-22/24/24/24/24/24/24/24/24/24/24/24/24/2	7-38 XXXII 7-38 XXXII 7-38 XXII 7-38	7-25/4 7-25/4 7-25/4 7-35/10 7	7-225x10 7-3x1337 7-3x1337 7-3x1337 7-4x1337 7-4x134 7-4x134 7-4x134 7-4x134 7-4x134 7-4x134 7-4x134	SUCCOCOCOCO COCOCOCOCOCOCOCOCOCOCOCOCOCOC
rs	.w.	Max. Brake H.P. at R.P Given	73-2800 76-2400 94-2200 94-2200 6-2000 76-2000 78-2000 78-2000	108-2400 108-2400 135-2200 135-2200	78888888888888888888888888888888888888	98-2800 95-2800 10-2200 10-2200 10-2200 10-2200	10-22-01 10-22-00 10-22-	86-28000 98-18800 06-28000 00-24000 10-220	800 100 100 100 100 100 100 100	00000000000000000000000000000000000000
DETAILS	.31	Torque Ib. 1	444 74176 72286 72288 7288 768 768 768 768 768 768 768 768 768 7	55522 55522 55522 55522	8222222 8222222	2330011 2330011 2330011 2330011 2330011	2330 2330 2350 2350 2350 2350 2350 2350	25000000000000000000000000000000000000	0.000 0.000	**************************************
	_	Displaceme Comp. Rati	22884442 23888220 23888220 244444	44.00 0.020 0.020 0.000 0.000	2522222 2522222 2522222 2522222 2522222 2522222 2522222 2522222 2522222 252222 252222 252222 25222 25222 25222 25222 25222 25222 25222 25222 25222 25222 25222 25222 25222 25222 25222 252 2522 2522 2522 2522 2522 2522 2522 2522 2522 2522 2522 2522 252 2522 2522 2522 2522 2522 2522 2522 2522 2522 2522 2522 2522 252 2522 2522 2522 2522 2522 2522 2522 2522 2522 2522 2522 2522 252 2522 2522 2522 2522 2522 2522 2522 2522 2522 2522 2522 2522 252 2522 2522 2522 2522 2522 252	10101010444	2501 2501 26035 24474 2601 2601 2601 2601 2601 2601 2601 2601	9388844000000000000000000000000000000000	381 381 511 511 511 511 511 511 511 511 511 5	8.44.024000 8.448600 8.448000 8.448600 8.4480000 8.448600 8.44800000000000000000000000000000000
ENGINE	- Ju	Cylinders, Bore and Stroke	80044440 844848 44848 44848 84848 84848 848440 848440 848440	4400	2222222 2222222	2×24555 × ×××××	555544555 77 7777	**************************************	#99999×********************************	** ** ** ** ** ** ** ** ** ** ** ** **
		Jo. of	<u> </u>	6666	00 00 00 00 00 00 00 00	6363	200000000000	@@@@@@@@@@@@@	NNK SSR SSR SSR SSR SSR SSR SSR SSR SSR SS	
		Make and Model	Her JXC Her JXC Her WXC Her YXC Her YXC Her RXB	Bud	Ford V8		BEEFEE E E E E E E E E E E E E E E E E E		Current Was a Character Ch	00 00 00 00 00 00 00 00 00 00 00 00 00
SIZES	D-dual rear S-single rear	mumixaM szie siiT baneinsu-I	7.50/20 8.25/20 8.25/20 9.75/20 9.75/20 10.50/20	9.75/24 9.75/24 9.75/24 10.50/24	9.00/158 7.50/178 32x6 32x6 32x6 32x6 7.50/20	7.50/20 8.25/20 9.00/20 9.75/20 9.75/20 9.75/20	9.75/22 10.50/22 10.50/22 10.50/24 10.50/20 8.25/20 9.75/22 10.50/22 10.50/22	9.00/20 9.00/20 10.50/20 11.25/20 11.25/20 11.25/20 11.25/20 11.25/20 11.25/20 11.25/20 11.25/20 11.25/20 11.25/20 11.25/20 11.25/20 11.25/20 11.25/20 11.25/20 11.25/20	9.00/20 9.75/20 10.50/24 10.50/24 10.50/24 112.00/24 10.50/24 13.50/24	9.00.20 9.75/20 10.50/20 10.50/20 9.00/20 9.75/20 10.75/2
TIRE	S-sin	Standard Front and Rear	6.50/20D 7.50/20D 7.50/20D 9.00/20D 9.00/20D 9.75/20D 10.50/20D	9.00/20D 9.75/20D 9.75/20D 10.50/20D	7.50/158 7.00/178 7.00/178 6.00/20D 6.00/20D 6.00/20D 6.50/20D	99999999	33330000	7.50/20D 7.50/20D 10.50/20S 10.50/20S 9.75/20D 9.75/20D 10.50/20S 10.50/20D 10.50/20D 13.50/20S	9.75.206 9.00/20D 9.75/20D 9.75/24D 10.50/24D 11.25/24D 11.25/24D 11.25/24D 10.50/24D 13.50/24D	8,000,000,000,000,000,000,000,000,000,0
9		Chassis Wt. (Stripped)	25000 25000 25000 87000 10600 10600	19180 10310 10650 10935	2719 3322 4273 44207 4424 4430	4665 5155 7000 7895 8100 8785	9880 10420 112600 113850 5420 5615 9800 111315 113300	5900 6050 6050 8255 8255 8250 9575 9500 4200 4200	7500 8500 8500 8500 12000 12000 13000	9345 10485 11005 11005 15045 13125 15045 13125 1
Keynote)		Gross Vehic Weight with Max. Tires		24000 27700 27700 35000				43000000000000000000000000000000000000	220000 2280000 2280000 2300000 2300000 2300000 250000	332000 332000 450000 52000 520000 520000 5200000 5200000
(See h	_	Wheelbase Max. W. B. Furnished	0000000	146 146 146	5775533 57755335 577557 577557 577557 577557	1583000 1583000 15830000 15830000	258844835688 20000000000000000	888888888888888888888888888888888888888	6222222500	2008-00-00-00-00-00-00-00-00-00-00-00-00-
GENERAL	9:	Chassis Pric	255555 255555 2555555 2555555 2555555 255555 255555 25555 25555 255 2555 2555 2555 2555 2555 2555 2555 2	6118 13 7251 13 7835 13 8412 13	1445 113 1585 123 1502 135 1855 135 1549 157 2490 143	2820 3250 4550 4550 15 4995 15 6120 15 6500 16	889510 975010 11290010 4409514 442515 1135016 11135115 143519	2885 153 33490 153 5140 146 5590 146 5635 146 6185 146 6200 146 6500 146 6500 146 6500 146	5700 126 7200 126 7500 126 8400 128 8600 138 8600 138 10500 138 10500 128 11000 128	\$5550011 \$5550011 \$5500011 \$55
GEN		Tounage Rating	200 00 00 00 00 00 00 00 00 00 00 00 00		80,000	927			. 02	
	MAKE	MODEL	12X4 14X42 14X42 16X42 18X44 18X44 20X45	Kenworth 539 540 541 541	Marmon-Herr. (c) LD3-1-4 (16) (c) P5-4-1-4 (16) (co.e.) P5-4-1-4 (16) (co.e.) P5-4-1-4 (16) (co.e.) P6-4-1-4 (16) (co.e.) P6-4-1-4 (16) (co.e.) P6-4-1-4	3888440A		108 108 138 138 138 138 138 138 138 138 138 13	Walter FYND 3- FERMD 6- FERMD 6- FERMD 6- FERMD 6- FERMD 6- FERMD 6- FERM 7- F	A Theology (1) A Theology (2) A Theology (3) A Theo
	,14	Line Numbe	-324006	8001	584555			889-384495-89		COMMERCIAL CAR JOURNAL

											57	
H+++++++++==	TTTTTTTTTTTTTT	PC	FFF			HHHHH	00000			FFFFAAAA		
AF THE MANAGEMENT OF THE PARTY	************	-07-07	**	M-1/80	**************************************	24444 24444	XXXXX	KAKKKK	XXXXXXX	**************************************	THE TOTAL	
10x3x	THE RESERVE AND THE RESERVE AN	10x3x 10x3x	00-00-00-00 00-00-00-00 00-00-00-00 00-00-	8 14 x3x 4 8 14 x3x 5 10x3x 6 10x3x 7	******	94x3x3 94x3x3 04x3x3 05x3x3 105x3x3 14x3x3	NAN XX	222222	8 12 X 3 14 X 10 12 X 3 14 X 10 10 10 10 10 10 10 10 10 10 10 10 10	SANANA P	1 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	
6 C C C C C C C C C C C C C C C C C C C	00.00.00.00.00.00.00.00.00.00	22	86266666	0000	ගගගගගත	00222	1-1-1-1-		% & & & & & & & & & & & & & & & & & & &	555555	2011-20-20	
**************************************	***************************************	120		25 25 100 100	77.22222	222222	24822	222223	88 555555	8585222522	8222222	
	99999999999	T6	222222222	5555	XXXXXX	NANA	55555	EEEEKK	XXXXXXX	PDDXX6656	SEXXSESS	
		00	anaaaaaa	0000	000000		-		******	*****		
1193 a 600 a	828 930 930 930 11168 11168 11168 11168 11168 11168 11168 11168 11168 11168 11168	089	5588811111	914 299 517	648 648 7780 7780 855 855	8855 192 192 518 520	193 158 158 158 158 158 158	1192 1192 1192 1093	940 940 940 940 940 940 940 940 940 940	840 840 840 1300 1300 1300 1400 1500 1500 1500 1500 1500 1500 15	6226 6226 6226 6226 6226 6226 6226 622	
2552 2352 2352 2352 2574 5574 1086 1086 1086 1086 1086 1086 1086 1086	65.65.65.65.65.65.65.65.65.65.65.65.65.6	085	6577755	406 576 588 588 1	4445 5557 5590 5990	599 599 505 102 102 102	668 800 782 782 1	88000 8800 8800 8800 8800 8800	619 619 619 1000 1014 1014 114	105601 10561 10561	256 266 266 266 266 266 266 266 266 266	
600000000										L-1-1-1	22000222	
Vella Vella	1.61HV 1.	W6IA W6IA	W61A W61A W61A W61A W61A W61A W61A	LAIHV W841A W841A	B6IHV B6IHV B6IHV B6IHV B6IHV	B61HV B61HV T61A T61A T61A	VS4ri	WS4FIA WS4FIA WS4FIA WS4FIA L6IHV L6IHV	L6IHV 1.61HV 0.61A 0.61A 0.61A 0.61A	100 H	<<==<	
		PP	PP>PP>PP	7722		MALLEL	TEERE	REERSO				
8200074W m 300020H 3100077W 3200077W 3200077W 3200077W 3200077W 3200077W 3200077W 3200077W 3200077W 3200077W 3200077W 3200077W 3200077W	31000H 31000H 31000H 32514H 32514H 32514H 3500TW 35011H 35011H 32515H	1337	1673 1673 1673 1673 1673 1673 1673	F200 210 F310 F310	F301 F301 F400 F500 F500	F500 F700 F700 F800 505	35100 35000 35000 35000 35000	38000 385000 385100 385100 385000 385000	ANXXA 196	MH993 MH993 MH993 MH993 MH995	H965 H965 H97	
2000 2000 2000 2000 2000 2000 2000 200		g g	22222222	8888 8888 8888	OWN F	OWN F	333333	3333333 3333333	0040 0040 0040 0040 0040 0040	EEEEEEEE	MANAMAN	
######################################	\$2000 \$200 \$200 \$200 \$200 \$200 \$200 \$20	56 Ow	88888888888888888888888888888888888888	866 W 111 W W 111			FFFFF	FFFFFF		67 Own 67		
Proposition 000000000000000000000000000000000000	40000404000000	9	22222222	1-0000	900-00-	8.74 -12.7 -9.03 -44.	0-000	92000	8.36 -10.27 -10.27 -10.27	66.67 67.67 8.12.93 8.14.93 8.14.93 8.14.93 8.14.93 8.14.93 8.14.93	11848555	
6400440044401-1- 80004-	8-88-44-84-88-88-88-88-88-88-88-88-88-88	9.68	**************************************	7.333	24.05.00 24.05.00 24.05.00	6.43 7.93 7.93 7.98	0.0000	408488	6.35.39.99	20000	0000-000	
**********	民民民民民民民民民民民民民民	異異				FEEFE	KKKII	REEEEE		KKKKKKKK		
TERROROGOROGOROGOROGOROGOROGOROGOROGOROGO	* FFFFFFFFFFFFF	2FF	888888888	00000 FFFF	00000000	20000000000000000000000000000000000000		WWWW WENTER	00000000000000000000000000000000000000	0.0.0000000000000000000000000000000000	#########	
## T. 1500 TW ## T. 250 TW #	SBT800 SBD900 SBD1000 SBD1000 SBT155 SBT251 SBT251 SBD352 SBD352 SBD352 SBD352 SBT150 SBT1000 SBT160	202	D452 D452 D520 D520 D520	SFD151 SD251H SFD320W SFD420W	RT1200 RT2200 RT-1400 RT2400 RF1401	RT2500 RT1550 RF1610 RF1660 RF1701	888202	2522 2522 2522 2522 2522 2522 2522 252	SBD1000 SBD52 SD252 SD352 BN6 SD452 BN6 SD452	1922 1923 1955 1965	90522 90522 90522 9055 9055 9055	
SED	SBT SBT SBT SBT SBT SBT SBT SBT SBT SBT	SD352 SD520		SPD SPD SFD	RTH	RATINATION NO.	8W252 T18000 8W252 75738	22233	SED	五五五五五	TETTTTT	
STEED STEED STEED STEED		2.9		Wis Wis	0000 0000 0000 0000	00000	EEEEE	EEEEEE	ELECTION OF STREET	THE WAY WAS NOW AS NOW	WWWW WW W W W W W W W W W W W W W W W	
00440000000000 00000	444400000000440	0C 0D	0000044444	****	444400	101010101010	04444	4400000	10101010101010	********	440000044	
5A430 5A430 5A620 5A330 5A430 5A620 5A620 7551 7541 7541 MHU	179 1855 1855 2700 2700 179 1855 2057	7440	8B86 8B86 8A866 7341 7341 7341 7341	5341 5341 7341	H41 H41 W-42 W42 F51	F52 F51 F52 F52 F53 F53	5A620 7341 7341 7341	7341 7341 5A-620 5A-620 5A-30	THEREER COCCERNICATION OF THE PROPERTY OF THE	25 4 3 3 3 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5	7341 5A833 5A620 7341 7341	
FU 55 FU 55 FU 55 FU 55 FU 55 FU 55 FU 55 FU 55 FU 55 FU 55	OOsaaasaaadaa	BL 74	Pu SP Pu SP SP 73 SP 73 SP 73 SP 73 SP 73	BL 53 BL 53 BL 73 BL 73	OWED OWED OWED	00 WHI 00	17773 1733 1733 1733 1733	BL 73 Fu 5A Fu 5A Fu 5A	Fu TE Own D Own C	Ford Ford Ford Ford Fu 5A33 Fu 5A430 Fu 5A620	BL 73 FU 5A FU 5A FU 5A BL 73 BL 73	
ZZZZZZZZZZZZZZZZZ	<u>8800000000800</u>	X B		MAMA KKKK	7.7.7.7.7	まるまままれ		*****				
222 224 27X	000000000000000000000000000000000000000	13%	/m/m/m/m/m/m/m	t-t-		*******	-0000	22	2004444	4444000	22xx30-22	
HANKAKAKAKAKAKAKAKAKAKAKAKAKAKAKAKAKAKAK	KKKKKKKKKKK	3x13	2444444466 20000000000000000000000000000	3x14 3x14 35x17 35x17	XXXXXXX	XXXXXX	KXXXX	4450000 0000000000000000000000000000000	SAN	00000000000 4444 62671 88888888444 6666011144	SECOND SE	
postaletestatelete belefe	44444444444	2-4	Coloredoleron	Print	444444		conce	perter	total-labele		presente.	
50000000000000000000000000000000000000	000000000000000000000000000000000000000	2400	000000000000000000000000000000000000000	2200 2000 2000 2000	8000000 800000000000000000000000000000	00000000000000000000000000000000000000	800000	2500000 2500000000000000000000000000000	00000000	00000000000000000000000000000000000000	00000000000000000000000000000000000000	
1888888999899255 8001	22222222222222222222222222222222222222	126	888000000000000000000000000000000000000	2=44	222222	884456	800000	888888	486005	8888848851	884884455 884884	
0044444000488433 02-1-988444843 02-1-9884444 02-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1	11 200 12	369	86000000000000000000000000000000000000	283 350 455 455	22720 22720	2228888 220888 888882 60	500000		9332222	00000000000000000000000000000000000000	555 178 535 535 530 530 530 530 530 530 530 530	
さいじらいいいいい ちゅうき	ம் வர் வர் வர் வர் வர் வர் வர்	50.00	8014801801-1 6-144141-11 6-18-18-18-18-18-18-18-18-18-18-18-18-18-	4000	9999999	P-1-0101014	F	77.0007	P-480000	\$000000 44 	444444	
23.23.33.33.24.00.00.00.00.00.00.00.00.00.00.00.00.00	7777	6 517	\$0000000000000000000000000000000000000	7628 707 707	222222 2121212121 2224420 2131-1-88	22 22 22 22 22 22 23 24 25 25 25 25 25 25 25 25 25 25 25 25 25	46776	27.75 67.75	2000 004 004 004 004 004 004 004 004 004	226889999 2278 XXXX	25.334 88.22.24 56.02.44 7.00.44 7.00.44 7.00.44	, f
444444444444000 7444C	यं के के के कि क्ये के के के के के	5 34 5 34	244044444 254044444 25504 2504 2504 2504	8x43 8x5 8x5 8	*****	446666	000000	66664	AXXXXXXXXX	0000004444 444433223 8000044488	SSAASSA ,	selffentlen
60000000000000000000000000000000000000	60000000000000000000000000000000000000	6-4% 6-5×5	000000044 040040400	6-4-9 6-5-4-6 6-5-8-6 6-5-8-6	60000000000000000000000000000000000000	86844440 44440		111111	8000000 8004444	00000000000000000000000000000000000000	000000000 000004400 000004000	0
1146.8 11	Te. tv. tv. tv. like like to to to like				22022 298 298 298 298 298	OW FBB298 OW FBB401 OW FBB401 Own FBB401 Own FBB450-A	40000	ස ස ස ස ස ස		~		=
	つつつつつつ元元元元のつつ	SRKI	DESCRIPTION OF THE PROPERTY OF	YXC RXC HXB HXB	FEBB FBB	FBB FBB FBB		ARECEES	ADDOCTO ADDOCTO	VS S S S S S S S S S S S S S S S S S S	HXX DINKE DINKE DHXI DHXI NHXI	change
#### #################################	000000000000000000000000000000000000000	Wau	Wau 6GAL Cum HB6 Wau 6GAK Cum HB6 Wau 6GAL Cum HB6 Cat D8800	Her Her Her	000000	000000	55555	COMMO	000000	Ford V8 Ford V8 Ford V8 Her JND Her JND Her WXLC3 Her RXB	HHHHHHH	-
10.56/22 10.	22222222222222	202	4440000000	8887	8888 8	88888	22222	**************************************	88888444	22222	สลือออลสลี	models
10.50/20 10.50/20 10.50/20 10.50/20 10.50/20 10.50/20 10.50/20 10.50/20 10.50/20 10.50/20 10.50/20 10.50/20 10.50/20 10.50/20	7.50 9.00 9.00 9.00 9.00 9.00 9.00 9.00 9	2.75	275755500 27575755500	7.50 9.75 9.75 9.75	00,25,25,00 00,85,55,00 00,85,55,00	000/000/00/00/00/00/00/00/00/00/00/00/0	757	0.000	75.75	32x6 32x6 32x6 7.20/20 9.00/20 9.00/20	9.75/22 10.50/24 7.00/20 8.25/20 9.00/20 9.75/22 10.50/24	E
		20D 208	844868888	2488 2450 2000 2000								s new
25.000000000000000000000000000000000000	7.00/20D 7.00/20D 7.50/20D 8.25/20D 8.25/20D 9.00/20D 9.00/20D 7.50/20D 7.50/20D 8.25/20D 8.25/20D 8.25/20D	83	40000000000	25/20 75/20 75/20	888888	9000000 9000000	88888	888888	5555555 5555555 5555555 555555 55555 5555	26/20D 26/20D 26/20D 26/20D 26/20D 26/20D 26/20D	75/20D 0.50/20D 50/20D 50/20D 75/20D 75/20D 0.50/20D	enote
90000000000000000000000000000000000000	000000000000000000000000000000000000000	0 13	202000000	P-0000								
10700 5800 5800 10000 110000 114600 15400 12600 12600 12600 12600 15400 15400 15400 15400 15400 15400 15400 15400	6650 7200 7500 8050 8050 8050 10150 111000 6700 8700 8700	17200	20750 21500 25500 16700 18140 20480 21880	0000 15000 16000	6436 6536 7265 10310 9710	9710 9845 12395 11425 14305 20470	10350 12630 13500 12200 12150	13700 14700 112400 10750	7250 8200 10350 13650 14050 13950	5950 58210 58210 7800 10000 11000 11000 11000	1888 1888 1888 1888 1888 1888 1888 188	eost.
28000 332000 40000		40000		::::		::::::	35000 38000 40300 46000	2000 2000 25000 35000 3500				extra
200000000000000000000000000000000000000	88000000000000000000000000000000000000	204 40 228 52	000000000000000000000000000000000000000	8888	191 194 194 215 15	5335555	35 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4	22222222222222222222222222222222222222		22222222	6000000	
	2222222222222	184 20	1889 1755 1755 1866 1866 1866 1866 1866 1866 1866 18	20000	148 178 176 161 2161 2161 2161 2161 2161 2161 2	\$55558 855558	21244	444-44 9999999	88877487 99999999	738998585	985-55-58 885-55-58 985-55-58 985-55-58	*
2800 2800 2800 2800 2800 2800 2800 2800	1850 162 32550 162 32550 162 3250 162 3250 162 3250 162 5590 162 5675 162 5675 162 5675 162 3355 127	13585 2	13000 13375 15266 15266 10275 11300 12275 10500 112865	2000 2000 2000	1475 1590 1760 1945 1945 19850	3060 3015 5900 5000 7500 12500	25.55 25.55	9149 94149 728420 69099 69099 69099		7.195 7.195 7.195 7.195 1.195 1.195 1.195	14000 5270 6070 14350 14350	available
					88	278888	F 20 00 F 20	20,70,00	21.00 € £ 7.00 €			
6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6	44 22000-0000420	10	550005500 884554455	1222			:::::			27.5 5 2 3 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5	27.50	wheelbase
and the cases die de de	SESENSES	3.5	88888888888888888888888888888888888888	8000 840r	FFFFF	777777 777777	AUAUU AFAFF	KKKKKK	ZZZZZZZ	**************************************	99999999	whee
1. 3568 B2 1. 358 B4 1. 358 B4 1. 358 B4 1. 358 B4 1. 358 B4 1. 358 B6 1. 358 B6 548 D6 1. 500 1. 50	2424242204422	MJ6X6 M6x6		9999	718- (5) 201 D186T 2016-T 20216-T 208216-T 20-246-F			845828	SHONKER	0000000000	1145266 (17452666666666666666666666666666666666666	length
25.55 25.55	669	-	ê	16X6 18X6 20X6 22X6	05 05 05 05 05 05 05 05 05 05 05 05 05 0	246 346 346 842 622	99999	66:::69	ECHERA BAN BAN BAN BAN BAN BAN BAN BAN BAN BA	200	E COCCEE	
8	Federal. (0.0.e. (0.0.e.	W. D		Indiana	International tional	D8-246-T DR-246-T D-346-T DR-346-T DR426F AR-626F					330000	
0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0			H				Wo		X	d.		E
COMMERCIAL COLOR	### + ******	106	000 1111111111111111111111111111111111	1118	1222222	322222	387	85-544	2444 2444 2500 200 200 200 200 200 200 200 200 20	2224222	555555555555555555555555555555555555555	**
LABOR MERCEAN C. W.												

Commercial Car Journal June, 1939

,					
FRAME	su	Dimension	22 XX	000000000000000000000000000000000000000	10444 4%%44 4%%44 4%%44 8%&4 8%%44 8%&4 8%%44 8%%44 8%%44 8%%44 8%&4 8%&
	(**	Side Rail	10x3 X x X 10x3 X x X 9x3 X x X 9 X x 3 X x Y	4444 8 8 8 444444444444444444444444444	% % % % % % % % % % % % % % % % % % %
-	noisn	C-A Dime	9031	777778888877786888888	************
	noita	Material Hand Loc	XXXX	88888888888888	XX252X
BRAKES	83	Drum Area mund	1024 B 1024 B 1352 A 1464 B	88888888888888888888888888888888888888	12249 B B B B B B B B B B B B B B B B B B B
BRA	SERVICE	Lining	584 584 792	000000000000000000000000000000000000000	718
	Ø5	Make Location Type Operat'n	LATIHV LATIHV W84FIA W84FIA	С611HV С611HV С611HV С611HV С611HV С611HV F611HV F611HV F611HV F611HV	161HV 161HV 061A 061A 161HV
FRONT		Make and Model	The 35000N Tim 35000N Tim 26450N Tim 27452N	Cheve Frond Cheve Frond Frond Frond Frond Ford Frond F	Own Own Own 9D Own 13D Own 16D
2		Gent Ratio	5.57-7.80 6.20-9.25 7.33-10.3 9.98-13.25	6. 88. 7. 7. 87. 6. 88. 6. 7. 87. 6. 88. 6. 9. 9. 9. 9. 9. 9. 9. 9. 9. 9. 9. 9. 9.	R 5.93-8.30 R 7.0-8.4 R 7.33-9.11 R 8.15-10.2 R 7.00-8.40
AXL		Gear and Drive & To	SF R WF R 2F R CD R	HHHHHHHHHHHHHHHHHHHHHHHHHHHHHHHHHHHHHH	FEFFF
REAR AXLE		Make and	Tim SW251H S Tim SW251H S Tim SD352W 2 Own SR210W C	Eat 1265 Eat 1465 Eat 1465 Chev 1465 Eat 1266 Chev 1266 Eat 1260 Eat 1250 Eat 1250 Eat 1250 Eat 1250 Eat 1250 Eat 1250	Tim SBD 1000 Tim SD 252 Tim SDD353 Tim SDD452 Tim SDD452 Tim SD252
ız	s,pd	Porward S	2044	44 44 44 00 00 00 00 44 44 44 44 00 00 0	\$ 40000000
TRANS-		Make and Model	Own U25 Own UC25 Own UC2 Own UC9	Cobey Cobey Cobey Cobey Cobey Code Cobey Code Code Code Code Code Code Code Code	Own Own Own 36B Own 10B Own 51B
bre	1	Governor 5	* * * * * * * * * * * * * * * * * * *	*X*XXXXXX*	*****
	Main	Number, Diameter and Length	7-2%x12 7-2%x12 7-3x13% 4-3%x11	44444444600000000000000000000000000000	7-2%x10 7-2%x13 7-2%x13 7-2%x13 7-3%x13 7-3%x13 8-10%
rs	·w.	Max. Brake H.P. at R.I. Given	89-2400 89-2400 125-2400 145-2000	78-3200 78-	91-290 110-280 123-240 134-240 136-300 116-300
DETAILS	-	Torque lb.	7 267 7 267 0 328 3 470	00000000000000000000000000000000000000	88.00 88 28.88.20 28.88.20 28.80 28.00 26.00 26.
E D	-	Displaceme Comp. Rat	404 4604 6777 5.5.5.	00000000000000000000000000000000000000	25.000 2000 2000 2000 2000 2000 2000 200
ENGINE		No. of Cylinders, Bore and Stroke	6-4% x 24 24 26 -6 -6 26 26 26 26 26 26 26 26 26 26 26 26 26	######################################	000000 0000000000000000000000000000000
		Make and Model	Wau 6MZ Wau 6MZ Wau 6-125 Wau 6RB	Cobee Cobee	280 7.00/20D 8.25/20 Own 270 280 9.00/20D 9.75/22 Own 460 275 9.75/20D 11.50/22 Own 580 275 9.75/20D 11.50/22 Own 580 550 9.00/20D 19.75/20 Own 580
SIZES	l rear	Maximum Tire Size Furnished	9.75/20 9.75/20 10.50/22 10.50/24	88884788888888888888888888888888888888	8.25/20 9.75/22 10.50/22 11.25/22 0.11.25 24
TIRE	D-dual rear S-single rear	Standard Front and Rear	9.00/20D 9.00/20D 9.75/20D 40x8D	7.00/20x1 7.00/2	7.00/20D 8 9.00/20D 8 9.00/20D 1 5.975/20D 1 10.50/20D 1
0	1	Chassis Wt. (Stripped)	9476 9850 13500 14685	6000 6000 6000 6000 6000 6000 6000 600	
GENERAL (See Keynote)	oj:	Furnished Gross Vehic Weight with Max. Tires	207 32000 207 32000 211 40000 201 55000	216 22000 217 22000 218 24000 217 24000 217 24000 217 25000 218 25000 218 24000 218 24000	3185 160 214 7550 156 235 7550 158 235 9350 158 235 10000 149 245
(See	-	Wheelbase	177 177 181 181 185 20	47555444555559444488 888888888888888888888	9000000 9000000 9000000
ERAL	93	Chassis Pric	4105 4580 11595	18653 18653	3185 160 4995 160 7550 158 9350 158 10900 149 5520 160
OEN		SannoT Zailsa	8-10 8-10 10-12 12-18	(60.00) (60.00	
	MAKE	MODEL	Ster- FBT1522C2F 8- Ing., FWS152 4R 8- (7) FDS180 4R 10 (7) HCS210 4R 11	Truckstell Tru	Valte 904 4R 918 4R 920 4R 922 4R 991 4R
-		Line Numb	10004 801	201200120000000000000000000000000000000	20000000 20000000

NEWSCAST (Continued from page 42)

Factory Notes

Turning now to a few industrial notes of interest we find these items from the truck factories . . . a new \$150,000 truck sales and service building is to be erected at 35th Ave. and 44th St., Long Island City, N. Y., for International Harvester Co. It is to be I.H.C.'s headquarters for all Long Island north of Brooklyn and the old quarters at 44th Road and Vernon Ave. will be abandoned . . . Studebaker scored 10,974 passenger car and truck sales during April, more than the whole second quarter of last year. A new Studebaker branch has been opened in Omaha, Neb., with C. H. Monahan in charge. . . . Nelson-LeMoon Truck Co. of Chicago has purchased the Chicago branch of the Federal Motor Truck Co., and will henceforth be known as the Federal-LeMoon Co. The company has discontinued the manufacture of LeMoon trucks and will devote its time to the sales and service of Federal trucks for which it is franchised as Chicago Distributor. . . . Federal stockholders, by the way, recently extended the Articles of Association for an additional 30-year period. Present directors and officers were all reelected. . . . and when you see how clean the New York World's Fair grounds are kept, think of the 12 new Autocars, recently delivered, and equipped with the latest in sanitation equipment.

Among the suppliers, word has it that Goodrich is erecting a \$1,500,000 mechanical rubber goods factory at Clarksville, Tenn. The company has also taken on for national distribution two new horns, known as "Clearway" and "Multitone" and the Trippe and Supreme auxiliary driving lights. . . . Champion Spark Plug Co. has announced a most important merchandising decision, namely that all of its dealings are henceforth under the provisions of the Fair Trade Acts designed to maintain a fixed price schedule. . . . The addition of three new warehouses by the Sealed Power Corp. located at Jacksonville, Fla.; Richmond, Va.; and Baltimore, Md, raises the total to 21 and makes Sealed Power products all the easier to obtain.

Taking advantage of the greater facilities offered by the Pon Authority Building at 111 Eighth Ave., DeVilbies has moved its New York City sales and service branch to that address. . . . Toledo Steel Products has opened new warehouses in Pittsburgh, Memphis and Jacksonville to further facilitate its distribution those aidriven Sterling sanders will now be manufactured and serviced on the West Coast from a new Sterling Products factory at 8928 Aguinaldo Ave., Los Angeles, where activities of the Detroit factory will be supplemented and as a final sidelight, du Pont tells us that down on the exposure farms where they test all kinds and colors of finishes, no less than 60,000 panels are now exposed to the elements in Delaware, Florida and Texas.

Personal

Getting personal this month takes us on a pretty rapid hop. So let us begin right here at home where we find the new chairman of the Philadelphia section of the Society of Automotive Engineer is none other than Henry Jennings, our own technical editor. The vice-chairman is William Schwarze, Jr., White district service manager. In New York, the Metropolitan section has named T. L. Preble, of Tide Water Oil Co., as chairman and Clayton Farris, president of Trucktor Corp., as vice-chairman.

For the fifth time, Robert F. Black was re-elected president of the White Motor Corp., along with all of the directors. Change within the same corporation include the resignation of L. C. Walson as sales manager of Manhatten, Bronx and Westchester territories. He will operate independently as a White distributor in Westchester. Ray Davis has been named district service manager with headquarters at the company's Long Island City branch. At Buffalo, O. D. Gagnon replaces D. L. Hennigar, resigned, as branch

A Studebaker series of appointments goes like this: Arthur J. Chanter becomes regional manager at Boston replacing George E. Read, who takes the same post in Pittsburgh, where he replaces F. L. Beelby, who has been named wholesale supervisor of the Chicago and St. Louis territories.


Stewart Warner has announced the appointment of Fred R. Cross as sales manager of the Alemite Retail Sales Division. He succeeds C. A. Fine who will be transferred to new duties. . . . M. J. O'Neill,

(TURN TO PAGE 123, PLEASE)

Seven more months of Studebaker satisfaction sees

194 MOLE STUDEBAKER Cab-Forwards

added to this great nation-wide fleet!



The above advertisement appeared in November, 1938. It is reproduced, with latest news, to re-prove that "Studebaker Saves as it Serves."

COMMERCIAL CAR JOURNAL JUNE, 1939

When writing to advertisers please mention Commercial Car Journal

d these les and Long to he yn and idoned. during

A new
C. H.
Igo has
O., and
Impany
devote
h it is
exs, by
a addi-

h it is ers, by a addiall re-Vorld's tly deting a

ting a
Tenn.
o new
see and
sg Co.
amely
of the
Corp.,
Md.,

Port ed its coledo mphis e air-ed on 8925 actory tells

and ed to

So an of neers The man-

nt of nges Watcerrir in ager At

e E.
aces
the

ross eeds eill,

NAL 939

NEW PRODUCTS

(CONTINUED FROM PAGE 36)


head covers the fabric break inside the casing. For a free sample, write The Wedler-Shuford Co., 2222 Olive St., St. Louis, Mo.

Automatic Decelerating Control

An automatic decelerating control is being made by the Marvel Schebler Div. Borg-Warner Corp., for the California Machinery and Supply Co. The device eliminates fumes and backfiring through

the muffler and at the same time shows a substantial reduction in gasoline and oil consumption.

When the carburetor throttle closes the butterfly, valves in the decelerating control are automatically closed by means of a suction controlled piston, entirely eliminating communication between carburetor and engine, therefore no gasoline can enter engine during decelerating period. Closing the valves in the decelerator controls an air passage which is opened by the same piston admitting air to the intake manifold. The amount of air which is drawn through the air cleaner can be regulated. For full details address California Machinery and Supply Co., 2128 Los Angeles



St., Los Angeles, Cal., or 1910 John St., Flint, Mich.

Do-Ray Flush Clearance Lamp

A new clearance lamp, that is only 11/4. in. high and gives maximum light from

11/2 cp. bulb is announced by Do-Ray Lamp Co., 1458 S. Michigan Ave., Chicago. This new number 1182 is compact and strongly built and a rust-proof bezel holds lens securely in place. Lenses are available in red, green, amber, or white.



Simmons Bumper Jack


A new Simmons mechanical bumper jack, introduced by the Simmons Mfg. Co., Ashland, Ohio, is adaptable for use with all cars having knee action and coil springs as well as conventional type suspensions. The jack has but one moving part, a machined steel lift screw 7/8 in. in diameter. The adjustable bumper clamp is a malleable iron casting which fits the bumper brackets on any car. This jack has a lifting range



from 91/2 in. to 301/2 in.

Micro Brake Shoe Gage

Fleetmen who take their brake work seriously should find a real interest in a



(TURN TO PAGE 62, PLEASE)

COMMERCIAL CAR JOURNAL JUNE, 1939





If you want to step up efficiency and mileage . . . and cut down gasoline consumption . . . use Edison Spark Plugs designed for heavy duty service. Edison heavy duty plugs are not just an offshoot from a passenger car line. Each is specifically engineered for its particular heavy duty job, and no other.

Edison Spark Plugs are writing a record of economy across the ledgers of commercial operators from coast to coast. Prove it to yourself by trying just one set in any one of your units, from a lighter job on through to a semidiesel, and add up the savings per mile.

EDISON-SPLITDORF CORP. West Orange, N. J.

Only Edwon Spark Plugs include

HI-VOLTAGE ALBANITE INSULATOR SEALED-IN ELECTRODE CAP **BUILT-IN, LEAK-PROOF GASKET** CONDENSER ACTION FLAT GAP


On_ SPARK PLUGS



ELASTICITY

AS REQUIRED OF STEEL

First to capture the attention of visitors to the 1939 New York World's Fair is certain to be the Trylon.



(C) N.Y.W.F.

11/2

rom:

This slender steel tower, rising 700 feet from a base 63 feet square to a mere 31 inches at the top will awe thousands as it glistens and sways. That it will sway is only characteristic of its structure, and since the smooth solid sides will provide greater surfaces for wind pressure, the beacon-topped head can be expected to nod in an appreciable arc, yet always eventually returning to its original position. Symbol of tomorrow, the Trylon is likewise a splendid example of elasticity in steel.

Parish Heat-Treated Frames, just as rigid as the Trylon when motionless, just as flexible as the tower in a gale, make the finest truck frames. Although overloaded, battered, twisted, Parish Heat-Treated Frames always return to their original shape when stress and strain are removed. Heat-Treatment gives these frames the resiliency they require to meet modern trucking needs.

By insisting upon Parish Heat-Treated Frames for your trucks and trailers, you are demanding frames which insure longer life because they resist greater fatigue. Good frames make vehicles stand up longer for better service. So make certain the rolling stock you buy from now on is assembled with Parish Heat-Treated Frames.



PARISH

PRESSED-STEEL • HEAT-TREATED FRAMES
FOR TRUCKS AND TRAILERS

•



COMMERCIAL CAR JOURNAL JUNE 1939

NEW PRODUCTS

(CONTINUED FROM PAGE 60)

new Micro Brake Shoe Gage just introduced by Shepard-Thomason, Los Angeles, Cal. Purposes of the device is to measure the diameter of the brake shoe arc—with or without lining—to an accuracy of .005 in.

For full details address Shepard-Thomason, 2023 W. Gage Ave., Los Angeles, Cal.

Stainless Steel Electrode

The Lincoln Electric Co., Cleveland, Ohio, announces a new arc welding electrode of the 18-8 type, having 3½ per cent

molybdenum. Designated "Stainweld C," it was developed to meet a demand for an arc welding electrode to weld the considerable number of stainless steels on the market which contain approximately $3\frac{1}{2}$ per cent molybdenum.

Diesel Compression Gage

A direct reading compression gage for diesel engines has been announced by the Bacharach Industrial Instrument Co., 7000 Bennett St., Pittsburgh, Pa. Known as the Premax Indicator, it can be used on running engines. The operation is simple. One injector is replaced by the indicator and the engine started. Index sleeve is



rotated by hand until the flashes of the neon light disappear. It is then possible to read the cylinder pressure directly from the indicator scale. Full details from the manufacturer.

Collision Switch

An entirely new type of collision and tip-over switch has been put on the market by the Elsbert Mfg. Co., Inc., Chicago. Unlike previous switches of this class, the Elsbert switch is entirely mechanical and not only operates in case of overturning but



also in case of collision in front, back, or from either side, even though the vehicle remains upright. Any severe shock displaces a special weight and breaks the circuit. Contacts are silver plated. For full information write to the Elsbert Mfg. Co., Inc., at 353 West Grand Ave., Chicago, Ill.

Spin-A-Bin for Parts

Having all your bolts, nuts, screws, washers, shims, gaskets, fuses, contact

points and other small parts neatly stored in a Spin-A-Bin is a sure time and temper saver. Each compartment may be labeled or a specimen wired to the front. Made by Noggle Products Co., Ann Arbor,




Mich., it is available in a unit containing 24 bins each $3x3x2\frac{1}{2}$ in., or 4x4x3 in.

MORE NEW PRODUCTS ON PAGE 125

COMMERCIAL CAR JOURNAL JUNE, 1939

"55" shows 'em who's boss



The most ornery nuts and bolts on busses, trucks and cars surrender when "55" goes to work on them. Even those hidden, hard-to-get-at "babies" yield easily when you choose one of these twenty-one "Supersockets", Standard and Heavy Duty — all different 12-point openings, 7/16 to 15%" — and a full line of handles, parts and socket wrench combinations to boot. Accessories include Offset, Sliding T and Flex Handles, Speeders, Ratchets, Extensions and Universal Joints. Strong, steel case. This Master Mechanic's Set is a real time- and money-saver. See it at your jobber's — today.

Write for literature of the complete Williams ine including all types of wrenches, pliers, screw drivers, chisels and punches.




"SUPERSOCKETS"

J. H. WILLIAMS & CO.
225 Lafayette St. New York, N. Y.

Western Warehouse and Sales Office: Chicago

Works: Buffalo



HERE'S a Timken 3 for 1 Axle that suits your kind of hauling job to a "T"! Now available on most makes of trucks ... It lets you get exactly the type of final drive in the right gear ratio to give you finest truck performance . . . longest truck life . . . lowest maintenance costs. Tell your dealer you want a Timken 3 for 1 Axle on your next truck!

1 Rear Axle Housing that takes any one of 3 types of Final Drive

- · Bevel Gear
- Double Reduction
- 2-Speed Double Reduction

in a complete range of gear ratios

TIMKENEDAXLES

THE TIMKEN-DETROIT AXLE COMPANY . DETROIT, MICHIGAN WISCONSIN AXLE DIVISION . OSHKOSH, WISCONSIN

COMMERCIAL CAR JOURNAL JUNE 1939

When writing to advertisers please mention Commercial Car Journal

MEN AND METHODS

(CONTINUED FROM PAGE 29)

chargeable accidents for the year ending June 30, 1938, although they covered about the same mileage as in 1935. It might be mentioned, also, that the Boston Store was reported still at the lead at the "half-way point" on January 1, 1939, among all large department stores in the present annual contest of the National Safety Council.

Thus the question is—what new fleet management methods have enabled us to accomplish such a large accident reduction?

As previously stated, the only possible answer must be a rather general review of the reorganization of our delivery department.

Rerouting Deliveries

The first step in this reorganization program was a careful analysis of our Chicago and suburban delivery field. This analysis was made necessary because we found much variation in the daily working hours of our drivers. Some would get in early and others would put in much overtime. This led to dissatisfactions among the drivers, too much overtime expense, and doubtless considerable speedy and hazardous driving both by drivers who wanted to get in still earlier and by those who wished to escape criticism for "too much" overtime. Also, there was considerable extra cost from drivers kept waiting around for special deliveries, most of which we later found could be handled by the regular

It required several months of experimenting, including a study of the time-recording charts on our trucks, to work out new evenly balanced delivery districts, taking into consideration total distances to be covered, and the percentages of paid versus C.O.D. packages. We planned the new districts so they also could be easily and fairly divided for two delivery trucks during Christmas and other special sales periods. As a follow-up comment, we have found that this careful balancing of our districts, and our new daily records of total packages delivered to each district, now have numerous business values. For instance, through a comparative study of package totals, our

main office can measure the localized results from special sales, community circularization of advertising, competing community sales, etc.

One of the immediate results from this reclassification of delivery districts was a considerable reduction in trucks and drivers regularly needed. and also the elimination of much driving overtime. Thus we were able to plan out more standardized working periods for our drivers and more systematic driver training methods; and these new plans and methods naturally included special attention to accident prevention. Toward this end we have worked out the following general supervising principles:

Supervising Principles

1. Expect from all drivers a good honest day's work.

2. Give drivers and helpers as steady employment as possible.

3. Help drivers to eliminate personal worries.

4. Train drivers to avoid traffic arguments.

5. Keep trucks in best possible mechanical condition.

6. Get cooperation of drivers in winning fleet no-accident awards.

Fundamentally, we believe that the human element—the man behind the wheel-is the key to our fleet safety. But this statement needs interpretations. We also must help our drivers to keep in good physical and mental condition for their work; and also provide them with good equipment for their jobs. We now require all drivers to have annual physical examinations; and we do all that we can to provide all of our regular drivers and helpers with steady employment. We do not believe our drivers profit by or want "an easy time." With scheduled full days they are more contented, do better work, and feel more certain of their jobs.

We continue to make careful studies of our package totals for delivery districts, to know how many packages a driver and his helper normally can handle as a day's work. These studies are aided by our time-recording dials. We have about half as many time recorders as trucks and thus shift them about. We do not do this with secret spying intent. Our drivers are kept informed about our "time studies"; and this knowledge undoubtedly is a tonic to more steady work. We often call in a driver for "explanations" when the dial on his

truck, changed every third day, indicates prolonged idle periods.

We keep a driver and his helper assigned mostly to a regular district. He thus comes to know all the accident hazards of his territory—the bad streets, crossings, intersections. He and his helper also become acquainted with all the Store's regular customers; and at rush times when the district must be divided and the helper becomes the driver of the extra truck, he also thoroughly knows the driving hazards and the Store's regular customers.

We expect each driver to do a good steady day's work. But, in the interest of accident-control, we do not have any hard and fast delivery quotas or time schedules which might cause a driver to take extra driving risks. We tell our drivers that we would much rather pay over-time once in a while, rather than to have them take chances on marring their own and our Fleet Safety record.

We help our drivers to earn extra money during the "special store-wide sales" which we conduct two or three times a year. The sale is usually on some single item, such as men's shirts or women's hosiery, sold in large volume at special bargain prices from cellophane-wrapped samples. Various chance and volume prizes are offered, in addition to small sales commissions. Most of our drivers take an active part in the contest which usually continues for a month, and some of them make high sales records. One of them recently was lucky enough to win the grand prize automobile, awarded to the one who had turned in the lucky sales slip drawn from all that were turned in.

Another encouragement to our helpers is the fact that our new drivers are chosen from our trained helpers. All but two or three of our present helpers are trained to the point where they are licensed chauffeurs. Thus they are qualified, during Christmas and other special sales periods, to drive our extra trucks, with extra helpers to assist them. The helper is paid regular driver's wages and he usually has four to six weeks of such work during the year. The best qualified of these helpers thus are in line when we need a new driver; and new regular helpers are likewise chosen from among our extra helpers.

There are a number of ways in (Turn to Page 66, Please)





DO THESE THREE THINGS and You'll Get Complete Satisfaction

- 1 Standardize on the right make.
- 2 Select the right Heat Range.
- 3 Clean and regap all plugs every 3,000-4,000 miles.

Fleet experience, representing millions of miles, shows that best spark plug service is assured this way.

AC's 30 years of experience assure you of satisfactory spark plugs—year in and year out.

When engine conditions are normal, the specified AC type gives uniform satisfaction. When those conditions are not normal, the AC Heat Range (most complete in the industry) provides the satisfactory solution.

When it comes to cleaning and adjusting, the new, improved AC Cleaner gives you faster cleaning with less compound per plug, and the AC round wire gap gauge assures real accuracy in gap setting.

This is "the answer" when it comes to spark plugs. And it means good engine performance...long plug life... freedom from service interruptions.

- for Thirty Years THE QUALITY SPARK PLUG

International Trucks and Tractors, Allis-Chalmers Tractors; Diamond-T, White, GMC, and Chevrolet Trucks; Chevrolet, Pontiac, Packard, Oldsmobile, Nash, Buick, Cadillac and La Salle motor cars—these are some of the well-known tractors, trucks and cars which use AC Quality Spark Plugs as standard equipment. Trust your spark plug requirements to the same brand of spark plugs which the leading, big-volume manufacturers select.

NEW, IMPROVED (Model "C")

AC PLUG CLEANER

Size 12" x 24"...cleans faster, better, and uses less compound...dual valve control, cleans and dusts in one operation...no flying dust...adapters automatically locate plugs for best cleaning results...available with or without stand.

See Your AC Supplier



AC SPARK PLUG DIVISION . General Motors Corporation . FLINT, MICH.

COMMERCIAL CAR JOURNAL JUNE, 1939

When writing to advertisers please mention Commercial Car Journal

which we can help our drivers "to eliminate personal worries." As stated, we require annual physical examinations by our Store physicians, to lessen the health worry. At the beginning of our reorganization program we called a meeting of all drivers, to let them know that I would be at the garage every day, beginning from their starting time in the early morning to their quitting time, and that I would be only too glad to take up with them any personal or

business problems that might confront them. I figured that when a chauffeur or extra driver is thinking about his personal difficulties, he can't be safety minded.

Our chief method of financial aid, when that is needed, is through our Store credit union. Nearly all our drivers and helpers have accounts, built up through authorized weekly pay deductions varying from 25 cents up to several dollars. The maximum credit deposit is \$350. A small interest charge is made on loans, which

may be returned in weekly payments; and there is an interest allowance on surplus deposits. A driver whose credit has been established thus can get a loan quickly, up to several hundred dollars. We feel that this agency has been of great importance, helping drivers to reduce money worries and keeping away from "loan sharks."

Another method of reducing driver worries has been through the instal. lation of small cash-deposit safes in most of our delivery trucks. This change has more than paid for itself. since we formerly were paying out as much as \$170 some months for "money orders," purchased at sub-urban post-offices by drivers who had collected large sums from C.O.D. orders, as a precaution against the frequent holdups of such drivers three years ago. Our drivers perhaps were especially marked by such hold-up men, because from 45 to 70 per cent of their deliveries are C.O.D. orders. Thus, it is not uncommon for a driver to collect \$200 to \$500 in a day. Our reorganization remedy was the installation of small safes, fastened with wide steel straps and large rivets to the foundation beams of the truck. The safe is so constructed that money (or even a pay check about which the driver might become nervous) can be dropped in and then cannot be removed. Since then there has been only one attempted C.O.D. robbery. The wouldbe hijacker was told to read the sign on the safe, stating that the truck driver had no key to the safe; and one kick at the safe convinced him that the safe was too solid for easy removal.

Monthly Safety Meetings

Our drivers are trained in our monthly safety meetings to the effect that they never get anywhere by permitting themselves to get into a traffic argument with anybody—with another driver, a pedestrian, or a policeman. This is a part of our training in "road courtesy." We tell our drivers that if another driver wants to pass in a hurry, let him do it.

"And maybe," I sometimes add, "he will be in the hospital while you're still driving. Nothing is gained," I continue, "by trying to bluff anybody when you find yourself in traffic trouble. Don't bluff, apologize, or explain. Keep calm and courteous. Give them your number

(TURN TO PAGE 68, PLEASE)



COMMERCIAL CAR JOURNAL Trine, 1939



"In all our experience we have never seen anything to equal the service given by this set of **Nitricastiron** Cylinder Sleeves."

(Signed) A. V. SMITH
Shuptrine Construction Co.
McComb, Mississippi

"We installed a set of **Nitricastiron** Sleeves in our Model "L" Allis-Chalmers tractor in March, 1938. This tractor has worked night and day 60% of the time since. So when we tore the motor down this week these sleeves have seen service for an average of a year and a half. We found these conditions:

Piston and Wall Wear . . . practically none Ring good enough to put back in Connecting Rods . took out one shim in each rod Oil Consumption 1 to 2 quarts in 10 hours of hardest use."

C. E. SHUPTRINE says:

We agree with our master mechanic when he said, "These sleeves are an answer to a contractor's prayer!"



These are the Thompson Heavy Duty Parts which convert ordinary engines into super power plants for super service: Nitricastiron Cylinder Sleeves, Aerotype Pistons, Chrome Plated Piston Pins, Aerotype Valves, Duracrome Valve Seats, Graphited Valve Guides, Packless Pumps.

THOMPSON PRODUCTS, INC. · Cleveland · Detroit



Thompson Products

COMMERCIAL CAR JOURNAL JUNE, 1939

When writing to advertisers please mention Commercial Car Journal

(CONTINUED FROM PAGE 66) and name; tell them you're sorry and promise a fair settlement for any damage done . . . Then get back and tell us all about it as soon as possible."

This same training in driver courtesy—not talking too much and keeping calm—has helped us to bring a large reduction in the reports of customers about "driver discourtesy," when there are misunderstandings in the delivery of goods. "The less you say," I tell them, "the better.

If you say nothing—nothing at all—they certainly can't accuse you of discourtesy!"

We try to develop real safety comradeship with our drivers—prove to them that we are really interested in their individual safety records. Each month we post a list which includes a condensed safety record of all our regular drivers, listed in the order of longest no-accident periods. For instance, our last monthly report shows that E. Treacy began as a chauffcur on Nov. 24, 1924; that he has driven for 6 years and one month without an accident, covering 155,307 miles; and that he has No. 1 no-accident rank both in length of time and miles. This list also shows 8 drivers who have driven more than 6 years without an accident; 5 who have driven over 5 years; 5 over 4 years; 12 over 3 years; 9 over 2 years; 10 over 1 year; and 8 with no-accident records of from one to 11 months. It is becoming more and more a matter of pride among our drivers to see their names gradually crawl higher and higher toward the top of this monthly list.

We hold monthly safety meetings, frankly talk over our most recent fleet accidents, and new problems in accident prevention. We use every opportunity to honor the men with the best safety records, in the presentation of annual awards at our annual banquets and at other like special meetings.

It may be interesting at this point to note the nature of the 12 chargeable accidents, listed in the order of their occurrence, which were reported by our drivers during the 12 months of the last annual safety contest:

 Driver backed into a bus which was unobserved by his helper.

2. Driver turned at intersection and was unable to avoid collision with approaching cab.

3. Driver backed from service station into approaching truck, not hearing any warning from his helper.

4. Driver going slowly, looking for house number, was hit by truck backing from a driveway.

5. Driver turning right at intersection, struck fender of a light car attempting to pass.

 Driving through an alley, truck bumped into a car being driven along an intersecting alley.

7. Truck, driving away from a curb, was struck in rear by a car stopping at the curb.

8. Driver, emerging from viaduct, was unable because of icy street to prevent slight collision with another truck which started to cross street directly in front.

9. Driver, thinking another car intended to let him pass at intersection, bumped into it.

10. Driver, observing packages sliding from truck, turned toward curb, but icy street caused sliding into another car.

11. Driver, attempting to park (Turn to Page 70, Please)



Prompt Service through National Distribution

EVERY red dot on this map shows a sales and service organization which, in effect, brings Handy factory service to every truck owner in its compact, surrounding region.

These Handy Distributors are specialists. Most of them have sold and serviced Handy Governors for many years.

Your Handy Distributor will give you expert counsel and prompt experience service. He carries a full stock of all Handy products.

Ask your Handy Distributor about the new Handy Visible Governor, the sensational model you can inspect at a glance for operation and condition. And remember —Handy is the Governor sold AND SERV-ICED IN YOUR TERRITORY.

HANDY GOVERNOR

Division of King-Seeley Corporation

World's Largest Builder of Automotive Governors

GOVERNORS ...





THIS NEW TYPE SPARK PLUG CUTS COSTS FOR BUS OPERATORS

ONE of the surest ways to slash maintenance and operating costs is to switch over to Auto-Lite Spark Plugs. Tests, conducted under actual operating conditions by bus and truck operators, convincingly demonstrate this new kind of spark plug definitely saves them money two important ways.

Auto-Lite Spark Plugs are more durable - last longer in service - and they improve gasoline economy by preventing gasoline waste.

These two qualities are due primarily to the new Ziramic insulator and Konium Electrode—two developments of Auto-Lite research engineers that mean money-inpocket to every one who has to keep transportation rolling at low cost.

The Konium Electrode, together with Auto-Lite "geometric" gap design, makes it possible to produce a more effective, more certain spark with less effort. And Ziramic, the new improved insulator material, resists heat, electrical and mechanical shock as no other insulator ever has.

From Border to Border and Coast to Coast this sensational new Auto-Lite Spark Plug is cutting operating costs for bus and truck fleets. Write to The Electric Auto-Lite Company, Merchandising Division, Toledo, Ohio, for Special Fleet Contract details today!

COMMERCIAL CAR JOURNAL JUNE. 1939

ir

nt

When writing to advertisers please mention Commercial Car Journal

(CONTINUED FROM PAGE 68) ahead of another car, slid on wet pavement and scratched fender of

other car.

12. Driver, unable to stop in time when oil truck stopped in front, damaged his truck.

We have made great effort to aid our drivers by keeping our trucks in good condition for safe driving. As stated, nine-tenths of our trucks are more than ten years old and have two-wheel brakes. We have tried to compensate by training our drivers to more careful driving habits. Another compensation has been extra booster brakes on some of our trucks. All of our brakes of course are tested twice a year when they pass through the compulsory Chicago "safety lane." In addition, we test them once a month with a "decelerometer" which we use either on our garage floor or outside in a suitable place.

We also make a specialty in the care of our tires. We have an individual record card for each tire, and retread some of them 4 or 5 times.

There has been a double reward. First, tire failures on the road are almost unknown to our drivers; and this undoubtedly has great safety importance. Secondly, our 1938 report shows that our tire mileage cost was only two mills per truck mile or fourtenths of a mill per tire mile.

At the beginning of our reorganization program we established a thorough system of garage inspection. We now have four such inspectors and expert mechanics, whom we consider an essential part of our safety program. They are expected to attendall driver safety meetings and their pictures are taken with all group safety pictures of our drivers.


Every night each driver reports any observed mechanical fault in his truck. These reports are followed up each night by our garage mechanics and the minor faults are corrected immediately. In addition, each truck is inspected nightly for tires and for greasing; and every third day each truck receives a more complete inspection. The repairs of each truck and all new material and appliances put on it, are tabulated on a special individual truck form originated by our department. Thus we keep a complete record on each truck, with operation costs classified in detail.

A further fact of importance is that we have in our garage an expert body maker. During recent years he has supervised the making of all our truck bodies. He keeps all truck bodies in repair, and during other times he and his assistant are at work on new bodies. Thus we have been able to build a number of original safety and utility features into these bodies, including conveniences and changes suggested by a certain driver scheduled to use a new body. For instance, a more comfortable seat; and new inside loading helps.

As stated, we consider the "human element" most important in our fleet safety and efficiency program, hence wish to keep in close touch with the desires and needs of our drivers.

Battery Troubles?

How a battery is constructed, how it produces electrical energy, what makes it break down, how to get the most out of all available tests—all this and more is contained in a new book, "An Easy Way to Get at Battery Trouble!" just published by Battery Book, 600 S. Michigan Avenue, Chicago. Cartoons and colored drawings add spice and information. It's yours for two bits. Just address the publisher.




... AND STILL GIVE IT, TOO!

Construction trucks, wallowing in and out of hub-deep mud, soaking their brake blocks with muddy water, stopping fully-loaded on sharply-inclined ramps—these are tests to try the endurance of any brake blocks and Grey-Rock can take it.

But when those same trucks get out on the open highway and roll along with throttles open, Grey-Rock can give, too—give the sure, certain, smooth, balanced stops that safety demands.

Your Grey-Rock jobber backed by factory field engineers can balance the brake action, reduce brake maintenance costs and increase the brake lining life on any fleet operation. These men have at their command the Grey-Rock Balanced materials for light or heavy trucks:



For LIGHT Trucks Grey-Rock has two Blocks—GREY-ROCK BLOCKS, homogeneous, rigid molded with medium friction (orange edges), and HiWaY BloX, hydraulic compressed, rigid woven with higher friction (black edges). When used as directed by Grey-Rock engineers in the Recommendation Guide, they will balance the brakes on any vehicle using RIVET-ON Blocks.

Yes, Grey-Rock can take punishment and give service. Regardless of the make, model, year or operating conditions in your truck fleet every problem can be solved by Grey-Rock's specialized materials.



★ For HEAVY Trucks these 5 Bolt-On Blocks in Factory-Combined Sets

BALANCED TRUCK BLOCKS

of Raybestos-Manhattan, Inc., MANHEIM, PA.

BRAKE LININGS • CLUTCH FACINGS



★★ For LIGHT Trucks these 2 Rivet-On Blocks and the Guide

ard,

im.

was

112.

or.

on.

019

on

ei

up

ice

ed

or ch

k

e

by

ri

ne

H

DYNAMOMETER

(CONTINUED FROM PAGE 35)

proven the economic value of thorough acceptance tests combined with tune-ups of all new equipment. This work is done by the same shop section that handles routine tests of older operating equipment. Standard factory instructions which are required with each piece of equipment are used in determining adjustments.

Complete acceptance tests includ-

ing full load performance will reveal deficiencies that might escape attention in normal operation until months later when unusual maintenance costs are checked back against the vehicle as a matter of routine. It is then rather late to effect any adjustment under a guarantee.

This matter of acceptance tests is important for it not only assures guaranteed performance but has also proved to be of unusual value in determining standards for new car performance which may be used as a goal in later reconditioning or in specifications for other purchases.

The chassis dynamometer is an advanced type of tool in the "tune-up" kit. Those fleets equipped with full power chassis dynamometers report consistent savings through load test performances which quickly prove efficiencies or deficiencies in the equipment under test.

L. L. Beardslee, superintendent of shops and garages for the county of Los Angeles, has formed the following conclusions after extensive use of a chassis dynamometer:

"By the use of the chassis dynamometer we are able to more closely diagnose the ailments of the modern, high-speed, high compression, very often irritable automobile.

"The dynamometer not only duplicates road conditions, but is able to exaggerate them to such an extent that conditions not apparent to the operator of the vehicle will often show up under test.

"For instance, a fuel pump that will not furnish sufficient gas to operate at 60 m.p.h wide open throttle, would tend to vapor-lock under operating conditions. Likewise an ignition system that is not functioning properly will show up under the same test.

"Spark plugs that are cracked or worn, or not of the proper heat range, will show their condition more readily on the dynamometer than on the road because we can maintain any throttle or load condition indefinitely.

"Carburetor adjustments under various speeds and loads are easily made with the additional use of the Exhaust-Gas Analyzer and Vacuum Gauge. Cruising mixtures can be set for each individual car, depending on where and how it is operated. No two engines of the same make and model will operate to their best ability on the same carburetor or ignition adjustments. This condition is very apparent by the use of the chassis dynamometer.

"Using the dynamometer we are able to regulate the size and the 'coming-in' time of the step-up or power jet. This is a very important item as so much depends on the power jet. It has been found that by enlarging or reducing the size of this jet we have been able to increase the horsepower output of the engine as much as ten per cent.

(TURN TO PAGE 78, PLEASE)



At last—a time-proved, automatic vacuum-controlled device which shuts off the fuel at the idling jet—every time the motor is decelerated! Actuated by the excessive vacuum which ordinarily sucks a heavy charge of fuel into the manifold at every decelerating operation, the LEIBING DEGASSER positively eliminates poisonous monoxide gases and exhaust fumes—right at the source. It cuts fuel costs . . reduces crankcase dilution . . . prevents manifold loading . . . aids accelerating action. Repeated tests show fuel savings ranging from 12% to 27%—zero readings on carbon monoxide gas—drastic reduction of nauseous aldehydes.

Several hundred bus and truck fleets are now using the DEGASSER—a real boon to passenger operation—a thrifty aid to lower ton mile costs. Illustrated descriptive folder will be sent on request.

NOTEWORTHY FEATURES .

1. Vacuum action automatically operates diaphragm. 2. Idle jet fuel flow instantly shuts off whenever motor is decelerated. 3. Perfect idling condition instantly restored when deceleration is ended. 4. Is tamper and feelproof and built into carburetor for matched performance.

LEIBING AUTOMOTIVE DEVICES INC.

Manufacturers of Governors and Degassers
Detroit, Michigan

ELIMINATES All EXHAUST GAS FUMES



We are not able to determine the exact strings in weight of this tank over the tank it replaced. We can say this: Our first semi-trailer had a 280. gallon tank and this was the maximum we could haul and stay within the 40,000 lb. limit. Our new job is fabricated with Republic Double Strength Steel and has a

1 e,

i

ıg

10 e, d. he

ly. er ily

ım set ng

il-011 ry

are the

the

his


the

of 38.0 gallons. This unit, too, is within the 40,000 of John gallons. This unit, too, is within the 40,000 lb. gross eight limit. We must amplify the statement by saving the new job does have a lighter semi-trailer chass s and this accounts for part of the increased tank capacity. However, it would hardly be possible to ighter chassis if we had used the regular steel tank."

This Could Have Been 1300 Pounds Lighter —

The Tank itself was built of Republic Double Strength Steel, but not the side-carried boxes, and is 80 lbs. lighter than a duplicate in mild steel whil carrying the same number of gallons. It me carrier boxes had been built of Republic Double Strength Steel, an additional saving in we the of The total weight of the steel tank is 6,570 lbs. while the Republic Double Strength Steel tank weigns to lbs. Both carry 2400 gallons of gas.

13 g ge shell sheets and 12 gauge head sheets
of P public Double Strength Steel were used.



Other REPUBLIC STEEL Products used by the Automotive Industry

Moy Steels - ENDURO* Stainless and Heatlesisting Steels - Carbon Steels - Copper-Bearing iteel - Toncan* Iron - Silicon Stools - Pig Iron

Shoots - Strip - Plates - Hot Rolled and Cold Drawn Bars - Pipe - Tubing - Bolts - Nuts -Rivers - Wire - Welding Rod - Boiler Tubes

COMMERCIAL CAR JOURNAL JUNE, 1939

When writing to advertisers please mention Commercial Car Journal

(CONTINUED FROM PAGE 74)

"Irregularities in the ignition system, especially in governor and vacuum advance characteristics, are easily found and remedied. The cut-back of the vacuum spark control and the coming-in time of the carburetor power system can be balanced to eliminate any roughness or flat spots at this very critical point.

"By varying the load and throttle opening we are able to show up carbon deposits so plainly that in some cases the engine will operate just as well with the ignition switch off. This can be done very quickly because we are able to feel out the spot where the engine tends to 'ping' most.

"Any unusual vibration such as worn universal joints or crooked drive shafts are easily discernible.

"Noises emanating from the rear of the car are easily classified. A tire hum or rumble takes on an unmistakable sound on the rolls of a dynamometer. A sound that is actually in the rear axle housing cannot be mistaken. "Eccentric wheel or tire conditions will make themselves known without any effort on the part of the operator.

"Our method of procedure is designed to find and classify troubles quickly. As yet we have attempted no extensive or involved engineering. We cannot tie up our equipment too long, so we must locate and remedy the troubles quickly. In this type of equipment dependability is most desired.

"We have quite a number of 1937 cars with over 100,000 miles. Many of our 1938 cars have been driven from 60,000 to 70,000 miles. Most of these cars are in 24-hour service, some having as many as six different drivers in 24 hours.

"When the car is placed on the dynamometer, a vacuum-gauge and exhaust-analyzer are connected. The car is then tested under part load at 20, 40, and 60 m.p.h. When the 60 m.p.h. test is completed, the load is increased until the throttle is wide open at 60 m.p.h. Horsepower and carburetor readings are taken at this point. The test is duplicated, and readings taken at 40 and 20 m.p.h.

"The part load test shows cruising mixtures.

"The full load test shows power mixtures and horsepower readings, as well as any irregularities, such as sticky valves and faulty ignition.

"If carbon deposits are present, the engine will have a persistent 'ping' at 20 m.p.h. under this test. A further test to verify this symptom is to turn off the ignition switch momentarily during the most severe 'ping.' If the engine continues to run with switch off, it indicates that incandescent carbon or cracked spark plug is furnishing 'self-ignition.'

"At the completion of these tests, the engine is shut down and necessary adjustments are made. At the same time compression, starter, cooling system, and accessories are inspected.

"After necessary repairs have been made, it is advisable to retest in the above procedure."

C. B. Lindsey, Superintendent of Automotive Equipment, Los Angeles Railway Company, has illustrated the use of the chassis dynamometer with a set of power curves Nos. 1 to 6 inclusive. He states:

"I am going to attempt to show by graphs some of the conditions which affect the horsepower and fuel con-

(TURN TO PAGE 82, PLEASE)

NOW YOU CAN CUT FUEL, OIL, REPAIR EXPENSE

AS MUCH AS 25%

BY OPERATING TRUCKS IN THE ECONOMY RANGE

of these components of the comp

with the new

STEWART-WARNER MOTOR MILE TACHOMETER

EVERY truck has an ECON-OMY RANGE—a certain range of r.p.m. within which it operates at maximum torque, horsepower, and road-speed efficiency consistent with fuel economy. Above that range, overspeeding occurs—a short cut to early motor death. All truck manufacturers warn against overspeeding. Below that range, "lugging" results.

NOW, with the amazing new Stewart-Warner Motor Mile Tachometer, it is possible for the driver to know the ECONOMY RANGE of bis truck—and to keep his engine speed always within that range! Two red pointers are permanently set at the upper and lower limits of this range. The driver merely needs to keep his tachometer pointer between those two red pointers—and you save up to 25% on your fuel and oil expense!

Records Motor Miles for Accurate Servicing

More than that, this utterly new kind of tachometer not only shows engine r.p.m., but records them in terms of "motor miles"—the only safe basis for engine service. Thus the added "motor miles" which your motors pile up traveling in low gear—or while your engines idle during a long stop—are truly recorded. Servicing your trucks on this basis can save as much as 25% of your repair bills! Mail the coupon for complete details.

POWER CURVE CHART 130 120 110 100 90 80 70 300 5 60 50 40 200 = 150 M 30 20 10 1500 R. P. M.

Graph Shows Economy Range

In determining the economy range of a truck, brake horsepower is recorded at all operating speeds. So also is the torque. Fuel consumption is likewise carefully computed. In this particular case, the range of engine speed between 1200 and 2300 r.p.m. proves to develop the most power with the lowest fuel consumption, and is, therefore, the ECONOMY RANGE.

STEWART WARNER MOTOR MILE TACHOMETER

STEWART-WARNER CORPORATION
1876 Diversey Parkway . Chicago, III.

STEWA 1876 D Pleas operati	live e gi	V	e;	n	P	a	r a	k'	3	a	y. e	f	C	h	i	Ci	ı	go	0,	1	11	li	at	IE:	i	3	R.		rı	00	cl
Motor :	Mile	e '	T	a	cl	h	Di	m	e	te	er		I	•	þ	24	es	ra	81	e						ŧı	ru	10	k	S	
Name						•			*						•																
Addres	s															*															
City						*					×					*	*			Si	a	te									
Firm N	ame																														



WHERE ELSE COULD YOU FIND SO MUCH TAPERED ROLLER BEARING KNOWLEDGE AND EXPERIENCE?

The Timken Roller Bearing Company pioneered the tapered roller bearing. We have been manufacturing and applying these bearings for more than 40 years. During this time upwards of 450,000,000 TIMKEN Bearings have been applied to automobiles, motor trucks, tractors, trailers and all kinds of industrial machinery. Our service connections have available bearings of all sizes to fit these many types of equipment even though some of them may be obsolete.

TIMKEN Bearings are dominant on (a) steel mill roll necks where bearings are required to support loads running into millions of pounds; (b) machine tool spindles where extreme precision is required; (c) American railroads where an overwhelming majority of new locomotives, passenger cars and streamlined trains are equipped with these bearings.

99% of all makes of automobiles, trucks and buses use TIMKEN Bearings at one or more points.



THE TIMKEN ROLLER BEARING COMPANY, CANTON, OHIO Service-sales Division

e

oo ly of

37

ny en es

e, nt

nd he

50

er

n

16

(CONTINUED FROM PAGE 80) sumption of our engines in service. All of these curves were made from one of our engines, the various units being purposely thrown out of adjustment to duplicate the condition usually found on engines reported for low power or excessive fuel consumption.

"Curve No. 1 shows the effect of a partly closed choke. The top curve in each chart shows the maximum horsepower at the rear wheels of the vehicle in normal condition. As shown by the lower curve, there is a loss of 6 per cent in maximum horsepower caused by the over-rich mixture. This condition also caused an 11 per cent rise in fuel consumption.

"In curve No. 2 we have the effect of a retarded spark. Although it is probable that this condition would not be detected under ordinary operating conditions, we find a loss of 8 per cent in power and 15 per cent increase in fuel consumption.


"Curve No. 3 shows the effect of a broken spark plug wire: 19 per cent power loss and 28 per cent increase in fuel consumption.

"Curve No. 4 shows a slight leak in the intake manifold; 8.5 per cent power loss and 5 per cent increase in fuel consumption.

"Curve No. 5 shows the effect of late valve timing; power loss 7 per cent and fuel consumption increased 4 per cent.

"Curve No. 6 shows that governor incorrectly adjusted can easily cause this 34 per cent power loss and 25 per cent increased fuel consumption."

JOYCE BUS and TRUCK LIFTS



YOU THE WHOLE PICTURE

... at a glance ... of the service parts of your fleet. And with every vital spot in the clear ... with lots of head room and arm room ... it's no wonder your mechanics do better work, more thoroughly and safely and at much less cost.

It's a simple matter to drop drive shafts, transmissions or pancake engines . . . to check springs, steering gear or wheels . . . if you have a JOYCE Two-Post Lift with divided superstructure.

And only in JOYCE Lifts can you find that combination of an extra-long genuine bronze guide-bearing, seven layers of Chevron packing, and a water-tight wiper ring to take the wear and strain of off-center loads without binding or leaking.

Joyce makes the world's largest line of Bus and Truck Lifts. To get the most practical and economical installation for your fleet consult our experienced engineers.

THE JOYCE-CRIDLAND CO.
Onyton Ohio

JOYCE

The Joyce-Cridland Co. Dayton, Ohio Send me your new Bus and Truck Lift Bulletin:

TOLL ROADS

(CONTINUED FROM PAGE-31)

needs of growing peace-time traffic.

2. The modernization of the Federal-aid highway system with the Federal Government paying a greater share of the cost.

3. The elimination of hazards at railroad grade crossings.

4. An improvement of secondary and feeder roads, properly integrated with land-use programs.

5. The creation of a Federal Land Authority empowered to acquire, hold, sell, and lease lands needed for public purposes and to acquire and sell excess lands for the purpose of recoupment.

White House interest in the recommendations immediately prompted reports that the New Deal is preparing to adopt the Bureau's plan as an Administration measure. Such strategy dovetails with President Roosevelt's proposal to reorganize Federal administrative machinery, under which the Bureau of Public Roads would be removed from the Agriculture Department's jurisdiction and its functions, including the allocation of funds to the states under the Federal Aid Highway Act, transferred to a new Federal Works Agency together with PWA, WPA, and other agencies whose principal jobs involve construction.

Mr. Roosevelt has referred at least once to the possibility of putting WPA labor at work building superhighways and he has also touched briefly on the national defense angle. In his message to Congress accompanying the report, he referred specifically to the question of taking ex-

(TURN TO PAGE 84, PLEASE)

LORS OF THE MONTH FOR THE BODY OF-THE-MONTH*

eak ent in

of

ed

OI ISE

he he

ry.

e. or

d r-

nt-els-dne

e

e d







MAT'S color to the fleet operator? Dollars and cents! There's a best color combination for advertisement. The correct use of colors can also tation Color Service your source of authority. It's give added appeal to your products, make your lars by making each unit an effective traveling free!-part of the "plus" value in the No. 1 Finish your fleet. One that will identify your company, fleet sell as well as deliver, win favorable attention, convert your painting dollars into profit dolincrease visibility and safety—cut operating costs. in Transportation-Kem Transport Enamel. Write What colors and where? Make The S-W Transpor-The Sherwin-Williams Company, Cleveland, Ohio, and principal cities. No obligation.

*COLORS-OF-THE-MONTH

feature. Recommended colors for the Laundry fleet are: Kem Again the S-W Transportation Color Service cooperates on Commercial Car Journal's outstanding "Body-of-the-Month" Transport Enamel Export Blue No. 43215. Export Blue tinted with white. Kem Transport Blue-white No. 43050.



KEM TRANSPORT ENAMEL SHERWIN-WILLIAMS

COMMERCIAL JUNE, 1939 CAR JOURNAL (CONTINUED FROM PAGE 82) cess lands for road development and re-selling at a profit—a subject he has mentioned before when discussing the highway issue. He talked more at length on this phase of the problem than any other in his highway message.

Aftermath to the report on Capitol Hill indicated that committees in both Houses were laying plans to carry the program into action.

"It's too big a problem for the individual states to handle," said Representative Cartwright, ranking member of the House Roads Committee and author of several highway bills introduced in former years. "My bill would provide for an Authority which would have the same power of operation as the TVA (Tennessee Valley Authority) to proceed under the right of eminent domain, with a national program."

Said Representative Snyder, Democrat of Pennsylvania, who has introduced three super-highway bills in as many sessions: "The Bureau proposes to construct inter-regional highways. I speak of them in my bill as transcontinental highways. The general principles in volved in both plans are the same; except I would have the roads constructed in straight lines to avoid cities wherever possible."

Other super-highway advocates in Congress declined comment, insisting that time had not permitted them to read the comprehensive report. None would concede that pending super-highway measures have been relegated further to the background as a result of the Bureau's painstaking

analysis.

Before turning thumbs down on the toll-road idea, the Bureau of Public Roads studied all angles of the problem, submitted tentative locations for three north-south and three eastwest highways to highway departments in 48 states, checked traffic flow at representative points, estimated the anticipated toll collections and compiled data on all items of cost, including right-of-way acquisition, construction, operation, and finance charges.

Weighing all factors and without cutting corners in any particular, it was estimated the total construction cost of the 14,336 mile toll-road system would be \$2,899,440,000; or \$184,050,000 annually for the period 1945-1960; while the maximum amount of traffic which reasonably could be expected to patronize the highways would yield only \$72,140,000 per year, assuming an average rate of toll at 1.5 cents per vehicle mile for all vehicles.

It was found that there is no fully transcontinental travel, nor any of semi-continental range which can be accumulated in sufficient volume on any one of several highways skirting across the country either to justify the construction or to estimate the character or location of such roads. By actual count, there are only 300 cars starting daily on transcontinental trips between the Atlantic and the Pacific coasts and few of these, the Bureau said, could be attracted under any circumstances to a single eastwest route. Motor truck and bus movements were checked in three farwestern states and showed their range of travel to be much shorter than the range of passenger cars.

Long trips were found to be a small percentage of all trips, and as (TURN TO PAGE 86, PLEASE)



For every requirement of Truck, Tractor,
Trailer and Passenger
Car fleets, GATKE
Brake Liners and
Blocks are available in
CUSTOM-BILT Sets,
service proved for the particular unit and condition.



When fleet operators say GATKE Brake Blocks and Liners reduce maintenance costs, that's only half the story.

Safety made possible by GATKE Dependable Performance comes first in real economy.

Fewer brake adjustments keep equipment rolling, instead of in the shop.

Dependable brake action helps maintain tough schedules with safety.

Why penalize your operation with needless cost and avoidable risk. Install GATKE CUSTOM-BILT Sets on your next five relines. We are confident you'll never be satisfied with ordinary brake liners again.

Your GATKE Jobber will gladly recommend Sets CUSTOM-BILT for each unit you operate.



BRAKE LINERS & BLOCKS

GATHE CORPORATION 228 N. La Salle St., CHICAGO, ILL.

swer to higher fuel costs


To the fleet operator or truck owner, Cummins Dependable Diesels offer these advantages:

- A seven-year record for dependability—a record accumulated by operators of every size and type—every load, traffic, and road condition from coast to coast.
- 2. An investment whose proved earnings continue to pile up after a second and third 200,000 miles of service.
- 3. A demonstrated way to substantially reduce the cost of every ton mile.

To you, the "job-test evidence" back of the Cummins Diesel is important because it substitutes certainty for hope . . . proof for expectancy. Why experiment? Cummins Engine Co., 1016 Wilson Street, Columbus, Indiana.

One of five Cummins Diesel-powered Internationals Model DRD-70, owned by Willett, Chicago. This unit hauls 6685 gallons of gasoline and operates two shifts a day. The other four operate out of Springfield, Ohio.

CUMMINS
Dependable
DIESEL
PIONEER IN MODERN DIESEL DEVELOPMENT



the

one

fic

stions

of

it

on ad

od

bly

0,

if

the the der

ar-

1

(CONTINUED FROM PAGE 84) only a long-distance traveler would accept or tolerate any diversion from his direct course to enjoy superior highways, it was concluded that the traffic volume which could be listed as transferable to a limited-access road from a generally parallel normal highway at a considerable distance must be very small, probably less than one-third of all cars on the road

If Congressional devotees of the toll-road nostrum persist, however.

the Bureau will have no objection to Congress putting the findings to the acid test by building a super-road between Boston and Washington where there is "a reasonable prospect of the recovery of the costs through tolls."

The recommendations outlined two specific plans of action for Congressional consideration in the interest of providing improved road facilities wherever the needs are sufficient to justify the improvements. The first plan, depending exclusively upon

local action, included the repair and improvement of existing roads by reducing excessive curvatures, flatten ing heavy grades, widening pave ments, constructing additional lanes. and separating highway and railroad crossings. The second plan, require ing Congressional action, would aim at the construction of long distance. inter-regional highways to supple ment present indirect roads.

The national highway system out lined, consisting of 26,700 miles of roads designed to meet peace-time and national defense requirements. was represented as including even line of inter-regional travel in the country to which would be attracted new activity in "contradistinction to the traffic repelling tendency of the proposed toll-road system."

The suggested routes would follow the alinement of existing highways. Pavements more than two lanes wide would be provided where traffic exceeds 2000 vehicles per average day: the right to limit access would be invoked wherever entering vehicles interfere with the freedom of move ment of the main traffic stream Right-of-way widths in rural areas would not be less than 300 ft. and in urban areas not less than 160 ft. By providing ample capacity and every safety device known to modern high way engineering, the roads could be expected to effect a greater reduction in highway accidents than could be made by an equivalent sum spent for highways in any other way.

The Bureau found that problems involving large volumes of traffic are found almost exclusively on the Federal-aid and state highway systems and on city streets and suggested that any program designed to improve other highway systems should be weighed carefully since the roads in the latter category constitute about 2,650,000 miles of road but serve only 10 per cent of the total traffic.

Main highways, comprising the Federal-aid and state highway systems and their trans-city connections, serve approximately 60 per cent of the total vehicle-milage on all roads and streets although these systems constitute only 16 per cent of the total mileage. Local city streets, constituting only 6 per cent of the total road and street mileage, serve ap proximately 30 per cent of the total traffic; other country and rural roads.

(TURN TO PAGE 88, PLEASE)



Cantilever

HOOF PRODUCTS CO., Dept. BEC. 6543 S. Laramie Ave., CHICAGO, ILL. Makers of the FAMOUS HOOF CANTILEVER GOVERNORS.

part in creating a record breaking demand for

Hoof Cantilever Governors.

nomy from any governor and

carburetor combination. It's



MUCH LARGER TRUCKS THROUGH .When the going is Bad"

HERE'S no secret, nothing mysterious about the amazing pulling power of Marmon-Herrington All-Wheel-Drive Fords. With power and traction on the front wheels, as well as on the rear wheels, bad roads become easier to travel, loads become easier to haul, hills become easier to climb.

And when the going becomes simply "impossible" for conventional drive vehicles, because of mud or sand or snow, these All-Wheel-Drive Fords walk right through—taking materials, men and equipment wherever you want them to go.

Rapidly Increasing In Favor

For many years Marmon-Herrington All-Wheel-Drive vehicles have been doing miraculous things in the world's toughest jobs of transportation-over the world's worst roads, or where there were no roads at all-in the oil fields, in

logging, mining, etc. But now that Marmon-Herrington is converting all standard Fords to All-Wheel-Drive, literally scores of new opportunities to make and save money with these vehicles are arising daily.

Contractors on construction projects, road builders, town, township, county, state and Federal highway maintenance officials, public utility men, owners of large scale agricultural projects, operators of overland hauling systems-all these, and scores more, are now finding Marmon-Herrington All-Wheel-Drive Fords the most profitable investments they ever made in automotive equipment.

Unsurpassed for Road Building and Maintenance

"Did more than we thought possible," "gave us a smoother road surface faster than any equipment we ever had-used to pull heavier trucks through tough going," "Still amazed at its performance. It sure has made a believer out of me," "Keeps our roads clear of snow at one third the cost." These are but a few of the scores of similar expressions about Marmon-Herrington

All-Wheel-Drive Fords from municipal, township, county and state highway officials, in

our files.

Why not get all the facts about these amazingly profitable vehicles now? Write for literature, and name of nearest dealer.



MARMON-HERRINGTON CO., Inc., Indianapolis, Indiana, U. S. A.

Cable Address: MARTON, Indianapolis, U.S.A.

tten ave

'oad uir ain nce ple

OU 0 im nts en the ted to the

ide

ex

in

le

a

r

th

on

(CONTINUED FROM PAGE 86)

78 per cent and serve only about 10 per cent of the total traffic.

Taking cognizance of clamor from some sources for putting WPA labor to work building super-highways, the Bureau suggested that "possibly no other work . . . would so profitably provide employment coincident with the centers of present unemployment" as the construction of trans-city connections. Because the greater part of locally generated in-and-out traffic in large cities cannot be drained off

through by-pass roads, the report urged the construction of depressed or elevated arteries to carry the traffic into and through the heart of cities. It put these projects at the head of the list for prompt consideration.

Next on the Bureau's "must" list was the construction of belt-line distribution roads which, while bypassing a city and permitting more direct entrance to off-center parts. would form a circumferential or beltline route around a city's outer fringe. Because right-of-way difficulties have persistently stood in the way of laying out new routes, it was suggested that Congress take steps to dovetail the slum-clearance program with the roads building program on the theory that old, decadent areas in many cities are being purchased, new buildings are going up, and transcity routes should be laid out without delay so that their eventual courses may not be blocked by the mush-rooming of other projects.

The crux of the whole long-range program, the Bureau conceded, is the right-of-way problem, primarily because the laws have not kept pace with the phenomenal growth of highway traffic. A few state legislatures have liberalized the laws, and the courts, generally more responsive to traffic growth than heretofore, are slowly taking a more liberal attitude toward the taking of lands for "public use."

As the most effective weapon for attacking the right-of-way problem, the Bureau proposed the creation of a Federal Land Authority, whose jurisdiction would be general throughout the states. It would be given sufficient funds and authority to acquire land needed for road improvements substantially in advance of the scheduled road construction date and would be empowered to begin construction before the question of compensation or damages had been determined by the courts. Of course, legislative changes-a slow tedious process at best-would be necessary in most of

To be vested with discretionary power to determine right of way widths and whether excess taking is necessary for future needs, the Authority would, at the request of state highway departments, purchase the land and hold, sell, or lease to the state over a period of 50 years on terms designed to amortize the initial cost. The Authority's jurisdiction would not be limited to the purchase of land for highway use but would extend to other purchases where the Federal Government had an interest in buying the land.

Turning back to the adverse report on toll-road highways, another factor weighed by the Bureau was the reaction of the average motorist to toll charges. When John Smith, the average car owner earning \$1,500 a year or less, takes to the open road he thinks only in terms of immediate

(TURN TO PAGE 90, PLEASE)

DIRT...



STEALS
UP TO 400
LBS. OF YOUR
PAY LOAD!

HYPRESSURE JENNY STEAM CLEANING RE-MOVES DIRT QUICKLY, EASILY, ECONOMICALLY



There's plenty of evidence to prove that DIRT may add 50 to 400 pounds of dead weight to every load you carry . . . if allowed to accumulate on bodies, fenders and chassis of trucks or trailers. Hypressure Jenny Steam Cleaning will quickly rid you of this costly "free passenger." It will "up" your PAYLOAD and reduce your fleet maintenance costs 25 to 40%. With HYPRESSURE JENNY on the job, cleaning work that formerly took hours may be completed in minutes-inspection and repair work is speeded and JENNY keeps 'em rolling at lower costs. Ask us to prove it. Return the coupon today for a survey of possible savings to you. No obligation.

HOMESTEAD VALVE MFG. COMPANY
P. O. Box 90 Coraopolis, Pa.

Go	ah	ead	-	-te	ell	1	13	1	he	W	1	8.2	10	1	h	07	F	11	nu	c	h	J	E	N	N	Y	-	ca	n	9	12	V	9	u	Š,
We	hs	ve.				e.		n	10	n		en	nj	pl	03	rei	d	1	n	E	ni	ıíı	ni	el	na	n	ce								
We	re	pai	r.						t	rı	ıc	k		m	10	mt	h	13																	
We	re	pai	nt				. ,			ŧı	·u	cl	kı	1 1	m	or	it	hl	y.																
We	el	ean		. e				. 1	g		ť	t.		gi	RF	aş	26	1	flo	00	r	n	10	n	th	ly									
We	W	ant	t	ō	cl	es	n																			•				ú	×				
Nan	ne																						ĸ												
Add	res	R																																	

• Reduce Clutch Wear and Trouble—

• Get MORE Clutch Engagements—

DESIGNED especially for heavy-duty service by the world's leading maker of heavy-duty clutches, Lipe Clutches are installed as standard equipment by 85% of the heavy-duty motor-truck manufacturers of America. That record alone proves the claim that Lipe construction and design reduces clutch burning and trouble and insures more clutch engagements before the clutch need be adjusted or relined.


Twenty ball-hinged levers multiply the spring pressure on the pressure plate and positively engage the friction disc. The spring pressure is evenly distributed all around the pressure plate—there is no grab or shock. The thick pressure plate makes contact in an absolutely parallel plane. Therefore, no cocking of the plate, no small area of high speed slippage where localized burning might occur. Every square inch of surface is uniformly contacted. Full engagement is rapid, smooth, non-shock and nonslip. The heat of friction is dissipated in two ways: 1-by the thick mass of the pressure plate; 2-by forced air cooling between the driven and driving members that wipes away surface heat.

Wear and tear on the clutch, transmission, drive line, differential and rear axles are all held to a minimum. Clutch life is increased. Clutch service is reduced. You save time, trouble and upkeep expense.

The new Lipe Clutch Service Manual has just been issued. It shows how simply Lipe clutches can be serviced — and without special tools. Write for a copy.

W. C. LIPE, INC. SYRACUSE, N. Y.





(CONTINUED FROM PAGE 88) operating expenses and the toll rate of 1 cent per mile appears to him as a 100 per cent increase in the cost of running his car. He would soon sour on the idea after a few junkets.

Charging admission to express highways has always been regarded as a prohibitive cost to operators of commercial vehicles. Whether this factor was taken into consideration in the report is not known but the Bureau expressed the view that "commercial vehicles, especially the heavier units, would be attracted to these roads in greater proportion than that in which they are found on the existing roads." This argument, the report noted, was based upon the theory that the value of time and distance saved by using super-roads will be the largest for commercial vehicles.

The estimate that the super-high-way system would yield only \$72,140,000 per year, as compared to its annual cost of \$184,050,000, was based upon assumed average toll

rates of 3.5 cents per vehicle-mile for motor trucks and buses and 1 cent per vehicle-mile for passenger cars. Since it was estimated that the ratio of motor trucks and buses to passenger cars would be approximately 1 to 4, the assumed toll rates for each type resulted in an average rate of 1.5 cents per vehicle-mile for all vehicles.

Indicative of the thoroughness with which the roads agency approached the job, Bureau engineers in laying out the toll-road network planned a right-of-way width of 300 feet in rural areas, 160 feet in suburban sections; all designed for normal maximum speeds of 70 miles per hour. Even the normal standards of curvature and gradient were set and provision was made in the design to allow ample provision to permit passing of trucks by passenger cars.

The report referred to Bureau tests which show that larger trucks, when loaded in accordance with the manufacturer's gross weight rating, cannol climb 4 per cent grades at a speed greater than 25 miles per hour; or on a 3 per cent grade, a speed of 30 miles. With vehicles loaded 50 per cent over the manufacturer's rating -a practice which the report said was not uncommon-the corresponding maximum speeds for 4 and 3 per cent grades are 16 and 22 miles per hour respectively. Under either condition of loading, it was noted, a 6 per cent grade slows the larger modern trucks to a crawling speed

OVER JACK BUYS!



● Look over these great features . . . "Ryth-Matic" Valve Action for smoother lifting. Pendulum Balance speeds positioning. High Carbon "Gun Barrel" Steel Cylinder for strength, power, and safety. "Micro-Accurate" Safety Release Control for positive lowering. "Snug-Fit" Power Pump for long life, trouble-free action. See them at Jack Headquarters—your Walker Jobber.

WALKER MANUFACTURING CO., RACINE, WIS., Also makers of Walker Electric Lifts and Exhaust Silencers

WALKER leads in JACKS

THUMBNAIL SKETCHES OF PENDING SUPER-HIGHWAY MEASURES

By Senator Frazier, Republican, of North Dakota, S. 2028

Would create a United States Motorways Commission of Congressional-departmental representatives based by the President and empowered to study and reporwith recommendations on a national system of highways.

By Representative Jeffries, Republican of New Jersey, H. R. 5749

Provides for a national super-highway system of safety automobile highways, consisting of 13 designated routes, and emergency airports. To be administered by a Director of Super-highways, subject to the approval of a seven-member commission, the plan call for prompt award of contracts for all needed maisrials to aid the unemployed and to stabilize was levels. Toll charges could not exceed I cent per mile for private passenger cars. Director could take been sary steps to control traffic "to prevent unfair competition among common carriers". Construction well be financed with a \$10,000,000,000 bond issued, with 3 per cent bonds guaranteed by the Government.

By Representative Lea, Democrat, of California, H. R. 3753

A designated private group, headed by T. A Tomasini, would be licensed as an agency of the Federal Government to construct, maintain and operate for a 50-year term parts of a transcontinental system of self-liquidating highways. Empowered to cellest tolls at a rate determined by the War Departuses, the agency would be vested with the right of emission domain. The highways would be privately financed is open to the use of the public and in the event of war would be under the central of the War Departuses.

By Senator McKellar, Democrat, of Tennessee, S. 679

Creates a Highway Planning Commission of an Presidential appointees to study all angles invalving (Turn to page 92, please)

> COMMERCIAL CAR JOURNAL JUNE, 1939



ile

18.

ch

n


n

u-

10

INCREASE
PAYLOAD PROFITS
BY REDUCING YOUR
BRAKING COSTS

WAGNER
Hir Brakes



FOOT VALVE

HAND
VALVE

You truck, trailer, tractor and bus operators are in business to make money. The profit you make is whatever portion of your payload dollar is left after all operating expenses are paid.

Labor, gasoline, oil and depreciation are set charges that cannot be reduced. But, there are operating costs that can be reduced, and outstanding among these is braking cost.

Thousands of dollars are spent needlessly each year for brake repairs and maintenance. A goodly portion of this waste can be eliminated by equipping your rolling stock with Wagner Air Brakes.

They are a product of Wagner's proven hydraulic brake engineering ability, and have been developed by engineers who have been in the industry since the inception of hydraulic brakes. This knowledge, plus unlimited manufacturing facilities, is your assurance that Wagner Air Brakes are the ideal brakes for all hydraulic brake equipped trucks, tractors, trailers and buses, as well as those equipped with mechanical brakes. The coupon below is for your convenience. It will bring you complete information.

Do you know

I have been a factor of the converse of the conve

POWER

AUTOMOTIVE PARTS DIVISION GGJ 1630-14
Wagner Electric Corporation 6400 Plymouth Avenue, Saint Louis, U.S.A.
I am interested in receiving full information or the Wagner safety equipment checked below
☐ Wagner Air Brakes
☐ Brake Testing Laboratory Book
☐ Brake lesting Laboratory Book
NAME
COMPANY
ADDRESS
CITYSTATE

(Continued from page 90)

the construction of a through highway from Washington to New York, including the desirability of charging tolls; and the construction of three transcontinental and three north-south highways. Calls for a Congressional apprepriation of \$200,000.

By Representative Randolph, Democrat, of West Virginia, H. R. 2767

Would create a Transcontinental Streamlined Super-Highway Corp., whose job would be to lay plans, supervise construction, maintain and operate two north-south and two east-west super-highways. Construction funds would be raised by a \$3,000,000,000 bond issue over a four-wear period with 3 per cent bends to mature in 30 years. Tolls fixed by the ICC would be collected by the Corporation which would be vested with the right of eminent domain. A five-man commission would administer the plan.

By Representative Snyder, Democrat, of Pennsylvania, H. R. 1939

The Department of Interior with the aid of Army Engineers and the Bureau of Public Roads would be authorized to locate and build three transcontinental and six north-south highways which would avoid large cities. An 38,000,000,000 Treasury appropriation would be expended over a 16-year period. A 10-man commission would purchase rights-of-way. Contractors building the roads would have to give prior consideration to the employment of workers between 50 and 65. The question of tolls is left open.

By Senator Lundeen, Farmer-Laborite, of Minnesota, S. 814

Almost identical to the Snyder bill except that it specifically routes one of the highways through the Senator's state.

Pooled Pick-Up for Los Angeles

Associated Carriers Agency of Los Angeles now handles a pooled pick up and delivery of seven truck lines serving 500 shippers out of Los Angeles. Combined bookkeeping as well as combined physical undertakings have brought about marked improvements from the standpoint of cost and convenience.

SERVICING
GM INJECTOR

(CONTINUED FROM PAGE 34)


air and wipe thoroughly with toilet tissue. (Do not use rag.) Bearing surface of bushing can be dried by wrapping toilet tissue around tool (GM No. 1021), a simple cylinder of the correct diameter with a longitudinal slit from which to start and hold the tissue. Work tool in and out and rotate. Insert plunger in bushing making sure that fingers do not touch bearing surface as moisture or dirt left by fingers may cause plunger to stick. With bushing on bearing surface of plunger, spin bushing with fingers. It should spin freely. At least as free as a small, clean, well-oiled ball bearing. If it does not, start in and clean and blow, clean and blow until it does.

7. After carbon and discoloration have been removed from spray tip by immersion in cleaning pan No. 1 and brushing with an extra fine wire brush, hold in under magnifying glass and punch out the six spray holes with tool (GM No. KMO-235). which is a handle for holding a length of .006 in. music wire. Rotate the wire in the orifice. When using a new length of wire it may be necessary to stone the end of it to remove burrs caused by cutting. After long service it might be well to test orifices with .007 in. wire. If wire enters holes the tip must be discarded but indications are that this will happen only after enormous mileages.

8. Using tool (GM No. J-1243) ream out inside of spray tip to remove accumulated foreign matter. Wash out in No. 1 cleaning pan and blow dry before rinsing in No. 2 cleaning pan.

9. After cleaning and blowing check valve-check seats for any discoloration. If discolored, polish on lapping block, using a figure eight motion. Lap only for discoloration and do as little of it as possible. If there is mechanical damage to these parts a matched set of spacer, flat valve, double-check valve seat and spherical valve must be used in replacement.

10. Before reassembly make sure (Turn to Page 94, Please)



The Truck Trend Proves It...

CHEVROLET'S the Chassis



American business and industry bought 115,426 trucks in the first quarter of 1939—a gain of 19,769 over the same period of last year. That is a nice increase for the truck industry—20.7 per cent.

American business and industry bought 41,555 Chevrolet trucks in the first quarter of 1939—a gain of 9,892 units over last year. And that is a nice increase for Chevrolet—31.2 per cent.

Chevrolet's gain over last year—exceeding the gain of all other makes combined—is due to two main factors: First, Chevrolet's proved records of efficient transportation at lowest cost; and, second, Chevrolet's enlarged line of models, making Chevrolet economy and excellence available in many more truck operations than ever before. Now there are 45 models to choose from—including one fitted to *your* needs.

CHEVROLET MOTOR DIVISION, General Motors Sales Corporation, DETROIT, MICHIGAN General Motors Instalment Plan—convenient, economical monthly payments. A General Motors Value.

DESIGNED FOR THE LOAD



POWERED FOR THE PULL

MASSIVE NEW SUPREMLINE TRUCK STYLING...COUPE-TYPE CABS...VASTLY IMPROVED VISIBILITY • FAMOUS VALVE-IN-HEAD TRUCK ENGINE • POWERFUL HYDRAULIC TRUCK BRAKES (Vacuum-Power Brake Equipment optional on Heavy Duty models at additional cost) • FULL-FLOATING REAR AXLE on Heavy Duty models only (2-Speed Axle optional on Heavy Duty models at additional cost)

GM INJECTOR

(CONTINUED FROM PAGE 92)

that all parts placed in No. 1 cleaning pan have been thoroughly cleaned and blown dry, then rinsed in No. 2 cleaning pan and blown dry and finally wiped with tissue. In cleaning filters be sure to blow the air from the inside out. Replace neoprene seat nut gaskets.

11. To reassemble place injector

body in holding vise in inverted position. Oil all parts as assembled with light oil.

12. Insert rack in injector body with yoke toward the side of the injector on which dowel pin is located. Note that teeth Nos. 5 and 6 on the rack are punch marked. Center these teeth in body of injector so that tooth No. 3 on the pinion, which is also marked, can be dropped into mating position with them. Install spacer.

13. Place bushing on body with bushing pin in slot of body. Place flat check-valve seat on bushing and then place flat check valve on seat, covering it with spherical check valve seat making sure that flat check-valve fits into recess. Insert spherical check-valve in check-valve spring and insert check-valve stop in other end of spring. Add assembly placing spherical valve on its seat and hold check-valve assembly in place by placing spray-valve tip over it and holding with finger.

14. Take tool (GM No. KMO-235) and place end on spray tip to hold it in position while spill deflector is dropped into position. Then place seat nut over tool and gently line up parts. When in proper position, oil threads. Seat nut should screw down by hand until the gasket seats. Tighten seat nut not to exceed 1/4 turn with wrench.

as

in

in

ec gi ec th

ca

15. Place injector in holding vise in right side up position. Install fuel filters in place with holes downward. Install springs and fuel line connectors making sure that threads are oiled and that new copper gaskets are in place on connectors. Unless injector is to be used immediately screw acorn nuts on connectors to prevent dirt from entering. Threads on nuts must be oiled. All threads on injector should be oiled before installation of mating part to prevent shearing off particles of metal which would get into the injector.

16. Assemble plunger through follower guide and install follower and lock pin. Slide follower spring in place and no matter how careful you have been again wipe bearing surface of plunger with clean tissue.

17. Note timing flat on pinion and insert plunger so that flat on plunger will mate and a gentle downward pressure will place plunger in proper position. Make sure that slot in plunger follower guide is lined up with hole in injector body so that stop pin can be installed. Install stop

18. Check the injector on the testing equipment as previously outlined.

General Motors' recommendation at this writing is not to dis-assemble injectors unless there is some indication that something is wrong with them. They do not advise dis-assembly for inspection. Test injectors at inspection periods but do not disassemble unless test shows some

Next month-The GM Blower.



FUEL CONSUMPTION METER

. The meter that tells you ALL about fuel consumption! Like many fleet operators you have long searched for a way to check drivers and motors, fuels, payloads and other factors . . . and from experience have learned that the only accurate way to check fuel is AT THE MOTOR. That's just what AKRAFLO does . . . for it's a star performer in cutting fleet fuel costs. At its moderate price, Akraflo will pay for itself quickly. Get full details - NOW!

S. F. BOWSER & CO., Inc.

1358 Creighton Avenue FORT WAYNE, INDIANA

makers of the worlds most widely used meter

COSTS

(CONTINUED FROM PAGE 23)

al.

k

lat

ri

er

5

ce

ts.

iel

rd.

re

ets

ly

to

mi

ch

rd

er

in

al

op

trucks have been purchased to replace one of the older larger ones.

In both of these fleets which provide a good cross section of fleet operation it is to be noted that the depression was instrumental in producing the lowest operating costs. Increased labor rates and material costs as well as increases in the prices of the vehicles have contributed to the increases since 1933. The increases in costs have, however, been kept to a minimum by good fleet management in both cases.

Experience in heavy duty truck equipment has shown that if the engine is overloaded its efficiency and economy is reduced. Why doesn't the same principle apply to the small car and one-half ton truck? As a matter of fact I think it does. The 60 hp. Ford has proved quite unsatisfactory in many localities, yet the 85 hp. is too large, providing too much power. As an example, I wish to cite the operation of fifteen 60 hp. Fords and fifteen 85 hp. models in the same service, in a city which is quite hilly, in which case the cost of the 60 hp. units is 5 mills per mile higher than the 85 hp. cars. Poor accelerating ability and the high motor speed necessary for maximum torque are the prime contributing factors to this result. In my opinion the economy desired could have been obtained with a motor of approximately 20 cu. in. more displacement than the 60 hp. Ford, yet the performance would not have been curtailed to the extent that it is dangerous in heavy traffic. The motor would not be overloaded to the extent that its efficiency is reduced to a point lower than the 85 hp. motor.

I thoroughly disagree with the attempts of Chevrolet and Plymouth to reach an ultimate in economy. Experience in bus operation indicates that the economy is proportional to the weight regardless of the design. I use this comparison because of the controlled operating conditions which provide a good comparison. It seems logical to assume therefore that the economy which has been realized is due to forcing the driver to operate the car at reasonable speed and acceleration. Tests conducted by one of our operating companies indicate just what can be done in regulating speed and particuarly acceleration. The results are so outstanding that I have included them in this paper. Figs. 4 and 5 indicate the results of fast driving and acceleration on gasoline mileage and a brief description of the tests follows:

Fig. 4 shows the effect of high speed operation on gasoline mileage. The data was obtained on a 1935 V-8 85 hp. coach. The tests were made with a standard mileage tester and all tests were made at constant speed. Note the drop in mileage at speeds

above 55 m.p.h. resulting from the opening of the power jet in the carburetor.

Study of Driving Habits

Fig. 5 shows the results obtained and the savings possible by developing economical driving habits. The tests were conducted as follows:

A. Low gear accelerate gradually to 7 m.p.h.

Second gear accelerate gradually to 14 m.ph.

(TURN TO NEXT PAGE, PLEASE)



ADDRESS

CITY..... STATE....





MCCULLOCH ENGINEERING COMPANY 32231/2 NORTH 31ST STREET MILWAUKEE, WISCONSIN

(CONTINUED FROM PAGE 97)
High gear accelerate gradually to 25 m.p.h.

Brake used as little as possible. Let engine act as brake making a gradual smooth stop.

B. Low gear as in Test A.

Second gear as in Test A.

High gear accelerate fast to 25

m.p.h.

Brake as in Test A.

C. Low gear as in Test A.

Second gear as in Test A.

High gear accelerate fast to 25

m.p.h.
Brake used *hard*. Speed kept at 25 m.p.h. until brakes had to be

applied to make stop.

D. Low gear accelerate fast to 14 m.ph.

Second gear accelerate fast to 25 m.ph.

High gear speed held to 25 m.p.h. Brake *hard* to stop.

These tests were made on a straight course with a stake each 1/10 mile. A complete stop was made at each stake. Maximum speed was held to 25 m.p.h.

The difference in time required to

drive a mile in Test A and Test D was only 5 sec.

From the tests will be seen the advisability, both for the company and for the personal car, of improving driving habits. Note particularly the small amount of the time saved by hurrying.

What then should be the operators' demand for future economy? Here are a few suggestions:

1. Reduced vehicle weight.

2. Reduced engine size keeping the hp. vs. weight ratio high enough for good engine efficiency.

3. Improved carburetion.

4. Improved ignition.

Reduced weight should be simple with high tensile steel and aluminum alloys. Reducing the vehicle weight will permit reduced engine size but it should not be obtained by using the same block with smaller bore and shorter stroke. A reduction in the weight of the engine is also advisable and necessary. As regards carburetion and ignition, it is my opinion that vast improvements will be made in the next few years. It is sincerely hoped that this improvement will re-

duce the need of some of the specialized maintenance equipment and highly trained maintenance personnel.

horsepower, increase gas mileage from 7.3 to 19.7%

-all without materially in-

creasing weight. Give your Ford V-8 truck the benefits of this modern engineering development for faster schedules, greater loads, easier operation at lower cost.

One of the independent manufacturers announced a car which is supposed to provide the economy, performance, durability, etc., which will answer the operators' problem. It has not been on the market long enough for the operators to determine the results, but regardless of the future of this car, it seems to me that the theory is correct. Furthermore, it was my pleasure to hear the president of this company talk about economy of operation. Perhaps this is the start of a new trend of thought in the minds of the executives of the automobile manufacturers. Let us hope so.

Condensed Comments

Personnel: "One of our operations consisting of 150 cars traveling 2: 000,000 miles annually has the following maintenance force: 1 foreman, 2 washers, 4 service men and 4 mechanics."

Economical Life: "Depreciation on (Turn to Page 100, Please)

COMMERCIAL CAR JOURNAL JUNE, 1939




CITIZENS OF CINCINNATI are saving money on gasoline, oil, tires and paint.

They are saving because six street-flushers, owned by the city, are equipped with all-Aluminum tanks and fittings. Weight savings ranging from 1044 lbs. (on an 800-gal. tank) to 3667 lbs. (on 3000-gal. tanks) bring operating savings. And the resistance to corrosion of Alcoa Aluminum Alloys not only saves on repair and maintenance costs, but also gives the tanks an outer surface so bright and attractive that they

are not painted! Painting cost is therefore nothing.

This continued satisfaction over a long period is typical of operators who have tried equipment built of Alcoa Aluminum. Aluminum tanks, truck bodies, and trailers ordinarily increase payload (by reducing dead weight) so they pay for themselves in less than a year. Ask any up-to-date builder to explain how equipment constructed of Alcoa Aluminum Alloys can serve your trucking needs. Aluminum Company of America. 2139 Gulf Building, Pittsburgh, Pennsylvania.



11

the on rea ors hift In-

up 24

gas

in

sof deedier ost.

IN

ialand nel. iacupperwill

It

er

the

hat

, it

ent

my

he

to

re-

(CONTINUED FROM PAGE 98) most of our cars is established by using 65,000 miles or 60 months for 85 per cent of the cost, leaving 15 per cent as estimated salvage. Experience indicates that over 20 per cent of the original cost is being realized on vehicles which have been fully depreciated and the difference is credited to the costs of the old vehicle when it is traded in. After considerable discussion, the management agreed to waive the 65,000 miles life expectancy and allow trades when they

were more economical. The result in one location has been most outstanding. During 1938, 32 per cent salvage was realized on passenger cars and pick-ups, making the depreciation costs less than 7 mills per mile. The service in this area is rather severe and we have adopted a plan of making replacements before the first major overhaul is necessary, which will vary from 35,000 to 80,000 miles depending upon operating conditions."

Gadgets: "An accessory out of the

gadget class is the condenser which can be connected to the radiator for condensing volatile anti-freeze. We have used a number of these units with very satisfactory results and in many areas consider them to be essential.

"Top cylinder lubricants are placed in the gadget class. That is, they do no particular harm as most of them are ordinary perfumed lubricating oil but they do no particular good and therefore are a waste of money. If carbon needs removing, top cylinder lubrication won't remove it.

"Another group of gadgets are the sludge removers. There may be a few of these on the market which are satisfactory but there are so many others that the safest recommendation is not to use them. We have found that the best method of remov. ing sludge is to reverse flush the crankcase using kerosene under 20 to 30 lb. pressure."

Repair Practices: "During the last two years we have had some very sad experiences where dealers in small towns either do not know or do not care to maintain the vehicles in serviceable condition. In addition to being paid for the repairs they were paid for the inspection and to our surprise, many items were overlooked and we were forced to discontinue the practice due to the fact that we got nothing for the money we spent for the inspection."

Tires: "When cars using 5.50/16 tires are purchased we specify a change to 6.00/16. We feel that the greater mileage will more than pay the difference and an additional size in stock is eliminated.


"Probably the best recommendation is that if you now have a tire record. keep it. If you don't-make a careful study of the costs before starting it."

Use of Vehicles: "Mr. Fred Heinlein of the Cincinnati Gas and Electric Co. has prepared a comparison of the costs of coupes and the 1/2-ton truck.

Annual Miles Cost License per gal. per mile Fee

½ ton truck 12.0 \$0.57 \$23.99 Coupe 18.3 0.43

"Total savings per year by using coupe instead of 1/2 ton truck is \$240.90. Mileage reduction due to fact that coupe can be used on the boulevards is 1800 miles annually per car."



This is the **Brake for you!**

COMPLETE KITS ENGINEERED FOR POPULAR TRUCKS

• Midland Power Brake Kits include every nut, bolt and screw needed for simple installation on Ford, Chevrolet, Dodge, G. M. C. and International trucks and tractors.

Made by one of the world's largest manufacturers of automotive accessories, Midland power brakes never cost more and generally less than other power brake equipment.

PRICED WITHIN EVERY FLEET OPERATOR'S BUDGET

GUARANTEED SERVICE IN EVERY IMPORTANT CENTER

A nation-wide distributor organization plus Midland's "Factory Rebuilt Exchange Plan" assures prompt and economical service. See your nearest Midland distributor today for prices and complete information.

THE MIDLAND STEEL PRODUCTS CO. 10605 MADISON AVENUE CLEVELAND, OHIO

Export Dept., 38 Pearl Street, New York City



COMMERCIAL CAR JOURNAL JUNE, 1939






BLOOD BROTHERS MACHINE COMPANY ALLEGAN . . MICHIGAN

30 years is at your command. Our Engineering Department will gladly submit quotations covering your requirements.


This Burch Achievement Leaves NO COMPARISON

The Burch Hydromotor Hoist is miles ahead of competition. It gives equal power up or down—locks automatically, any position—has one moving part—no exposed working parts—no oil lines.



THE BURCH CORPORATION
330 THOMAN ST., CRESTLINE, OHIO

TAKE THE GRIEF OUT OF TUBING CONNECTION WORK



It is surprising how much trouble tubing connection work can cause in the operation of commercial vehicles. One failure of a tube coupling or a fuel or oil line can cause a loss of time that will far outweigh the slightly greater first cost of better couplings and flexible lines.

Fleet operators have found that these four steps will take the grief out of tubing connection work:

- 1 Periodically check the condition of the tubing connections and flexible tubing.
- 2 Equip the shop with all the various sizes and types of fittings for brass tubing that may be needed for any emergency job. Imperial has developed a number of kits that make it possible to maintain such a stock on a very economical basis.
- 3 Maintain a small stock of ready-made flexible fuel and oil lines for your cars. Or you can get

a coil of tubing and an assortment of couplings and make up your own lines as you need them.

4 Be sure you have the latest Imperial tools for handling tubing connection work.

By following these four simple suggestions, fleet owners are improving their tubing connection practice and reducing loss of time due to tubing failures.

THE IMPERIAL BRASS MFG. CO. 1209 W. Harrison Street, Chicago, Ill.



Tubing connection work is covered very completely in the new catalog No. 121. It gives you complete information on the latest Imperial kits of fittings and flexible tubing, and covers the various tube working tools and other Imperial service aids.

Write for your copy.

IMPERIAL Automotive Products

TUBE FITTINGS . FLEXIBLE TUBING . TUBING SERVICE TOOLS . FREEZETESTERS . WELDING OUTFITS AND SUPPLIES



REFRIGERATION FOR TRUCKS AND TRAILERS

Write for Facts!

DROMGOLD and GLENN

1419 McCormick Bldg

Chicago, III

Cleanliness for 12 of Your Trucks

THERE'S no better advertisement of your efficiency and your firm's qualities than a clean truck. And there's no better dirt-chaser than No-Film!
This concentrated liquid is designed for truck use. It cleans thoroughly because of its energetic chemical action. It never leaves paint-killing film!

Prove it and profit . . . try No-Film FREE! Send your name and address, the number of your trucks, and your jobber's name. We'll send you enough No-Film to clean a dozen trucks . . . plus the well-known Technical Bulletins on Truck Finish Maintenance! The Mapor Corp., engineers-chemists, 151 W. 46th Street, New York.

NO-FILM

OSHKOSH

4 Wheel Drive Trucks

A proven product. 1½ to 10 ton capacity. Write for complete information.

OSHKOSH

Motor Trucks, Inc. Oshkosh, Wis.

VARNISH

(CONTINUED FROM PAGE 21)


a varnish condition. This sounds logical but so far it appears that investigators have been unable to trace any preponderance of varnish troubles to the engines which have the closest clearances.

This line of thought does provide a possible solution to a puzzle that confuses the efforts of investigators. Frequently a number of identical vehicles operating in identical service under identical conditions produce anything but identical results so far as varnish is concerned. Some of them will have none while in others it will be a serious problem. The suggested solution is that when the piston size high limit and the cylinder size low limit get assembled together the decreased clearance is the one difference that causes the trouble.

Varnish is more frequently found in new engines than in old ones. This is understandable to oil men who explain that the new metal in a new engine acts as a catalyst for whatever chemical action is involved, and that after a period of exposure the surface of the metal becomes chemically inactive.

A number of refinery technicians doubted that a rebuilt engine would be assembled tight enough to run into a varnish condition. Inquiry, however, revealed that engines with reconditioned cylinders and new pistons were encountering varnish, usually on the cylinders with the least clearance.

One well-informed investigator is beginning to think that perhaps fuel has something to do with the varnish. In this he gives tetraethyl lead a clean bill of health. His theory is that fuel gets down between the piston and cylinder and between these two cool-





They WON'T BURN OUT




Ruggedly built. Ballbearing Capacitor type motor protects against burn-out. Weight, 39% lbs. Guar anteed 1 \$2050 year

BALDOR ELECTRIC CO. 4340 Duncan Avenue ST. LOUIS. MO.

OUTSTANDING

performance in the Automotive Industry







HOISTS and DUMP BODIES
EVERY SIZE and TYPE


for every hauling job

GAR WOOD INDUSTRIES, INC.

Branches and Distributors Bueryschore



COMMERCIAL CAR JOURNAL June, 1939



I-R Type 30 compressors will give many years of service. This is assured by such features as: a dust-tight crankcase, sturdy construction, stainless steel valves and precision construction.

These features mean more years of life and less maintenance expense.

There is a complete range of sizes from $\frac{1}{4}$ to 10 hp.

Ask the I-R jobber about them and about the I-R Fender and Body straightening tool.



Ingersoll-Rand
II BROADWAY, NEW YORK, N.Y.
I-R JOBBERS EVERYWHERE

ing surfaces it is impossible to propagate a flame and that in an ensuing reaction there is formed one of the aldehydes which is one of the bases of bakelite. His reason for leaving tetraethyl lead out of his consideration is that varnish has appeared in Diesels where the fuel is innocent of this substance.

Varnish in a chemical definition is about 25 per cent iron naphthenate and the balance polymerized oil. Now if we take this definition away from the refinery technicians and turn it into layman's language it means that a naphthenic acid is formed in the oil which attacks the iron surface of the engine and forms the naphthenate. Polymerized oil means that the molecular structure of the oil has changed, resulting in larger molecules, which means that a different substance has been created.

No dog cares much what the veterinarian calls a flea. The dog is interested in how to get rid of the fleas and how to keep from getting them again. Fleet operators will stake the oil refiners to any kind of a fancy name they care to give varnish if they will tell them how to get rid of it and how to prevent future appearances.


Acetone seems to be the best known solvent. Strangely enough, however, a strong solution of castile soap will remove varnish. Both are applied to the affected part when the engine is disassembled.

At least one fleet operator seems to be getting satisfactory results without disassembly by purging engines with ½ pt. of a mixture containing the following: 16 qt. methyl acetone, 3 qts. nitro-benzine, 6 qt. xylene and 1½ lb. naphthalene flakes all added to a light oil in a 1 to 3 ratio. This is fed into a hot engine through a downdraft carburetor or through spark plug ports when the engine is turned over with the starter. He suggests an overnight soaking as best but says 30 min. idling will suffice. Then the crankcase is drained and flushed with flushing oil.

To prevent the formation of varnish all of the following ideas have been suggested at one time or another and probably all of them have merit.

- Experiment with the selection of oil.
- 2. Drain crank case more frequently.
 - 3. Use oil filters.

(TURN TO NEXT PAGE, PLEASE)



Don't Tear Down That Engine . . .

Keep Payloads
Rolling with the New

LEMPCO PORTABLE CRANKPIN GRINDER

With a Lempco Portable Crankpin Grinder in your garage you can grind the toughest and hardest of crankpins right in the block in only a fraction of the time ordinarily required to do the job. Once and for all you put an end to costly delays and profiteating, idle equipment. In emergencies the job can be done right at the breakdown—eliminating relief tractors, towing and load transfers—saving you immeasurable time and money.

Take the first step toward stretching your truck mile dollar by mailing in the coupon below.

I'm interested in keeping my trucks rolling. Send me your catalog giving all the details on the new Lempco Portable Crankpin Grinder.

Firm Name	
Address	_State
Requested by	

LEMPCO PRODUCTS, INC. BEDFORD, OHIO

A ST. PAUL HYDRAULIC HOIST AND BODY FOR EVERY MODEL OF TRUCK



25 Years of Successful Manufacture of Hydraulic Hoists for Motor Trucks.

ST. PAUL HYDRAULIC HOIST COMPANY 2207 University Ave. S.E. Minneapolis, Minn.

For running-in new and rebuilt engines use auxiliary lubricants containing "dag"* Brand colloidal graphite.

Acheson Colloids Corporation Port Buron - dag - Michigan

JONES PORTABLE TACHOMETER



The world's largest operators of commercial vehicles use Jones Portable Tach ometers to check engine speeds, for tune-ups, and setting governors, etc. Here are a few: Standard Oil Co., of La., N. J., N. Y.; Shell Petroleum Co., Atlantic Refining Company, Keeshin Motor Express. Ck Trucks, Brockway, U. S. Navy. Direct, instantaneous reading DNES-MOTROLA-STAMFORD. CONN.

JONES-MOTROLA-STAMFORD, CONN. 432 FAIRFIELD AVENUE

FEDERAL

THE HANDSOMEST TRUCK ON THE ROAD 37 models . . 3/4 to 8 ton

4 and 6 wheelers

conventional and cab-overengine types

FEDERAL MOTOR TRUCK CO. Detroit, Michigan

(CONTINUED FROM PAGE 121)

- 4. Use inhibitors.
- 5. Check water thermostats and make sure that engine is not operating too hot.
- 6. Do not be too aggressive in reducing oil consumption by mechanical means.
 - 7. Equip engines with oil coolers.
 - 8. Flush out engines periodically.

Fleet operators will have to experiment with these ideas until such a time as the technicians solve the problem of varnishing at its source. When they will solve it no one can tell, but fleet operators may rest assured that the best minds in the industry are now hard at work on the problem.

Safe-T-Eye

A device said to instantly detect low oil level as well as other symptoms of oil



failure has been introduced by Pressure Signals, Ltd., Elm-hurst, Ill. A compact control unit is installed on the oil pump or oil line and is electrically connected to an indicator light on the dash. A companion device warns of low pressure in the air

brake system. For full details, write the exclusive sales agents, J. E. Menaugh Co., 549 West Washington Blvd., Chicago.

MANY VALUABLE TESTING INSTRU-MENTS AND SHOP



for

PISTON

Ask for your copy Free Premium Book

REPAIR

FOR RECONDITIONING

Vacuum Power Brake Cylinders and Valves TRUCKS **TRACTORS TRAILERS** BUSES

Write for Catalog 16-A covering our complete line. Give jobber's name.

POWER BRAKE PARTS MFG. & SALES CO. 4418 Woodward Ave., Detroit, Mich.

WAUKESHA

- · Comet Diesel
- Hesselman
- · Gasoline
- Hy-Powr
- · Ricardo Head



the HILLMASTER. . is the only Governor made that releases full engine power on hills regardless of the governed

WRITE FOR FACTS -- KLEMM AUTOMOTIVE PRODUCTS CO. Chicago, III.

TRUCKS

DIESEL AND GASOLINE

GREATER PROFITS

Cost sheets tell the story! Net savings of over \$15,-000.00 per truck. An achievement of Sterling Diesel powered motor trucks -trucks which have traveled in excess of one-half million miles and are still in operation.

Be sure of maximum returns on investment. Select Sterling motor trucks for superior performance and lower operating costs. Write for full information.

SIZIENG MOTORS CORPORATION MILWAUKEE WISCONSIN

USE THE DAYTON FUELOMETER

Positive Gas Protection

Accurately records all gasoline consumed by any truck or passenger car. Write today for the complete story.

DAYTON FUELOMETER CORP. DAYTON, OHIO

Fifth Wheels Landing Gears Pintle Hooks

Austin Trailer Equipment Company Muskegon, Michigan

Manufacturers of Engineered Trailer Products

KINNEAR TRUCK DOORS Also Doors for Buildings



ALL METAL . . . Coils like a window shade, out of the way . . . CONVENIENT BURGLAR PROOF FIRE PROOF MORE DURABLE Write for Details KINNEAR

NEWSCAST

(CONTINUED FROM PAGE 58)

who last fall joined the Monarch Governor Co., as sales manager after 18 years with Ford, has been elevated to the vice-presidency in charge of sales. . . . S. J. Greeb, for 15 years district sales manager of the Boyce Motor Meter Co., has joined the Upper Lubrication Oil Co., Inc., of Brooklyn, N. Y., as a special sales representative.



W. D. Wise, who joined the Fruehauf sales department in 1931, has been named advertising manager of the Fruehauf Trailer Co. He will also supervise sales promotion activities.

Promotion of four General Tire sales representatives have been made as follows: H. T. Rattigan, in charge of accessory and



H. T. Rattigan (left), and J. J. Muckenhoupt

special product sales, eastern division; J. J. Muckenhoupt, truck tire manager for the eastern division; L. E. Marlowe and J. E. Powers, assistant district managers, New York sales district.


Chester C. Codding, recently named as assistant to the general manager, Willys-Overland Motors, Inc. For the past 15 years he has been onnected with various divisions of Chrysler Corp.



Tragedy struck twice recently within the industry. Once to Lawrence M. Viles, chairman of the board of the Buda Co., who died on April 27, and once to A. F. Davis, vice-president of Lincoln Electric Co., so seriously injured in an automobile accident that he was not expected to live. Latest word, however, is good and he is on the way to complete recovery.



THIS CAN'T HA WHEN YOU USE AN



Exclusive Patented Feature **Eliminates Air Pockets!**

FLEET owners swear by the Alemite "Rock Crusher"! This amazing grease gun has no equal for fast, dependable,

gun has no equal for fast, dependable, accurate performance—and its exclusive, patented helix arm and worm design positively prevents air pocket trouble!

Holds 40 pounds of lubricant. Delivers heavy fibrous grease at the rate of 14 ounces per minute on 150 pounds of air—at a pressure 33 times the air pressure used. Ruggedly constructed to stand heavy service. Handle serves as hose rack. Three large wheels make it easily portable. Comes complete with 10-foot hose assembly and quick detachable air coupling.

Also Available for Electric Power

Model 6524 "Rock Crusher" has the same Crusher" has the same exclusive, patented helix arm and worm, and is equipped with heavy duty universal electric motor for use with either AC or DC. Delivers 9½ ounces of grease per minute un-der 5000 pounds pres-sure per square inch.

Dependable lubrica-Dependable lubrica-tion is cheaper than repairs and layoffs. Investigate the complete line of Alemite Equipment, and learn how much the right Alemite Gun can save you over a year's time—not only in lubrication and maintenance costs, but in longer life and trouble-free service from your equipment. Write for information!


A Division of Stewart - Warner Corporation 1876 Diversey Parkway, Chicago, Ill.

Stewart-Warner-Alemite Corporation of Canada, Ltd., Belleville, Ontario

WORLD'S LARGEST MANUFACTURER OF LUBRICATION PRODUCTS

Black Diamond All-Rubber

SEAT CUSHIONSBuilt for ALL Conditions



Hard-boiled tests by fleet cwners everywhere have definitely established proof that Black Diamond all-rubber semi-sponge seat cushions and back rests don't give out under the toughest kind of gruelling service. It's the scientifically designed exclusive diamond grid construction that makes these cushions outwear, out-last and give greater riding comfort than other types. They're modest in cost and are designed to fit ANY type of truck. Let us give you more information!

KARPEX MANUFACTURING CO.

1426 E. 19th St., Indianapolis, Ind.


Available Trucks

Builders of fine Motor Trucks. Tractors, Trailers and Buses since 1910.

Capacities from 1% to 10 tens.

Write for bulletin

AVAILABLE TRUCK COMPANY 2501 Eiston Ave. Chicago, Illinois



Georgia Diesel Tax

To date relatively few diesel-powered trucks have found a permanent home in Georgia. Hence the subject of diesel fuel taxes had not yet been settled when our Fleet Operator's Reference Annual summed up the diesel tax situation in April. But last month came an appendage from Georgia's Department of Revenue—"Diesel fuel when used upon the highways for the propulsion of internal combustion motors—6 cents." This is the same as the state's gasoline tax.



S. B. Cochrane and C. H. Monahan, Studebaker regional managers in South Bend and Omaha received bronze plaques recently commemorating 15 years with the company

du Pont to Market Ethylene Glycol

And speaking of anti-freeze, a flash just over the wire has it that du Pont is building an ethylene glycol plant at Belle, W. Va. According to the report the plant will not only supply the company's present needs, but will furnish the product to the Zerone Division for sale as an anti-freeze.



Peter Zientek, Eloyd Jacobson and Howard Hagerty won safety awards recently for a combined total of 1,500,000 accident-free miles. They're ace drivers for Fruehaufequipped Barry Transfer of Milwaukee

KEEP YOUR VEHICLES MOVING ECONOMICALLY

with

HALL VALVE SERVICING EQUIPMENT

Ask Your Jobber or write

THE HALL MFG. CO.

-More Profits per Job with HEIL



Bodies and Hoists
Safe — dependable — complete line for

all types of service. Ask for free catalog.

Milwaukee, Wisconsin Hillside,

Hoists — Bodies — Tanks — Road Scrapers — Saon Pleas Bottle Washers — Dehydraters — Oil Burners — Waler System

IT PAYS TO BUY

QUALITY SEMI-TRAILERS

EDWARDS IRON WORKS, INC. SOUTH BEND, INDIANA

WALKER



- · No Gear Shifting
- · Lower Operating Costs
- · Greater Fuel Economy
- · Reduced Maintenance Costs
- · More Efficient Power Transmission
- · Start-stop Time Reduced

WALKER VEHICLE COMPANY

Manufacturers of Electric and Gas-Electric Trucks

All WEST 8746 STREET CHICAGO ILLINOIS

BIG ENOUGH

 This is space enough to tell you that Fitzgerald Bulldog Gaskets are best for modern heavy duty service.

THE FITZGERALD MFG. CO., TORRINGTON, CONN.

FITZGERALD GASKETS

COMMERCIAL CAR JOURNAL June, 1939

Self-drying Truck Wash NO Chamoising!




Cut truck washing time in half. Use self-drying Wonder Weld Magic Car Wash. No chamoising. Harmless to finish. Pint, and gallon, cans. Pint can gives 16 washes. See jobber. Sample, and folder, FREE. Write Miller Mfg. Co., 1220 Kaighn Ave., Camden, N. J.

WONDER-WELD

THE KNITY HE WILL PHISHIN LINGHIII

A Safer Turn Signal For Package Trucks



TELEOPTIC DELUXE

EASILY OPERATED — GUARANTEED
WRITE FOR DETAILS

THE TELEOPTIC CO.



hand or power hydraulic control FOR ALL MOTOR TRUCKS FROM 1% to 10 TONS

for

Wite for catalog 38AC and 38BC with discount to truck dealers.

CABL H. FRINK, Mfr., CLAYTON, 1000 Isl., N. Y.

DAYENPORT.BESLER CORP., DAVENPORT, IOWA
FRINK SNO-PLOWS OF CAN. Ltd., TORONTO, ONT

Be Sure to Specify



AMERICAN BOSCH Ruel Injection Equipment

For Diesel Engines

AMERICAN BOSCH CORPORATION

Springfield, Mass. New York. Chicago. Detroit.



GRAMM TRAILERS

Ask the man who pulls one
GRAMM TRAILER DIVISION
Delphos, O.

COMMERCIAL CAR JOURNAL

Is the Leading Publication in the TRUCK FLEET Field

NEW PRODUCTS

(CONTINUED FROM PAGE 62)

Schofield Dieselizer

Dieselizer Corp. of America, Van Nuys, Cal., has announced the Schofield Dieselizer. This device is for application on gasoline engines to make it possible for them to operate on fuel oils or distillate.



The unit provides an auxiliary fuel system for the engine. There are two accelerator pedals and gasoline or the heavy fuel can be used at will by merely depressing the correct pedal. The regular gasoline fuel system is used for starting and warming up in normal service. Water is metered into the heavy fuel when it is used, as an anti-knock.

Wheel Bearing Lubricator

To insure maximum efficiency in the lubrication of automobile and truck wheel-bearings, a new-type wheel-bearing lubricator is now being manufactured by the Alemite Division of the Stewart-Warner Corp., Chicago. It is adaptable to both



ball and roller wheel-bearings on all modern makes of passenger cars and trucks and assures uniform distribution of the lubricant within the bearing. For full details, address Stewart-Warner Corp., 1826 Diversey Parkway, Chicago.

ARE YOU THROWING AWAY HUNDREDS OF DOLLARS

You are, every year, if you are discarding used crankcase drainage.

With a Milwaukee Refining Machine, drainage oil yields 85-90% of oil better than new at 5¢ to 8¢ per gallon.

85 outstanding concerns in Milwaukee testify to its superiority over any machine produced.

Boynton Cab Co., Milwaukee, says—
"It is a vast improvement over the several other reclaiming machines used before we took yours."

Octore we took yours."

City of Milwaukee says—

"... your representations as to quantity of oil, amount of recovery, cost of operation, etc., have been fully justified by the facts. In reality they have been exceeded."

Advance Transportation Co. says—
". . . to date the direct saving in oil expense has exceeded the cost of the machine, in fact this saving is at the rate of over 200% per annum on the price paid to you."

Wisconsin Ice & Coal Co. says— "With your machine, the cost of rerefining is approximately one-third the former cost of reclaiming."

WE CAN DO THE SAME FOR YOU. Full particulars upon request.

Do you know a good man looking for another line? Capable distributors desired for all parts of the country.

EDDY, BIGGERT & COMPANY
20 N. Wacker Drive, CHICAGO, ILL.



Money-Wise Fleet Operators
Use
BEAURLINE FOUNTAINBRUSHES

Beaurline, the original fountain type car washing brush, is designed to save time, effort and space in busy fleet shops. That's why money-wise fleet operators everywhere are turning to Beaurline for the solution to their washing problems.

Write for complete information on several new models, shapes and sizes, and for new low prices.

BEAURLINE FOUNTAIN BRUSH CO. 1243 S. Wabash Avenue, Chicago

COMMERCIAL CAR JOURNAL JUNE, 1939

Advertisers' Index

This Advertisers' Index is published as a convenience, and not as part of the advertising contract. Every care will be taken to index correctly. No allowance will be made for errors or failure to insert.

A C Spark Plug Div. General	_	McCullock Engineering Co 00
9.00		McCulloch Engineering Co 98
Motors Corp 65	W	McQuay-Norris Mfg. Co 14
Acheson Colloids Corp 122		Mack Trucks, Inc 48
Alan Wood Steel Corp 118		Mapor Corp 120
Albertson & Co., Inc 10		Marmon-Herrington Co., Inc. 87
Alemite, A Division of Stew-		Midland Steel Products Co 100
art-Warner Corp 123	Federal-Mogul Corp 104	Miller Mfg. Co 124
Aluminum Company of Amer-		Miller Mig. Co 124
	Federal Motor Truck Co 122	0 11 1 W 1 M T 1 C 100
ica 99, 3rd Cover	Fitzgerald Mfg. Co 124	Oshkosh Motor Trucks Co 120
American Bosch Corp 125	Ford Motor Co 109	
American Brakeblok Div. of	Four Wheel Drive Auto Co.,	Packard Electric Div. General
the American Brake Shoe &	Back Cover	Motors Corp 79
Foundry Co 13	Frink, Carl H., Inc 125	Parish Pressed Steel Co.
American Cable Div., American		(Subsidiary of Spicer Mfg.
	Fruehauf Trailer Co 45	
Chain & Cable Co., Inc 3	Fuller Mfg. Co 66	Corp.)
Anthony Co		Power Brake Parts Mfg. &
Austin Trailer Equipment Co 123	Gar Wood Industries, Inc 120	Sales Co 122
Autopulse Corp 70	Gatke Corp 84	
Available Truck Co 124	General Motors Corp 8	Reo Motor Car Co Front Cover
	General Tire & Rubber Co 113	Republic Steel Corp 76, 77
Baldor Electric Co 120		
Barrett Equipment Co 117	Gerstenslager Co., The 118	S K F Industries, Inc 120
	Globe-Union, Inc 101	St. Paul Hydraulic Hoist Co 122
Beaurline Fountain Brush Co 125	Goodrich Co., The B. F 128	
Bendix Products Division of	Gramm Trailer Div. Gramm	Salisbury Axle Co 127
Bendix Aviation Corp 37	Motor Truck Corp 125	Seiberling Rubber Co 110
Bendix Westinghouse Auto-	Guide Lamp Div. of General	Service Recorder Co 42
matic Air Brake Co 95		Sherwin-Williams Co 83
Bibb Mfg. Co 7	Motors Corp	Shuler Axle Co., Inc 102
Blood Brothers Machine Co 119	Gulf Oil Corp 41	Snap-On Tools Corp 118
	77 11 377 Cl	Socony-Vacuum Oil Co., Inc 1
Bowser & Co., Inc., S. F 94	Hall Mfg. Co 124	
Brown-Lipe Gear Co 127	Handy Governor Div. of King-	Spicer Mfg. Corp 127
Burch Corp	Seeley Corp 68	Standard Oil Co. (Indiana) 11
	Hansen Mfg. Co., A. L 44	Sterling Motors Corp 123
Champion Spark Plug Co 9	Haskelite Mfg. Corp116-117	Stewart-Warner Corp 78
Chevrolet Motor Div. General	Heil Co., The 124	Studebaker Corporation 59
Motors Sales Corp 93		
Cummins Engine Co 85	Hein-Werner Motor Parts	Teleoptic Co., The 125
Curran Corp., The 106	Corp	Texas Co., The 4-5
Cultum Corp., The 100	Hercules Steel Products Co 116	Thompson Products, Inc 67
Dayton Fuelometer Corp 123	Highway Trailer Co 2	Thornton Tandem Co 120
Denman Tire & Rubber Co 97	Homestead Valve Mfg. Co 88	
	Hoof Products Co 86	Timken-Detroit Axle Co 63
Delco-Remy 96	TOOL A TOURIS CON THIT THE CO	Timken Roller Bearing Co 81
De Vilbiss Co., The 47	Imperial Brass Mfg. Co 119	Toledo Steel Products Co 111
Diesel Engine Division General	Ingersoll-Rand 121	Trailer Company of America 75
Motors Sales Corp 12		Trucktor Corp., The 120
Dieselizer Corp. of America 118	International Harvester Co.,	
Ditzler Color Co 6	Inc 16	United States Asbestos Div.
Dodge Div. of Chrysler Corp.,		Raybestos-Manhattan, Inc., 72, 73
	Jones-Motrola 122	,
2nd Cover	Joyce-Cridland Co., The 82	Vapo Dome Corp 118
Do-Ray Lamp Co 117		Veedor-Root, Inc 116
Dromgold & Glenn Co 120	K-D Lamp Co 98	vector-zeoot, zne
Dry-Zero Corp	Karpex Mfg. Co 124	Wagner Electric Corp 91
Du Pont de Nemours & Co.,	Kinnear Mfg. Co 123	Walker Mfg. Co 90
E. I. (Du Pont Finishes Divi-	Klemm Automotive Products	Walker Vehicle Co. Div. of the
sion)	Co	
Sion)	00	Yale & Towne Mfg. Co 124
Eberhard Mfg. Co. (Div. of the	Lee Tire & Rubber Co 46	Watkins Babbitting Service 104
		Waukesha Motor Co 122
Eastern Malleable Iron Co.). 92	Leibing Automotive Devices,	White Motor Co., The 43
Eddy Biggert & Co 125	Inc 74	Wilkening Mfg. Co 122
Edison-Splitdorf Corp 60	Lempco Products, Inc 121	Willard Storage Battery Co 107
Edwards Iron Works, Inc 124	Lion Oil Refining Co 80	Williams & Co., J. H 62
Electric Auto-Lite Co 69	Lipe, Inc., W. C 89	Wittek Mfg. Co
Electric Storage Battery Co 39	Long Mfg. Div. Borg-Warner	WILLER MIE. CO 124
Exide Batteries	Corp	Zollner Machine Works 120